

(1) Number of pages _____
(2) Date of repair _____
(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

P. W.

DEPARTMENT.

G.O. No. 3269	Press
449-450	Mis.
Dated 22-10-1869.	

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
22nd October 1867.*

No. 449. Read the following letter from the Superintending Engineer, 3rd Division, to the Secretary to Government, Public Works Department, dated Camp at Wontimitta, Cuddapah, 11th October 1867, No. 1,904 :—

I have the honor to submit, for the sanction of Government, an estimate, specification, and memorandum, for repairing the tiled shed in the Hoozoor treasury compound of Cuddapah, amounting to Rupees 145. The work is stated by the Collector to be urgently required, and the amount may be met from the grant for Minor Repairs to " Civil Buildings."

No. 450. ORDER THEREON, 22nd October 1867, No. 3,269.

CIVIL WORKS, No. 45.

Sanctioned.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 3rd Division, with one Specification.
,, Accountant General.
,, Controller of Public Works Accounts.

Exd. S. T. Augustin.

Memorandum

The tiled shed in the Huger
Treasury Compound is urgently required
to be repaired. The remittances from the
Calcutta which reach the Treasury after
usual hours are deposited by the Police
escorting the same till the money is dropped.
Several Empty treasure Boxes and other
things connected with the Treasury are
secured in the shed.

Cuddapah }
Collectors Office }
28th August 1867 }

[Signature]
Collector

[Signature]

A betreat Estimate No. of 1867/68
 District Cuddapah Taluk Cuddapah
 Town Cuddapah.
 Work Repairing the old Building in the
 Bangalore Treasury Compound.

Quantity	Description of work	Rate	Amount	Total
12 ²² / ₂₅ Lys.	Repairing the roof with ² / ₃ of repairs ¹ / ₂ tiles ² / ₃ Common rafters and New brats &c.	8	103	7
	Putting down Tiles ¹ / ₂ of the present roof		20	
	Repairing the Sundry cracks ¹ / ₂ in the sand walls		10	
13 ³⁷ / ₁₀₀ Lys.	Coiming and whitewashing the walls for protection from the weather	6	5	3
	Sundries at 5 per Cent.		6	15 2

Total Estimate Rupees 115

Civil Engg. Office
 Cuddapah
 19 September 1867

Shunteswar B. E.
Da Ch. Cuddapah Range
A. V. S. M. S.
 Coltr. Sub. Engineer

1 M39/19/67

Estimated by 1867/68

Estimate for Repairing
the Old Building in the
Huzoor Treasury Compound

7/18/39/19/67

No. 1904

From

The Superintendent,

To

The Secretary to Government
P.W.D.

By

I have the honor to submit
for the sanction of Government an estimate,
Specification and Memorandum for repair
engravings in the Huzoor Treasury
Compound of Addalah amounting to Rs. 145.
The work is stated by the Collector who urgently
requires and the amount may be met from
the grant for minor repairs to Civil Buildings.

I have the

N.

W. W. W. W. W.
Superintendent
3/10

1867 62 Dep
Pro. of York for Clerk
3919

The Supg. Engineer
C.D.

The Secy. of Genl.
M.D.

Dated 11th October 1867

Recd. 14

Enc. 3 No. 1904

Finances for Ranchon
Return to Accounting
of 1865 for repairing the
sided shed in the Hanger
Treasury Compound of A.D.
Dapah.

no. 3269-22nd Oct 1867

With an order,

Accepted
no. 3269

Start at 11:00
22nd Oct 1867

Recd. 23/10/67

No. 449-450
e. 16th Oct 1867 P. 12th