

(1) Number of pages 8
(2) Date of repair 21-5-18
(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No.	3789	Press Mis.
102-03		
Dated	5-12-18	1867.

Not to be folded or roughly handled

Proceedings of the Madras Government, Public Works Department.
5th December 1867.

No. 102. Read the following letter from the President of the Madras Municipal Commission, to the Secretary to Government, Public Works Department, dated Madras, 29th November 1867, No. 64 :—

1. The Band Stand on the South Beach Promenade, which was built by this department at the expense of Government in 1861, is in a dilapidated state, and on my bringing the same to the notice of the Superintending Engineer, 4th Division, he replied that it has not hitherto been repaired by his department, and that he presumed the work should be carried out from the repair funds of the South Beach Road.

2. A reference to the Order of Government, No. 1,609, dated 12th June 1865, will, however, show that only the walks in connection with the Band Stand are to be maintained by this department, and I, therefore, have the honor to request that the Superintending Engineer may be directed to make the necessary repairs to the Band Stand itself.

No. 103. ORDER THEREON, 5th December 1867, No. 3,789.

CIVIL WORKS, No. 20.

Although the Band Stand was not mentioned in the Order of the 12th June 1865, No. 1,609, it was obviously

the intention of Government that the whole of the Band Stand enclosure, including the walks as well as the railings, should be maintained in repair at the expense of the Municipality.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the President of the Municipal Commission:
,, Superintending Engineer, 4th Division:

Exd. S. T. Augustin.

Stated

MADRAS, 29th November 1867.

No. 14

To Colonel C. A. O. R. E.
Secretary to Government. P. M. D.

1. Sir, The Band Stand on the South Beach Promenade which was built by this Department at the expense of Government in 1861 is in a dilapidated state, and on my bringing the same to the notice of the Superintending Engineer, S. Division he replied that it has not hitherto been repaired by his Department and that he presumed the work should be carried out from the repair funds of the South Beach Road.

2. A reference to the order of Government & Co. 1869 dated 12th June 1865 will, however, show that only was the work in connection with the Band Stand

Band Stand are to be maintained
by the Department, and it therefore,
have the honor to request that the
Superintending Engineer may be directed
to make the necessary repairs to the
Band Stand itself.

I have the honor to be

Yours most Obedt. Servant
Chas. Derrison

President of the
Gravel Municipal Commission

W.M.

Dec 1902

Dec 3789-5 Dec 1902

Requiring that the
Jury Box at the 1st St.
may be repaired & be
sent to the repairer required
to the Court House
the Court House.

Dec 3789-5 Dec 1902

From
The President of the
Municipal Council

Dec 3789-5 Dec 1902

Chairman

No 3789 Public Works Department.
3789

PROCEEDINGS of the MADRAS GOVERNMENT.

Under date the 5th Dec 1902

Read the following

From the President of the
Madrass Municipal Council

(Here enter No. 64 dated 29th Nov 1902)

Although the band
stand was not mention-
ed in the order of the
12th June 1865, No. 1609,
it was obviously the in-
tention of Government
that the whole of the band
stand enclosure, including
the walks as well as
the railings, should be main-
tained in repair at the
expense of the Municipi-
pality.

W. H. C.
W. H. C.
W. H. C.

The Municipal Council
1. Eng 4 1902

Dec 1902

W. H. C.

P. W. 1867. Department.

Bo. of Govt. for December
No. 3789

PROCEEDINGS OF GOVERNMENT

of Madras

Dated 5th

December 1867

Informing the Madras
Municipal Commission that
the whole of the Band stand
enclosure &c on the South
Beach should be maintained
in repair at the expense
of the Municipality