

(1) Number of pages

6

(2) Date of repair

12-3-63

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Public works DEPARTMENT.

G.O. No. <u>63.</u>	Press
<u>133-134.</u>	~~Mis.~~
Dated <u>9-1</u>	<u>1867.</u>

Not to be folded or roughly handled

Proceedings of the Madras Government, Public Works Department
9th January 1867.

No. 133. Read the following Endorsement of the Superintending Engineer, 4th Division, dated Madras, 20th December 1866, No. 3,791 :—

Read the following letter from the the Acting Executive Engineer, 4th Range, Madras District, to the Superintending Engineer, 4th Division, dated Chingleput, 17th December 1866, No. 210.

I have the honor to inform you that the undermentioned tanks have been breached during the late heavy rains. Orders will be sent for their repair :—

Mambakam tank.
Vadapathy do.
Nelvay large do.
Ootramallore channel and cross
bund between large tank and
Chittary.
Vyaloore tank.
Cadiamungalum large do.
Marootham calingulah and chan-
nel washed away.
Maroothoovambady tank.
Thetalum do.
Camarazapooram channel.
Seeromallore tank.
Malayoncolum channel and cross
bund between Chittary and large
tank.

Caliampoondy tank.
Thinayampoondy do.
Agaram do.
Oolocaray do.
Parmatore river channel.
Tholarampoondy tank.
Chetput do.
Salavaukam do.
Pennagur channel.
Coonnumgolathur tank.
Allapaukam do.
Poothoochary do.
Kaleapettah channel.
Vyavoor Hissa tank.
Moosivankam do.
Vyavoor do.
Thottanavel do.

Estimates will be furnished shortly, and cause of breaches will be therewith reported.

Submitted to Government for information.

(Signed) A. J. M. BOILEAU, Colonel, R. E.,
Superintending Engineer, 4th Division.

No. 134. ORDER THEREON, 9th January 1867, No. 63.

CIVIL WORKS, No. 23.

Ordered to be recorded.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 4th Division.
,, Controller of Public Works Accounts.

Exd. S. T. Augustin.

Caliampoondy

Estimates

From, H. B. Leggett Esq.
By Resident Engineer 4th Range
Madras District

To, Colonel D. D. Barlow R. E.
Superintending Engineer 4th Division

I have the honor to inform you that the undermentioned Tanks have been breached during the late heavy rains. Orders will be sent for their repair.

Mambakam Tank	Theriyampandy Tank
Vadapathy Tank	Nagar Tank
Nelway large Tank	Olloocaray Tank
Ootramallore Channel and	Bamistore river Channel
cross bund between large	Thelavampandy Tank
Tank and Chetty	Chetty Tank
~~Thelavampandy Tank~~	Salavankam Tank
Radimungalam Large Tank	Bennagar Channel
Marotham Kaligutah and	Loonimugolathur Tank
Channel washed away	Thelavampandy Tank
Marothampandy Tank	Boothoohary Tank
Thetalam Tank	Kalepattah Channel
Camarazapooram Channel	Vyavoor Pissi Tank
Seeromallore Tank	Moodwan Kair Tank
Malayoncealum Channel	Vyavoor Tank
and cross bund between	Thattanam Tank
Chetty and large Tank	
Lahimpandy Tank	

Estimates

Estimates will be furnished shortly and cause
of breaches will be therewith reported.

I have the honor to be
Sir
Your most Obedt. Servant
H. B. Leggat

Sy. District Engineer to Range
Madras District

N^o 3791.

Submitted to the ~~Secretary~~
to Government ~~for~~ for information

By Order of Colonel A.

Superintd. Office of Supt. Engineer to Govt.
Madras 20 Decr 1866.

Dec 17 1866