

(1) Number of pages 4(2) Date of repair 25-5-48

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.**Government of Madras.****Public works DEPARTMENT.**

G.O. No. 63	Press
121-22	~~Mis~~
Dated 8 1	1868.

Not to be folded or roughly handled

(1) Number of pages 6(2) Date of repair 26.5.1943

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.**Government of Madras.***Public works* **DEPARTMENT.**

G.O. No. <u>62</u>	Press ~~Mis.~~
<u>119-20</u>	
Dated <u>8</u> <u>1</u> <u>1868</u>	

Not to be folded or roughly handled*12/11*

11

*Proceedings of the Madras Government, Public Works Department,
8th January 1868.*

No. 119. Read the following Proceedings of the Madras Government in the Ecclesiastical Department:—

Sanctioning the repair of the gateway of the Viza- } (Here enter 31st December 1867, No 310.)
gapatam Cemetery at a cost of Rupees 223.

No. 120. ORDER THERDON, 8th January 1868, No. 62.

CIVIL WORKS, No. 14.

Communicated to the Superintending Engineer of the 1st Division for information and guidance.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 1st Division.
.. Accountant General.
.. Controller of Public Works Accounts.

Exd. S. T. Augustin.

Estimate of the probable cost of Ordinary repairs to the walls, and especially the Entrance Building at the New Cemetery of Tzucapatan.

Measurements				Particulars of work	Rate	Amount	Total	Remarks
Length	Breadth	Height or Slope	Circular contents					
<u>Ordinary Repairs</u>								
41	"	9	61.38	Front wall				The entrance building Cemetery of Tzucapatan according to the Standard and consists of two rooms side of a covered gateway. At the inner side of the gateway is an open archway. At the outer side is a sign. The doorway covered by the circular arch in rear and the flat arch in front have had very defective work in the arches which has caused the roof over the entrance to crack and leak. It is proposed to rebuild the arches and the terra cotta and to substitute strong iron and steel which, being of great
105	"	9	72.90	Side do				
100	"	9	90.00	Do do				
104	"	9	90.72	Rear wall				
48	"	12	23.04	Front & rear wall of Entrance Building				
11	"	"	"	Partitions or Sidewalls				
14	"	2	11.56	Parapets				
			352.72	Cost of Repairing	1	22.09		
			352.72	Do of Whitewashing	2.8	58.12		
		4	Do of Plastering	2.6	9.8			
<u>Special Repairs</u>								
				Taking of Centre portion of roof and Archway to front		10		
1-6	2	2.4	Rubble Masonry over arch					
4	1 1/2	3 1/2	Parapet wall	1 1/2	4.5	3.97		
		5 1/2	or 2 1/8 Cost of Rubble Masonry	4.9	8.50			
1 1/2	1 1/2	4 9/16	do of Archwork over front door					
			stones for fixing cracks	2	16			

To the Venerable the Archdeacon.
Public Works Department, with plan and estimate.

2 1/4	6.63	Parapet	2.6	4.5	
	1.84	Cost of plastering	16.10	30.13	
	1.85 1/2	do of Terracing Complete			
14		Arched gateway in front		1.8	
17.6	10.1	with Ornamental hinges		21.8	
		Complete		11.7	
		Contingencies at 5%			
		Total Repairs			22.3

Executive Officer's Office
Tzucapatan

J. Beatty
Executive Officer
Tzucapatan

No 46. Read the following letter from the Venerable the Archdeacon of Madras, to the Chief Secretary to Government, Fort St. George; dated Madras, 7th December 1867,
No 385. Read a letter from the Reverend W M S Babington, Chaplain of Vizagapatam, dated 1st December 1867, in relation to the entrance gate of the cemetery,

No 46. Read the following letter from the Venerable the Archdeacon of Madras, to the Chief Secretary to Government, Fort St. George; dated Madras, 7th December 1867,
No 385. Read a letter from the Reverend W M S Bibington, Chaplain of Vizagapatam, dated 11th December 1867, relative to the entrance gate of the cemetery,

I have the honor to forward a letter from the Reverend W M S Babington, Chaplain of Vizagapatam, together with an estimate and plan for the repair of the entrance gate of the cemetery, amounting to Rupees 213, with a letter on the subject from the Executive Engineer, Vizagapatam. Although the building was constructed so recently as 1862 yet that the estimated for are quite necessary to its safety.

2 It appears that although the building was constructed so recently as 1862 yet that the dilapidations are very considerable, and the repairs estimated for are quite necessary to its safety. The Government is anxious to embrace the present opportunity of giving an ornamental character to the building, and in the accompanying letter, with proposed additions, is shown a plan of the proposed alterations.

2 It appears that although the building is in good repair, the dilapidations are very considerable, and the repairs estimated for are quite necessary. It is proposed to give an ornamental character to the gate, and has requested me to submit the accompanying letter, with proposed additions marked on the plan in pencil.

4 The Executive Engineer admits that these additions would be improvements, and with that view the Right Honorable the Governor in Council may be disposed to sanction them

From the Reverend W. M. S. BABINGTON, B. A., Chaplain of Vizagapatnam, to the Venerable the Archdeacon of Madras; dated Waltair, 14th November 1867

From the Reverend W. M. S. BABINGTON, the Archdeacon of Madras; dated Waltair, 14th November 1867.

I herewith have the honor to enclose you an estimate of the repairs required at the Waltair new cemetery. I also beg to forward you a letter from the Executive Engineer of the District in which I also beg to forward you a plan and estimate of the alterations and improvements which the Local Trustees agree with me, most decidedly, to carry out.

I herewith have the honor to enclose you a letter from the Executive Engineer of the new cemetery. I also beg to forward you a letter from the Executive Engineer of the new cemetery. I also beg to forward you a letter from the Executive Engineer of the new cemetery.

answer to my request to him for a plan and estimate. The Lay-Trustees agree with me, and think that such an improvement as shown in the enclosed plan would be desirable; and that, while repairs are executed, they may, as well be thoroughly complete, especially as the building of 1862 is by no means a well formed or safe structure.

that such an improvement in the structure of the bridge, if repairs are executed, they may, as well be a strong and safe structure. 1862 is by no means a well formed or safe structure. The cost, we imagine, could not exceed a total of double the amount mentioned in this estimate.

From the Executive Engineer, Visagapatnam, to the Reverend W. ...

From the Executive Engineer, Vizagapatam, dated Waltair, 6th November 1867, No 500.
Chaplain of Vizagapatam, dated Waltair, 6th November 1867, No 500.
I have the honor to send you an estimate of the repairs required at the new cemetery
to your letter of 22nd ultimo, I beg to return the plan sent with it. The
plan is of the year 1862, on a standard plan sanctioned by

2 With reference to your letter of 22nd ultimo, I beg to return the plan sent with it. The cemetery was erected so lately as 1862, on a standard plan sanctioned by the Ecclesiastical Department, and I cannot undertake the re-entrance building at the cemetery which would, in my opinion, be a waste of public

2 With reference to your letter of the 10th inst., in relation to the entrance building at the cemetery was erected so lately as 1867, I have the honor to inform you that the same has been examined by the Government, and approved of by the Ecclesiastical Department, and I cannot undertake the possibility of proposing alterations in the plan which would, in my opinion, be a waste of public money.

3 Possibly, however, you may regard these alterations in the light of improvements, and purpose undertaking them from private or other funds at your own disposal, and in that case I shall be happy to furnish you with a plan and estimate, on your obtaining the requisite sanction of Government.

4. Having only one Draftsman for the heavy work of this office, I am obliged to guard against wasting his time on plans, &c, which it is possible may never receive sanction.

ORDER THEREON, 31st December 1867, No. 310.

No. 47.

The Governor in Council sanctions the repairs as estimated by the Executive Engineer at Rupees 223.

2 Although the more ornamental and expensive alteration suggested by the Chaplain of Vizagapatam is not sanctioned, the Governor in Council will not object to the plan proposed. Rupees 243, can be expended beyond the amount above stated, at the request of the Vizagapatam Church.

2 Although the more ornamental and expensive design proposed for the Church at Vizagapatam is not sanctioned, the Governor in Council will not object to the plan proposed provided that the additional expenditure beyond the amount above stated, Rupees 243, can be met from any source at the disposal of the Lay-Trustees of the Vizagapatam Church.

(True Extract).

(True Extract).

W. H. H. H.
Chief Secretary.

To the Venerable the Archdeacon.
Public Works Department, with plan and estimate.

28 Feb 15

June 1/5

310

802 223

210. 62-875 January 17

Write carefully

acid

1562

Command to the
Supr Engineer of the
1st Div for information
and guidance:

Chut & Dagey
8th Jan'y 1868 }

2053/Ann ✓
" 2187 ✓
" Cambridge ✓



W. C. C. C.