M.R.O. 11—77/55—8-4-41.

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

DEPARTMENT.

G.O. No.	Press Mark
Dated ____ 19	

Not to be folded or roughly handled

Proceedings of the Madras Government, Public Works Department, 8th October 1869.

No. 155. Read the following letter from the Acting Superintending Engineer, 1st Division :—

Submits certain remarks with reference to G. O., of the 4th September 1869, No. 2,902, for the consideration of the Government regarding the sanctioned design for a Talook Cutcherry. (Here enter 24th September 1869, No. 2,366.)

No. 156. ORDER THEREON, 8th October 1869, No. 3,252.

CIVIL WORKS, No. 22. ORDERED to be recorded.

(True Extract.)

Colonel, R.E.,
Secretary to Government.

SUPERINTENDING ENGINEER'S OFFICE, 1ST DIVISION

DOWLAISHWARUM, 24th September 1862

No. 2366

From

Captain J. F. Fischer R.E

Superintending Engineer

1st Division

To

Colonel C. S. Orr R.E.

Secretary to Government P. W.

Madras

SIR,

I have the honor to acknowledge receipt of G.O. 4th September 1862 No 2908 and beg to submit the following remarks for the consideration of the Government.

1 The idea that the roofs of buildings should be adapted to the latitude of a climate may be "a would-be architectural theory" but it is one which has been pretty generally adopted all over the world in practice, and the consideration that the latitude is unalterable should, one would suppose, lead to the conclusion that materials must be used to suit it and not the converse construction which is in fact nothing more than leaving the earth before the house.

2 I was not suggesting that the roofs of the buildings in question did not afford sufficient protection from the sun to the walls

walls and the area surrounding
larger area for the whole to contain all the
necessary and that the
from the circumference
right angled
base in certain
the area of
feet in excess of
roof for every ten feet of
4 Branch of the
as stated above
station but of
already been provided
in the construction
hospitals per
to be laid under the
Method of Ventilation
Sanitated air before
5 Near always can be
that in this country
heats and treasuries should be afforded
with a tiled roof this is quite
cable, the object a most
ting to destroy which is really
known to those who have considered what
is likely to occur in the branch of
outbreak taking place
Circumference

occurrence in a country like
6 The General
for purposes of
attached would be caught
rat in a gin, the odour of the
Court could be cleansed from
without a shot being
to enter, the only
at points where
if therefore the position
at once no doubt
police patrol a station
long as possible, or longer
use the means of explosive
effectually, there could be no
their first duties
as these respectfully
not got them and cannot
duty -

I have the honor to be

Your most

Obt. Servt

H. Tichy Gunner

Public 1869 Draft
No 2368.
From Mr. H. 136.
The M. Supt Engineer
1st Division.

To The Secretary
to Government Pub. Wks
Madras

Dated 24th September 69
Recd 28th Oct. "

Submits certain remarks
with reference G.O. of the
4th September 1869 No 2902
for the consideration of the
Government.

No 3252 8 Oct. 69

With an order

Fort St. George
8 Oct. 1869

No 3252
Ordered &c &c recorded.

1 Engr 1 Draft
Recd 9/10/69.

Ser 4136

Out of USGS Atlas.

PUBLIC WORKS

No. 155-156