

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. <i>3091</i>	Press _____
<i>417-18</i>	Mis. _____
Dated <i>19-12-1870</i>	

Not to be folded or roughly handled

10

*Proceedings of the Madras Government, Public Works Department,
19th December 1870.*

No. 417. Read the following letter from the Superintending Engineer, 4th Division, to the Secretary to Government, Public Works Department, dated Madras, 28th November 1870, No. 3,570 :—

With reference to G. O., in the Public Works Department, No. 132, dated 24th November 1870, I have the honour to report that the sum of Rupees 110, for replacing the portion of the copper band of the lightning conductor of the church at Saint Thomas' Mount, can be met from the current year's allotment for Civil Repairs in the Presidency District.

No. 418. ORDER THEREON, 19th December 1870, No. 3,091.

CIVIL WORKS, No. 35.

THE Government approve of the sum of Rupees 110, which is reported in this letter to be available, being appropriated to replacing the portion of the copper band of the lightning conductor of the church at Saint Thomas' Mount, which has been stolen.

(True Extract.)

N^o 3570 Sup Engineer's Office 4th Fl^r
Madras 28th November 1870.

To Mr.
Colonel G. F. Wilkinson R.E.
Sup Engineer 4th Division

To
Colonel G. F. Orr R.E.
Secretary to Government P.W.D.

Sir,
With reference to G.O. in the
P.W.D. N^o 132 dated 24 November
1870, I have the honor to report that
the sum of Rupees 110 for replacing
the portion of the copper band of the
Lightning Conductor of the Church
at Saint Thomas Mount can be
met from the current year's allotment
for Civil Repairs in the Presidency
District.

I have the honor to be
Sir
Your most obedient servant

Wm. J. C. Colwell R.E.
Sup Engineer 4th Fl^r

CP

P. M. D. W

No 3091

Proceedings of the Madras Government

Read the following

From
The Super Engineer } (14. E. No. 3570 of 28th Nov 1900)
 Lt. Col. D. S. S.

The Government approve of the sum of Rs. 110, which is reported in this letter to be available, being appropriated to replacing the portion of the copper band of the lightning conductor of the church at Saint Thomas Mount, which has been stolen.

The Super Engineer, Lt. Col. D. S. S.
Ecclesiastical Dept.
Controller
Trichy District

Resd 20/12/00

1570 No. 3570
No. 4821
From
The Super Engineer
Trichy District
To
The Secy to Govt
1900

State 593-3
Dec 29 1900
According to the
sum of Rs. 110 for replacing
the portion of the copper
band of the lightning
conductor of the church
at Saint Thomas Mount.
can be met from the
constructive estimate
for civil works in the
Trichy District.
No 3091-19 Dec 1900

No 3091-19 Dec 1900

Apr 1871

Govt. of 1870: Madras.

PUBLIC WORKS.

To the Superintending Engineer
4th (Madr.)

Dated

Recd.

Encl.

G. O. 17th Dec 1870, No. 3091.

Nos. 417 & 418

Respecting Land Revenue. The
Administrative Officer, Mr. Brown
the current year's estimate
for "Civil Repairs" and also
in relation to the estimate of the
Superintendent of the
Commissioner of the District of
St. Thomas' Mount which
has been taken, & which