

(1) Number of pages 2

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public works DEPARTMENT.

G.O. No. 2988	Press Mis.
357-58	
Dated 20. 11	1871.

Not to be folded or roughly handled

27-44

*Proceedings of the Madras Government, Public Works Department,
20th November 1871.*

No. 357. Read the following Endorsement of the Public Department, dated Fort St. George, 13th November 1871 :—
From the Archdeacon of Madras, to the Chief Secretary to Government, Fort St. George, dated Madras, 10th November 1871, No. 3.

I HAVE the honour to forward a letter from the Sanitary Inspector drawing my attention to the present objectionable state of the Cathedral compound, which is in fact its normal condition during the heavy rains. It is almost entirely covered with water, and the Trustees have no means at their disposal for draining the compound. I have, therefore, no alternative but to solicit the sanction of Government in the Public Works Department, either for raising the level of the compound, (as proposed by the Sanitary Inspector,) or for draining it from its present level into the large tank at the east end of the church.

2. Trusting that His Excellency the Right Honourable the Governor in Council will be pleased to issue immediate orders for either of the above works to be done as may most effectually remove the cause of complaint.

TRANSFERRED to the Department of Public Works for the issue of the necessary orders for draining the Cathedral compound.

(Signed) R. S. ELLIS,
Chief Secretary.

No. 358. ORDER THEREON, 20th November 1871, No. 2,933.

CIVIL WORKS, No. 20.

COMMUNICATED to the Superintending Engineer of the 4th Division, who will report which of the alternative arrangements referred to he would recommend for draining the Cathedral compound, and submit the requisite estimate.

(True Extract.)

(Signed) J. CARPENDALE, Colonel, R.E.,
Secretary to Government.

To the Superintending Engineer, 4th Division, with one Enclosure (to be returned).
,, the Ecclesiastical Department.

Exd. E. C. Shunker.

P. W. 1871 Depart
Reels: Sept 10 5434

From the Double
The Archd. of Massas

To the Hon. R. S. Ellis esq
Chief Secy. to Govt
Fort St George

No. 297.

No. 3. Recd:

Dated: 10. November 1871
Reels: 14"

Submits a letter from
the Sanitary Inspector
calling attention to the
present state of the Cathedral
Compound, and solicits the
sanction of Govt. to the
drainage of the compound
proposed by that Officer

With an order
No. 2933-20 Recd: 17

Fort St George
13. Nov 1871

Transmitted to the Dept of
Public Works for the issue of the
necessary orders for draining the
Cathedral compound

Chief Secy

2933 5' incl. 100

No 2933.

Communicated to the
Superintending Engineer of the 11th
Division who will report which of
the alternative arrangements referred
to he would recommend for draining
the Cathedral Compound, and submit
the requisite estimate.

Jf.

Starts - 10/1/13
20-10-13

52

To the Sup^r Eng^r 11th Divⁿ (to be sent to the
Ecclesiastical Dept -
P.L. 24/1/13 has been referred.

Ch. 5236

City of 1871 Madr. S.

PUBLIC WORKS.

To The Superintendent Engrs
4th Division

Dated,

Recd.

G. O. 20th Nov. No 2933

Nos. 357 & 358

Cathedral Compound.

The S. Engrs of the C. D. &c.
requested to report the
arrangements to be made
recommenced for draining
the Cathedral Compound
& to submit the requisite
estimate.