M.R.O. 1—77,006—8-6-37.

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works **DEPARTMENT.**

G.O. No. 2961	Press / Mis.
408-409.	
Dated 23-11-	1871.

Not to be folded or roughly handled

K.M.S.

Proceedings of the Madras Government, Public Works Department, 23rd November 1871.

No. 408. Read the following letter from the Acting Superintending Engineer, 1st Division, to the Secretary to Government, Public Works Department, dated Dowlaishweram, 7th November 1871, No. 2,470 :—

In forwarding herewith an estimate, amounting to Rupees 380, for repairing the Tahsildar's Cutcherry at Rajahmundry, I have the honour to request, as this amount is in excess one-fourth the value of the building, you will be good enough to obtain the sanction of Government for the same, and place the necessary funds at my disposal from the Provincial Reserve grant.

No. 409. Order thereon, 23rd November 1871, No. 2,961.

CIVIL WORKS, No. 24.

The estimate of Rupees 380 is sanctioned; but the Government being unable to provide the amount, it will rest with the Superintending Engineer to do so by transfers.

(True Extract.)

Colonel, R.E.,
Secretary to Government.

Detailed Estimate for 1871-72
Rajahmundry Sailing
Godavery District.

Work. Repairing Thasildar's Cutcherry at Rajahmundry

Description of work	Nos	Measurement Length	Breadth	Depth	Cubic Contents
Shifting tiles & repairing beamboo }	"	20½	14	"	287 ✓
hurdle	"	47	16	"	752 ✓
	"	19½	16	"	312 ✓
	"	67½	12	"	810 ✓
	"	66	12	"	792 ✓
					2,953½ ✓
					or
Shifting and repairing beamboo hurdle					Sqrs 29-53½
Removing a beam broken and substi- }	"	16'	6"	5"	"
tuting a new one with hole					
Removing the old mud wall and building a brick wall with Chunam to prevent moisture					
Foundation to wall	"	75	2	4	600 ✓
Wall above	"	75	1½	10	1125 ✓
					1725 ✓
					63 24/27
Brick in Chunam					Cyds
Plastering the inside of new wall }	"	75	8½	"	637½ ✓
Repairing the floor in patches	"	"	"	"	400 ✓
					1037½ ✓
					or
Plastering 2 Coats					Sqrs 10-37½
Whitewashing					
Walls of Record Room	4	12½	8	"	400 ✓
	1	14½	9	"	130½ ✓
	"	14	8	"	112 ✓
	2	19	12	"	456 ✓
	2	12	12½	"	300 ✓
					1398½ ✓

					1398½
Walls of Treasury Room	2	16	13	.	416
	2	12	15	.	360
	.	22	14	.	308
Walls of Thasildars room	3	24	8	.	576
	1	24	12	.	288
	.	10	8	.	80
	.	46½	11	.	511½
Do of Hall	.	72.	15	.	1080
	"	44	8	.	352
	"	13½	8	.	108
	"	15	12	.	180
Basement	"	40	3	.	120
					5778
					or
Whitewashing 2 Coats Chunam				Sqrs	57.78
Contingencies	"	"	"	"	

No 6 Cavy Office
Samalcotta
September 1871

Assistant Engineer

Abstract Estimate of 1871-72
Rajahmundry Taluq
Godavery District.

Work—Repairing Thasildars Cutcherry at Rajahmundry

Quantity	Item	Rate	Per	Amt	Total
29 53/100	Sqrs Shifting tiles & repairing bamboo hurdle	1 8.	Sqrs	44 4 8	
1	Iron Beam	5..	Each	5..	
63 24/27	Cft Brick in Chunam	4..	Cft	255 8 10	
10.37½	Sqrs Plastering 2 Coats	2 8.	Sqrs	25 15.	
57.78	Do Whitewashing 2 Coats Chunam	" 4.	Do	14 7 1	
				345 3 7	
	Contingencies @ 10 per Cent			34 12 5	
				Total Rs	380 ..

No 6 Cavy Office
Samalcotta
21st September 1871

Assistant Engineer 1st Class

28/9/71

Major RE

Major & Superintending Engr

From

The Assistant Engineer
Chicacole Range

To The Supdg Engineer 1st Div

Dated 15th September 1871
Recd 16th Ditto

Estimate for repairing
Tahsildars Cutcherry at
Rajahmundry.

Superintending Engineer's Office, 1st Division.
Dowlaishwaram, 7th November 1871

No. 2470

From Major J. F. Fischer R.E.
Offg Superintending Engineer
1st Division

To Colonel J. Carshendale R.E.
Secretary to Government D. P. W.
MADRAS

SIR,

In forwarding herewith an Estimate, amounting to Rupees 380, for repairing the Tahsildar's Cutcherry at Rajahmundry, I have the honor to request, as this amount is in excess of the Fourth, the value of the Buildings you will be good enough to obtain the sanction of Government for the same, and to allow the necessary funds at my disposal from the Provincial Reserve Grant.

I have the honor to be
Sir
Your Most Obt. Servant

Constitution Major R.E.
Offg Supdg Engineer 1st Div.

P. W. S. 4483/71.
Enclosure in letter
No. 2470 dated 7th
November 1871 from
the Superintending
Engineer 1st Division
to the Secretary to
Government D. P. W.

P. W. 1871 Despatch

Linen No. 5483.

Major P. T. Fischer R.E.
Asst. Superintending Engineer
1st Division

To, Colonel [illegible] R.E.
Secretary to Government
P.W.D.
Madras.

Dated 7 November 1871
Received 17th

No. 2470

Epistle

Requests to obtain the sanction of Government to Estimate amounting to Rupees 380 required for repairing the Tahsildar's Cutcherry at Rajahmundry for reasons within stated.

No. 2961 - 23rd Nov/71.

Herewith an order

The estimate of Rs. 380 is sanctioned; but the Government being unable to furnish the amount, it will rest with the Superintending Engineer to pay it over.

To the Secretary to Government
" Collector of [illegible]
" Judicial Department

Rs. 24/11/71.

No. 5483

Govt of Madras.

PUBLIC WORKS.

To The Agt Superintending Engr. 1st Division

Dated.

Rcd. 17

G.O. 23rd Novr. No. 2961.

Nos. 1/188409

Tahsildar's Catcherry at Rajahmundry. The estimate of Rs. 580 for repairing the Tahsildar's Catcherry at Rajahmundry is sanctioned.