

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public works DEPARTMENT.

G.O. No.	1386	Press
44-45		Mis.
Dated	5-6-	1872.

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
5th June 1872.*

No. 44. Read the following letter from the Superintending Engineer, 5th Division, to the Secretary to Government, Public Works Department, dated Cuddalore, 27th May 1872, No. 48:—

WITH reference to the Order of Government of the 14th May, No. 1,267, I have the honour to state that I have received lists of breached tanks in the Salem District from the Collector and the Range Officers, but as yet no estimates. I am, therefore, unable to state what addition will have to be made to the allotment for Repairs Agricultural. This, however, will not interfere with the progress of the repairs. By far the greatest amount of damage caused by the storm of the 1st and 2nd was in the Salem Range.

2. The Executive Engineer has undertaken the repair of all works in three out of four of his taluqs, and has asked the Collector to get the breaches in the Salem Taluq closed, as the Overseer there has some heavy building works to look after.

3. In the 2nd Range of South Arcot fourteen tanks have either been breached or damaged so much as to require immediate repair, but the district generally has not suffered much from the storm, and the tanks have received a good supply of water.

P.S.—Since the above was written Mr. Lawford has stated that probably 20,000 Rupees will be required for the emergent works in his range, but the amount cannot be fixed with certainty as yet.

No. 45. ORDER THEREON, 5th June 1872, No. 1,386.

ESTABLISHMENT, No. 3.

It has been determined in re-arranging the Executive Ranges of the South Arcot District that No. III. Range shall be absorbed by addition of the Kallacoorchy Taluq to the Virdachelum Range, and of the Trickalore Taluq to the Cuddalore Range. In order to afford extra assistance to the Salem Range Officer, Colonel Foord is instructed at once to carry this into effect, and to detach Mr. Hawksworth for duty under Mr. Lawford as soon as he can be relieved by Mr. Bell, who will afterwards hand over the Trickalore Taluq to Mr. Norfor.

(True Extract.)

(Signed) G. W. WALKER, Colonel, R.E.,

Secretary to Government.

To the Superintending Engineer, 5th Division.
,, Controller of Public Works Accounts.

Exd. E. C. Shunker.

No. 48

33
Suptg. Engrs Office, 5th Div.,
Buddalore, 27th May 1872

From

The Superintending Engineer,
5th Division.

To

The Secretary to Government,
Public Works Department.

Sir,

With reference to the order of
Government of the 14th May No. 1267, I
have the honor to state, that I have re-
ceived lists of breached tanks in the
Salem district from the Collector and
the Range Officers, but as yet no Estimates.
I am therefore unable to state what addi-
tion will have to be made to the allotment
for Repairs Agricultural. This however will
not interfere with the progress of the repairs.
By far the greatest amount of damage
caused by the storm of the 1st and 2nd was in
the Salem Range.

2. The Executive Engineer has undertaken the repair of all works in three out of four of his taluqs, and has asked the Collector to get the breaches in the Salem taluq closed, as the Overseer there has some heavy building works to look after.

3. In the second range of South Arcot 14 tanks have either been breached or damaged so much as to require immediate repair, but the district generally has not suffered much from the storm, and the tanks have received a good supply of water.

I have the honor to be,
Sir,

Your Most Obedt. Servant

E A Smith Colonel R.E.

Suptg. Engineer, 5th Division.

P.S. Since the above was written Mr. Lawford has stated that probably 20000 rupees will be required for the emergent works in this range, but the amount cannot be fixed with certainty as yet.

E A Smith Col. R. E.
Suptg. Engineer 5th Div.

Recd 14 May/72 91324-325

P. W. 1872 ~~Richard C.~~
J. P. of ~~Good for~~ ~~11/10~~
The Suptg. Engineer
5th Division
The Secretary to Government
P. W. Deptt.

Dated 27th May 1872
Supd 29th No. 48.

Stating that lists of Irrigation works damaged by the late storm have been received, and the repairs have been undertaken, but that what addition will be required to the allotment for repairs Agricultural cannot be now reported, as no Estimates have yet been received.

No 1386. 5th Decr/72
With an order

No 44

Carry this into effect



22

மேல்க்குறிப்பிட்ட
No. 1386 க்கு மறுபதிலாக,
பெரியபாளையம் அங்கு
இருக்கும் இடம்
மேல்க்குறிப்பிட்ட இடத்தில்
உள்ளது. இது தான்.

[Handwritten initials and signatures: A.A., J. D.]

It has been deter-
mined in re-arranging
the Executive Ranges
of the South West Distt.,
that No. III Range shall
be absorbed by addition
of the Kallacorchy
Talook to the Vindachellam
Range, and of the Trich
alore Talook to the Cudda-
lore Range. In order
to afford extra assistance
to the Salem Range,
Officer Col^l Ford is
instructed at once to
carry this into effect

[Faint handwritten notes and signatures at the bottom of the right page.]

Supdy. Engineer 5th Div

C/2654

Govt. of 1872 Madras.

PUBLIC WORKS.

To the Superintending Eng^r
5th Division

Dated

Recd.

Encl.

G. O. 5th June 1872 No 1386.

Nos. 44 & 45

Ranges: Issuing instructions
for carrying into effect
the ~~arrangement~~ rearrange-
ment of the Executive
Ranges of the South
Arcot District.