

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public works **DEPARTMENT.**

G.O. No.	20 13	Press
391-392		Mis.
Dated	23 - 8 -	18 '12 .

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
23rd August 1872.*

No. 391. Read the following Endorsement of the Revenue Department, dated 16th July 1872:—

Read the following Proceedings of the Board of Revenue, dated 9th July 1872, Miscellaneous No. 4,761.

Read the following letter from the Acting Collector of North Arcot, to the Secretary to the Board of Revenue, dated Camp at Bireddipulli, Palmanair, 1st July 1872, No. 280.

In continuation of my letter of the 25th ultimo, No. 268, I have the honour to forward a statement showing the extent to which each irrigation work was damaged by the late cyclone in the Poloor Taluq.

2. In the statement which accompanied my letter, dated 3rd June 1872, No. 230, I reported on the strength of a report received from the Tahsildar of Poloor that that taluq had sustained no damage by the hurricane that occurred on the 2nd May last; but the Tahsildar has now forwarded to me this statement (of which the enclosure is a translation) without attempting in any way to explain the strong contradiction between the two reports submitted by him on the effects of the storm in his taluq.

3. He has now been called upon, through the Acting Sub-Collector, for an explanation of his conduct in this matter, and I shall submit it in due course for the information of the Board of Revenue.

List showing the Irrigation Works breached during the late storm in the Poloor Taluq, North Arcot District..

No. of the Village.	Name of the Village.	Revenue Department.	Particulars of breaches, etc.
		RS.	
6	Jadadaricooppum	86	The bund of the tank has breached in one place, 10 yards long, 5 yards broad, and 4 yards deep.
28	Vogoor	222	The tank has breached near its sluice 8 yards long, 17 yards broad, and 3 yards deep.
210	Vodalavadi	1,375	The bund has sunk in in two places, one 60 yards long, 2 yards wide, and 1 yard deep, and the other 100 yards long, 1 yard broad, and 1 yard deep.
212	Verasammanoor !... ..	546	The bund is sunk in to the extent of 100 yards in length, 2 yards in breadth, and 1 yard in depth.
213	Modanapoliem	134	The sluice has been destroyed and the bund breached 3 yards in length, 10 yards in width, and 3½ yards in depth.
215	Kolalavaridi... ..	44	The bund has breached in the middle 8 yards long, 10½ yards wide, and 3 yards deep.

PROCEEDINGS OF THE BOARD OF REVENUE,

Dated 9th July 1872.

Read the following

No. 280

From

W. P. Whiteside Esquire
Acting Collector of North Arcot,

To

J. Cross Esquire
Secretary to the Board of Revenue
Madras.

SIR,

In Continuation of my letter of the 25th ultimo at No. 268, I have the honor to forward a statement showing the extent to which each irrigation work was damaged by the late cyclone in the Poloor Taluk.
In the statement which accompanied my letter dated 3rd June 1872 at No. 230, I reported on the strength of a report received from the Tahsildar of Poloor that that Taluk had sustained no damage by the hurricane that occurred on the 2nd May last; but the Tahsildar has now forwarded to me this statement of which the Enclosure is a translation without

Proceedings of the Madras Government, Public Works Department,
23rd August 1872.

List showing the Irrigation Works breached during the late storm in the Poloor Taluk,
North Arcot District.—(Concluded.)

No. of the Village.	Name of the Village.	Revenue Department.	Particulars of breaches, etc.																
217	Murudampadi	RS. 239	Breached in three places to the extent shown below— <table> <tr> <td>1st</td><td>Length.</td><td>Breadth.</td><td>Depth.</td></tr> <tr> <td>2nd</td><td>6</td><td>9</td><td>3</td></tr> <tr> <td>3rd</td><td>34</td><td>6</td><td>2</td></tr> <tr> <td>3rd</td><td>10</td><td>4</td><td>1</td></tr> </table>	1st	Length.	Breadth.	Depth.	2nd	6	9	3	3rd	34	6	2	3rd	10	4	1
1st	Length.	Breadth.	Depth.																
2nd	6	9	3																
3rd	34	6	2																
3rd	10	4	1																
222	Appedu	625	The sluice has been damaged in four places.																
223	Vilvarayanellore	138	The bund is sunk in in five places.																
224	Indravanum	586	The sluice has been damaged inside to the extent of 1 yard square.																

(Signed) W. S. WHITESIDE,
Acting Collector.

SUBMITTED for the information of Government.

REFERRED to the Department Public Works.

(Signed) W. HUDLESTON,
Secretary to Government, R.D.

No. 392.

ORDER THEREON, 23rd August 1872, No. 2,013.

IRRIGATION, No. 17.

ORDERED to be recorded.

(True Extract.)

(Signed) G. W. WALKER, Colonel, R.E.,
Secretary to Government.

List showing the irrigation work done during the
 late storm in the Pithor Taluk North West District

Sl. No.	Name of the village	Revenue Receipt dent	Particulars of breach etc
6	Jadadrienshpur	86	The bunds of the Jank has breached in one place 10 yards long, 5 yards broad, and 4 yards deep.
28	Vogoor	222	The bank has breached near its sluice 6 yards long, 17 yards broad, 13 yards deep.
210	Vodalaradi	1375	The bunds has sunk in in two places one 60 yards long, 2 yards wide, 1 yard deep and the other 100 yards long, half yard broad 4 half yard deep.
212	Verasammanoor	546	The bunds is sunk in, to the extent of 100 yards in length 2 yards in breadth and half yard in depth.
213	Modanapoli	134	The sluice has been destroyed and the bunds breached 3 yards in length, 10 yards in width, and 3 1/2 yards in depth.
215	Kolalaradi	44	The bunds has breached in the middle 8 yards long, 10 1/2 yards wide and 3 yards deep.
217	Mundampadi	239	Breached in 3 places to the extent shown

PROCEEDINGS OF THE BOARD
 OF REVENUE

No. 2225

1072
 23494

Date 9 July 1972
 Despatched 9 July 1972
 Recd 19 July 1972

SUBJECT

Submitting for the
 information of Board
 letter from the Collector
 of the District forwarding
 a statement showing
 the extent of breach etc
 irrigation work done
 during the late
 cyclone in Pithor
 Taluk North West District

16 July 1972
 L. M. S. S.
 Secretary, P. O. 1
 Order to be recorded.
 1072

Shankhili

Pl.	Length	Breadth	Th.
1st	6	9	3
2d	34	6	2
3d	10	4	1

- 222 Appedus — 625 The sluice has been damaged in 4 places
- 223 Nilomayamellere — 138 The band is broken in 5 places
- 224 Sadranam — 586 The sluice has been damaged to the extent of 1 yard & 2 quare

C. Whilkin

Ag Collector

Q. 11/1

Dec. 23/25/72

In a letter from the
Rev. George Jones dated
the 12th of Dec.

Received of the
71 July 1872 Lt. 280.

P. M. 3494/72.

John M. 3332/72

James & Co. 1872

For

John M. 3332/72

C/2 3494

Gobt. of 1872 Madras.

PUBLIC WORKS. ✓

To

Dated

Recd.

Encl. ✓

G. O. 23rd Aug 2013.

No. 2914392

Irrigation Works. Per.

Mr H. E. S. Per. on the
letter from Mr. S. S. S. S.
of North Arcot submitting
statements of Irrigation
works damaged by the
late Cyclone, records.