

*Proceedings of the Madras Government, Public Works Department,
3rd February 1872.*

No. 68. Read the following Proceedings of the Board of Revenue, dated 22nd December 1871, Miscellaneous No. 557:—

Endorsement of the Acting Collector of the Kistna District, dated Masulipatam, 25th December 1871, No. 3,615.

From the Superintending Engineer, 2nd Division, to the Acting Collector of the Kistna District, dated Camp at Parikeed, 18th December 1871, No. 184.

I HAVE the honour to forward an estimate, amounting to Rupees 476, for the repairs of a detached building in the compound of the Sub-Collector's Cutcherry at Guntur for your approval. It has been prepared by the Range Officer at the request of the Sub-Collector. As the estimated cost of the repairs exceeds one-fourth of the approximate present value of the building, the sanction of Government for it is necessary, *vide* paragraph I., Clause III., Chapter XXIV., of the Public Works Code.

2. The walls and roof are so much shaken and cracked that the building is scarcely safe; if early measures are not taken, we shall have I fear to pull it down.

SUBMITTED to the Board of Revenue for sanction.

SUBMITTED accordingly for the sanction of Government.

No. 69. ORDER THEREON, 3rd February 1872, No. 335.

CIVIL WORKS, No. 3.

SANCTIONED.

(True Extract.)

Colonel, R.E.,
Secretary to Government.

To the Superintending Engineer, 2nd Division.
" Controller of Public Works Accounts.
" Board of Revenue.

Erd. S. T. Augustin.

Submitted

Revenue Department

Miscellaneous No. 557, dated 1872

Proceedings of the Board of Revenue
dated 22nd December 1872

No. 184. Read the following

From, Colonel F. J. Moberly R.E.,

Superintending Engineer 2nd Division

To, J. C. Haunington Esquire

Ag. Collector, Hista District

Sir, I have the honor to forward an estimate amounting to Rs 476 for the repairs of a detached building in the compound of the Sub Collector's Cutcherry at Guntur for your approval. It has been prepared by the Range Officer at the request of the Sub Collector. As the estimated cost of the repairs exceeds one fourth of the approximate present value of the building, the sanction of Government for it is necessary vide para I clause III Chapter XXIV of the P. W. Code.

2. The walls and roof are so much shaken and cracked that the building is scarcely safe; if early measures are not taken we shall have to pull it down.

Superintending Engineer's Office
2nd Division
Camp Parikud
18th December 1871

I have &c.
(Signed) F. J. Moberly R.E.
Supr Engineer 2nd Divⁿ

(True Copy)
Submitted

Enclosures 2.
Detailed and
Abstract —
Estimates.

No. 3615

Submitted to the Board of
Revenue for sanction.

Kistna District
Collector's Office
Masulipatam
(Signed) J. C. Haunington
Acting Collector
25th December 1871

Submitted accordingly for
the sanction of Government.

(True Copies and Extract)

J. C. Haunington
Acting Collector

The Secretary to Government
Revenue Department
with 2 Enclosures.

[Signature]

ABSTRACT-ESTIMATE-NO. 29. OF 1871-72
District Kistna

Work

Repairing the North & East rooms attached to Telegraph
Office in the Compound of Sub Collectors Cutcherry at
Guntur -

Quantity.	Description of Charges.	Rate.	Amount.	Total.
7½	Cyds of brick in chunam per Cyd	5 8 -	41 4 -	
87½	Cyds of Teak wood work per Cyd	3 8 -	306 4 -	
9 9/10	Sqrs of removing the roof and reconstructing it with ½ portion of new paw and ½ portion of new flat-tiles per sqrs	5 12 -	54 15 9	
24	Sqrs of whitewashing in 2 coats per sqrs	4 -	6 -	
3	Sqrs of plastering in one coat per sqrs	2 8 -	7 8 -	
5 5/8	Sqrs of do in 2 coats per sqrs	3 8 -	19 11 -	
2	Mounds of rafters nails 108 in number per mound	3 -	6 -	
2½	do reaper nails 1650 in number per mound	3 -	7 8 -	
	Repairing and wiring dome - - - - -	- - -	4 -	
	Superintendence & sundries per Cent	5 -	22 -	
			463 2 9	

Manning & Co
25.12.71
As Collector

23 Aug 71
Guntur

This Estimate prepared at the request of the Collector is for work to be done
in and near the Sub Collector's Office which is in a very ruinous state and as
it is not a small building and a portion of the roof is gone and the walls are
falling in some places and the floor is in a very bad state and
the rooms are very small and the work is very much increased for the
value of the building is 1000 Rupees.

[Signatures]
476-0-0

No 29 of 1871-72

Abstract - Estimate for repairing the North & East rooms of the kind in attached to Guntoor Sub Collector's Office used for depositing Revenue Settlement

2/8/82

Detailed Estimate of 29 of 1871-72

District of Pudukkottai

Work

Repairing the North and East rooms attached to Sub Collector's Office in the Compound of Sub Collector's Office, Pudukkottai

Particulars	Number	Measurements				Contents
		Length	Breadth	Depth or Height		
Repairing to cracks in the walls of North or Revenue Settlement record room, and 2 cracks in the wall of East room						54
Removing the portion of walls from top to bottom of wall plate & rebuilding it	1	99-6	1-6	1-0	149-3	
Total brick in chimney in 1/2 ft						202-8 on 7 1/2 Cys
Leak wood work						
Common rafters to North or Settlement record room	29	16-3	0-2 1/2	0-6	49-1-1	
High rafters to East room	2	21-6	0-4	0-8	9-6-8	
Common rafters for do	1	16-3	0-2 1/2	0-6	1-8-3	
Jack rafters to do	16	16-3	0-2 1/2	0-6	27-1-0	
Total Cubic ft of Leak wood work on						87-5-0 on 87 1/2 nearly
Removing the roof of North and East rooms and reconstructing it with 1/3 portion of new pan-tiles and 2/3 portion of new flat tiles						
North or Revenue Settlement Record room	1	29-6	16-6		486-9	
East room { Front	1	14-0	16-6		231-0	
Rear	2	7-3	16-6		239-3	
Total Removing the roof of North & East rooms & 1/3 ft						957-0 on 970 1/2
Whitewashing in 2 Coats -						
Inside of South side wall of North or Revenue Settlement record room	1	28-0		16-0	448-0	

Do of north side wall of do	1	28-0	10-0	280-0
Do of east and west walls of do	2	10-9	13-0	279-6
Inside of east and west walls of east room	2	23-0	10-0	460-0
Do of gable and over west wall of do	1	23-0	3-0	69-0
Inside of north & south walls of do	2	11-0	10-0	220-0
Outside of north walls of north on				
Revenue Settlement Record room and	1	82-0	9-3	758-6
East room and south and east wall				
of East room				
Soffits and sides of door ways in	2	17-0	1-2	39-8
walls of north and east rooms				
Soffits and sills and sides of	2	17-0	1-2	39-8
windows in walls of East room				
Do of north room	2	11-6	1-2	26-10
Total whitewashing in 2 coats				2621-2

Deduction

Door ways in walls of north and	2x2	4-0	6-6	104-0
East rooms				
Window-ways in walls of East room	2x2	3-6	5-0	70-0
Do in walls of West room	2x2	2-9	3-0	33-0
Total deduction in whitewashing in 2 coats				207-0

Total whitewashing in 2 coats less deduction 2414-0

Plastering in one coat to some portions of walls

Plastering in 2 coats -				
Floor of north or Revenue Settlement				
Record room	1	28-0	10-9	301-0
Floor of East room	1	23-0	11-0	253-0
Sills of door way	2	4-0	1-2	9-4
Total plastering in 2 coats				563-4

Rafter nails -
 Reeper nails -
 Repairing doors and windows -

23-August-1871.

Wm. H. Smith
 S. C. Smith

From the Officer in Charge
3 Range R

Letter No 16 of 1872

To the Engr. & Surveyor
in Charge

Reference to the
estimate amounting to
Rs 476-0-0

Order 23 of 11/11/71
No 29 of 11/11/72

Detailed Estimate
for repairing the
North & East rooms
of the building
attached to the
Collector's Sub Collector's
Cutcherry used
for depositing Revenue
settlement papers.

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Enclosure in letter from
the Engr. & Surveyor
to the Collector of R.
District No 104 of 18/11/71

Public Works 1872 Vol
No 393
Proceedings of the
Board of Revenue.

Dated 22nd January 1872
Recd. 23rd
Registered 25th

Submitting for sanction,
an estimate amounting
to Rs 476, for repairs to ad-
-joined building in compound
of Sub Collector's Cutcherry at
Guntur.

With an order

Govt. of 1872: Madras
PUBLIC WORKS.

10. The Superintendent Cong.
2nd Division

Encl 2✓

Feed.

G. 23" *Lehy* 1872, 825.

Nos. 68269

Sp. Pleuroz' (a. Cherryap)

Ambar. Ret. of Rs: 476
for repair of a detached
building in the compound
of the Sub. Mestoor's (Int-
cherry at Guntur, East-
India.