

(1) Number of pages 10

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 448-

277-278

Press
Mis.

Dated

16 2

1872.

Not to be folded or roughly handled

24 7-46

10

*Proceedings of the Madras Government, Public Works Department,
16th February 1872.*

No. 277. Read the following Endorsement of the Revenue Department, dated 2nd February 1872:—

Read the following Proceedings of the Board of Revenue, dated 1st February 1872, Mis. No. 763.

Endorsement of the Collector of South Arcot, dated Cuddalore, 8th January 1872.

From the Supervisor in charge of Villapuram Taluq, to the Executive Engineer, No. 1 Range, South Arcot District, dated Villapuram, 8th December 1871, No. 75.

As directed in your memorandum No. 809, dated the 5th instant, I humbly beg to inform you that the following is the report on the damages done to the anicuts in this taluq.

I. *Parany Anicut.*—The body and wing-walls of this anicut across the Pareaur river has been slightly damaged in several places during the recent high freshes. This anicut requires to be thoroughly repaired, which should be carried out at the commencement of next official year. The estimate for this work should be prepared by examining the anicut properly after the water falls down in the river. The earth in rear of the wing-walls has also been washed away, which is now being repaired under a separate estimate.

II. *Nady and Molianur Anicut.*—The body and wing-walls of this anicut across the Pareaur river has been slightly damaged in several places; the surplus calingulah of this anicut is also slightly damaged in its body, and the wing-walls have fallen down during the recent high freshes. This anicut and the surplus calingulah required to be thoroughly repaired at the commencement of next official year. The estimates will have to be framed after a careful examination when the water is fallen down in the river. The earthwork in rear of the wing-walls has also been washed away, which is now being repaired under a separate estimate.

III. *Kangeanur Anicut.*—The body and a portion of this anicut across the Pombay river has been slightly damaged in several places during the recent high freshes. The anicut requires to be thoroughly repaired, which should be done at the commencement of next official year; the estimate should be framed after a careful examination when the water is fallen down in the river. The north bank adjoining the anicut has been breached, which is now being closed under a separate estimate.

No. 831.

FORWARDED to the Superintending Engineer, 5th Division, for information.

(Signed) R. E. NORFOR,

Ex. Engineer, No. 1 Range, South Arcot.

13th December 1871.

No. 150.

FORWARDED to the Collector of South Arcot for information.

(Signed) J. VERTUE, Captain, R.E.,

Acting Superintending Engineer, 5th Division.

* SALEM,

20th December 1871.

*Proceedings of the Madras Government, Public Works Department,
16th February 1872.*

FORWARDED to the Board of Revenue, in continuation of the Collector's letters dated 10th, 12th, and 25th November 1871, Nos. 362, 363, and 378.

(Signed) J. H. GARSTIN,
Collector.

SUBMITTED for the information of Government.

2. A rough estimate of the amount required for repairs should have been given.

TRANSFERRED to the Department Public Works.

(Signed) W. HUDLESTON,
Secretary to Government.

No. 278.

ORDER THEREON, 16th February 1872, No. 448.

IRRIGATION, No. 25.

ORDERED to be recorded.

(True Extract.)

(Signed) J. CARPENDALE, Colonel, R.E.,
Secretary to Government.

Ed. S. T. Augustin.

30
Revenue Department

Mis: No. 463.

Proceedings of the Board of Revenue
dated 1st February 1872.

Read the following

No. 45.

From, The Supervisor in charge of
Villapuram Taluk.

To, The Executive Engineer,
No. 1 Range, South Arcot District.

Sir,

As directed in your memo-
randum no 809 dated the 5th instant,
I humbly beg to inform you that the
following is the report on the dama-
ges done to the Anicuts in this
Taluk.

I. Parany Anicut. The body and
wing walls of this Anicut across the
Pareaur river has been slightly da-
maged in several places during the
recent high freshes. This Anicut re-
quires to be thoroughly repaired, -
which should be carried out at the
commencement of next official year.
The estimate for this work should
be prepared by examining the Anicut
properly

properly after the water falls down in the river. The earth in rear of the wing walls has also been washed away, which is now being repaired under a separate estimate.

II. Nady and elloleannur Ancient.

The body and wing walls of this ancient across the Pareannur river has been slightly damaged in several places; the surplus Calingula of this ancient is also slightly damaged in its body, and the wing walls have fallen down during the recent high freshes. This ancient and the surplus Calingula required to be thoroughly repaired at the commencement of next official year. The estimates will have to be framed after a careful examination when the water is fallen down in the river. The earth work in rear of the wing walls has also been washed away, which is now being repaired under a separate estimate.

Kangeannur

III. Kangeannur Ancient. The body and a portion of this ancient across the Pumbay river has been slightly damaged in several places during the recent high freshes. The ancient requires to be thoroughly repaired, which should be done at the commencement of next official year, the estimate should be framed after a careful examination when the water is fallen down in the river. The north bank adjoining the ancient has been breached which is now being closed under a separate estimate.

Villapuram
8th December 1871

to be remain +
Sd/- M. Manickum Moodalan
Supervisor in charge of
Villapuram Taluk.

No. 831.

Forwarded to the Superintending Engineer, S.E. Division, for information.

Sd/- R.E. Norfor
Sd/- Eng. 1st Range
South Arcot

No. 150.

Forwarded to the Collector of South Arcot for information.
Superintending Engineer's Office,
Kalam 20th December 1871

Sd/- James Vertue Capt. R.E.
Sd/- Asst. Eng. S.E. Div.

True Copy - Forwarded

South Street } 887 J. H. Garstin
Collector's Cutcherry, }
Cuddalore } Collector
85. January 1872 }

A rough estimate of the amount required for repairs should have been given.

True Copy & Extract

J. W. Remington
Cutlery

For the Secretary to Government
Revenue Department

E. L. Buff
Croatian Language

P. W. 1872 Sept.
 Revenue No. 397-608.
 Proceedings of the
 Board of Revenue

Dated 1st February 1872
 Des^d 1
 Received 22.
 Recd 5.
 C. H. v. N. 7/63.

Submitting report
 on damage done
 to Public Works
 in South Arcot by
 late Cyclone.

No. 448-16th Feb 1872
 J. M. S. S. S. S.
 J. M. S. S. S. S.
 2nd Feb 1872. No. 88

Order to be recorded
 No. 448

15

Forwarded to the Board of
Administration of the

Chas

Govt. of 1873 Madras.

PUBLIC WORKS.

Dated

Recd.

Encl.

G. O. 16. Feby 1874 48.

Nos. 277 & 278

Public Works in South Arcot.

Recd. of the Mr. Fisher Esq.
Submitting Report on damage
done to Public Works in
South Arcot by the
Late Cyclone, forwarded