M.R.O. 1—10,006—28-2-50.

(1) Number of pages_____

(2) Date of repair_____

(3) Initials of the Referencer_____

MADRAS RECORD OFFICE

Government of Madras

Public works DEPARTMENT

G.O. No. 2560 Press

~~B.P. No.~~ ~~Mis.~~

326.327

Dated 20-10-1873 ~~195~~.

Not to be folded or roughly handled

Proceedings of the Madras Government, Public Works Department, 20th October 1873.

No. 326. Read the following letter from Colonel E. A. FOORD, R.E., Inspecting Engineer for Civil and Military Buildings, to Colonel G. W. WALKER, R.E., Secretary to Government, Public Works Department, dated Chepauk, 29th September 1873, No. 1,214 :—

I HAVE the honour to forward for the sanction of Government an estimate of Rupees 480 for ceiling the treasury-room attached to the Huzur Cutcherry at Calicut, Malabar District, prepared at the request of the Collector.

1 Specification.
1 Estimate.

2. No ceiling was put when the treasury-room was built in 1832; but the Collector considers that one should be given, as there is only the tiled roof to be got through to enter the building, and there is always a very large sum of money and a great amount of stamp-papers in it.

3. There are no funds at the District Engineer's disposal available for the work.

No. 327. ORDER THEREON, 20th October 1873, No. 2,560.

CIVIL WORKS, No. 20.

SANCTIONED for execution during the current year from the Reserve under Provincial. The specification for the work should have stated the distance apart at which the joists of the ceiling are to be laid. Careless specifications are useless.

(True Extract.)

(Signed) G. W. WALKER, Colonel, R.E.,
Secretary to Government.

To the District Engineer, Malabar.
,, Inspecting Engineer for Buildings.
,, Officiating Controller of Public Works Accounts.
,, Financial Department.
,, Revenue do.

Exd. F. R. Bantleman.

Spares Copies.

Malabar District

Civil Buildings — Abstract Estimate No. of 1873/74 — New Works

Work — Ceiling for the Treasury room attached to Hazoor Office at Calicut in No. II or Calicut Range of Malabar District Vide Requisition from the Collector No. 1027 of 9th May 1873

Probable value of Building Rupees 2500 - - -

Last Repaired in 1872/73 at a cost of Rupees 150 - -

Quantity	Description of Works	Rate	Amount	Total
200	C ft. of Crool or Karamardo wood wrought and put up per ft.	1 4 -	250 3 4	
136 2/3	Do. of 1 inch thick Crool or Karamardo wood planks & iron nails &c. Do.	1 8 -	205 - -	
	Sundries &c. @ about 5 per cent		24 12 8	
	Total Estimate Rupees 480 - -			

No. II or Calicut Range Office
Calicut 3d June 1873

(Signed) J. Laloor Supt. D.P.W.
Incharge Calicut Range

(Signed) H. Bailey Captain
Ag. Distt. Engr. Malabar.

(Signed) A MacGregor
Collector

Ea 3rd Colonel R. E.
Insp. Engineer for Buildings

Specification for ceiling for the Treasury room attached to Hazor Office at Calicut.
Amount of Rupees 480-- --

Joists (21'x6"x4") to be laid transversely over the existing wall plates of the Building, and their ends fixed into the latter, across which (Joists) planks 1 inch thick to be nailed longitudinally with iron nails. All joints of the planks to be made on the joists, the planks to be well planed made smooth and laid close to each other.

At the completion of the Work all rubbish to be removed and the place left clean.

Approved
Supervisor D.P.W.
In charge Calicut Range.

N. Hazor Calicut Range Office
Calicut 3rd June 1873

P. Hanley Captain
A.D. District Engineer, Malabar.

Malabar District.

Executive Engineer's Letter
No 1214 of 23rd May 1873

Rupees 25-0-0 on Collector
Rupees 5346/13

Abstract Estimate for
ceiling of the Treasury Room
attached to Hazor Office
at Calicut.

Amount of Estimate Rupees 480-0-0

Office of the Inspecting Engineer
for Civil and Military Buildings,
Chepauk, 29 September 1873.

No. 1214

From

The INSPECTING ENGINEER
for CIVIL and MILITARY BUILDINGS,

To.

The Secretary to Government
Public Works Department

Sir,

Enclosures 2
1 Specification
1 Estimate.

I have the honor to forward, for the sanction of Government, an Estimate of Rs 1,180, for ceiling the Treasury room attached to the Hoozoor Cutcherry at Calicut, Malabar District, prepared at the request of the Collector.

2. No ceiling was put when the Treasury room was built in 1832, but the Collector considers that one should be given as there is only the tiled roof to be got through to enter the building, and there is always a very large sum of money and a great amount of stamp papers in it.

3.

3. There are no funds at the District Engineer's disposal, available for the work.

I have the honor to be

Sir,

Your Most Obedient Servant

Lt. 3rd Colonel R.E.

Inspecting Engineer for

Civil & Military Buildings

PW. 1873 Deptt.
No. 5346

No. 1214

From

The Inspecting Engineer
for Buildings,

To

The Secretary to
Government P.W.D.

Encl-2

Dated 29 } September 1873.
Recd. 30 }

Forwards for sanction an estimate of Rs. 480 for ceiling the Treasury room attached to the Hospital Cutcherry at Calicut

Duplicate Order

Enclosed Abstract Estimate for Rs. 2560

Current year from the Executive for the Northern Division of Malabar and Canara

Ceiling are to be done

Zillah Court Clerk's Office

Sub Court Clerk's Office

Tahsildar's Office

Police Station

Dispensary

Civil Engineer

Dispatched 28/10/73

No. 326-2

3. There are no funds at the District

Engineer's

No. 5346

Govt. of {1873} Madras.

PUBLIC WORKS.

To The District Engr
Malabar

Dated

Recd. Encl. 2

G. O. 20 Aug 1873. 25 60.

25

Nos. 3261, 327

Hosgoor Cutcherry at

Calicut. Rek. for
Ceiling the Treasury
room attached to the
Cutcherry. Sanctioned
with remarks.