

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE**Government of Madras***Public works* DEPARTMENT

G.O. No.	441	Press
B.P. No.		Mis-
15.146		
Dated	4-3	1843.

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
7th March 1873.*

No. 175. Read the following letter from the Officiating District Engineer, South Arcot, to the Secretary to Government, Public Works Department, dated Cuddalore, 17th February 1873, No. 49 —

I HAVE the honour to report, for the information of Government, that the heavy rain experienced throughout this district, between the 2nd and 6th instant, has caused some damage to works in the Cuddalore and Tindevanum Range.

2. In the Cuddalore Range the floods in the Trivady Anicut; this caused a high, rising one foot above the wing-walls of the Guddellum were unusually breach in the southern embankment adjoining the anicut, carrying away the up and down stream wing-walls on the south, the anicut has sustained no further damage; a ring bund is being constructed across the breach, and the damaged wing-walls will be shortly reconstructed.

3. Captain Graham reports the destruction of the earthwork repairs recently completed on the roads Tindivanum to Merkanum, to Gingee to Pondicherry, by Killianoor, and Gingee to Chaitput. Application will be made to the Local Fund Board for funds at an early date as possible; the current year's reserve, I believe, is already fully appropriated.

No. 176. ORDER THEREON, 7th March 1873, No. 741.

ESTABLISHMENT, No. 23.

ORDERED to be recorded.

(True Extract.)

(Signed) G. W. WALKER, Colonel, R.E.,
Secretary to Government.

Exd. S. T. Austin.

No. 49 Dist. Engrs Office S. Arcot
Cuddalore 17th February 1873.

From, The Offg. District Engineer,
South Arcot,

To, The Secretary to Government,
D. P. W.

Sir, I have the honor to report,
for the information of Government, that
the heavy rain experienced throughout
this District between the 2nd and
6th Instant has caused some da-
mage to works in the Cuddalore
and Tiruvannam Ranges.

2 In the Cuddalore Range
the floods in the Cuddalore were
unusually high, rising one foot above
the wing walls of the Tiruvannam
Aqueduct, this caused a breach in the

The Southern embankment, joining the Ancient, carrying away the up and down stream wing walls on the South, the Ancient has sustained no further damage; a wing bend is being constructed across the breach, and the damaged wing walls will be shortly reconstructed.

3 Captain Graham reports the destruction of the Earthwork repairs recently completed on the roads Tindivanam to Mar. Mannar, to Quigee to Pondicherry. by Killiancor, and Quigee to Chait. sub. application will be made to the Local Fund Board for funds at an early date as possible. the current year's Reserve, the. here, is already fully appropriated. I

SD I have the honor to be
Yours Most Obedt. Servant.
M. W. B.
Offg. Dist. Engineer.

Tom Wright for Dr.
A-2 State Street

Rec'd 11/3/73

8:175.76.
6-254173

Wm

Produced to be recorded.
No 741

Reporting damages caused
to certain works in the C&D
docks and vicinities
Rangers by the heavy
fairs between the 19th
to 26th January 1873

No 419

Rec'd 19 February 1873

Wm
Rec'd 19 February 1873

Rec'd 19 February 1873

Rec'd on 19th

rec'd on 19th

L.P. 1132
Govt. of 1873
PUBLIC WORK

T. Holby Cng for
Friga

Dated
Recd.

7 March 73

Nos. 175117
Repair of the

Caused to work
works in the
low & Liddeman
Vangers, South A
St., by heavy
work.