

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public works DEPARTMENT

G.O. No.	122	Press
B.P. No.		Mis.
241-242		
Dated	17-1-1874	-195

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
17th January 1874.*

No. 241. Read the following letter from Major R. F. OAKES, R.E., District Engineer, Tanjore, to Colonel G. W. WALKER, R.E., Secretary to Government, Public Works Department, dated Tanjore; 16th August 1873, No. 513:—

... WITH reference to G. O., No. 1,979, dated 9th instant, I have the honour to observe that Government appear to have overlooked the suggestion that of the 353 cubic yards of stone available for the protective works at Tranquebar, 333 cubic yards should be placed along the face of the bastion, as the extension of the new groyne would not sufficiently protect this face, and the groyne itself would be taken in reverse and be destroyed if this face were undermined and fell. The extension of the groyne would protect the open beach to its north to a greater extent than the beach at present protected.

No. 242. ORDER THEREON, 17th January 1874, No. 122.

CIVIL WORKS, No. 13.

ORDERED to be recorded.

2. The District Engineer will now report, without delay, whether, as directed in G. O., No. 1,979, of 9th August, the estimate of Rupees 3,150 then sanctioned was carried out before the monsoon, as well as the work for which Rupees 2,350 were promised to be allotted in G. O., No. 1,560, of 14th June. He will also report, as formerly instructed, on the effects of what has been done.

(True Extract.)

Colonel, R.E.,
Secretary to Government.

To the District Engineer, Tanjore.

.. Inspecting Engineer for Ports and Harbours.

Exd. S. T. Austin.
Spare Copies

No. 513-

District Engineer's Office
Tanjore 18 August 1873

From
Major R. F. Coates R.E.
District Engineer

To
Colonel G. W. Walker R.E.
Secretary to Government
P. W. Department

Sir,

With reference to G. O. No. 1979 dated 9th Instant I have the honor to observe that Government appear to have overlooked the suggestion that of the 358 Cubic yards of stone available for the protective works at iranguebar, 333 Cubic yards should be placed along the face of the Bastion, as the extension of the new Groyne would not sufficiently protect this face and the Groyne itself would be taken in reverse and be destroyed if this face were undermined and fell. The extension of the Groyne would protect the open beach to its North to a greater extent than the ^{beach} at present protected

protected...

I have the honor to be
Sir
Your most obedient servant
A. G. A. G. R.
District Engineer

[Faint, mostly illegible handwritten text in the left margin]

States that, on 20th May 1979
dated 9th May, 1979, I have
instructed the Engineer
that at the 358-358 it since
is found for the Engineer
for the protection of the
face of the Kings Bastion.
Done 17th May 1979

The District Engineer
The Secretary to
Government
P. M. D.
Received: 18th
August 1979
No. 513.

Received 18th August 1979
No. 513.

No. 122 : 5
Public Works Dept

Proceedings of the Madras Government.

Read the following letter from
the District Engineer
Tanjore

N. R. No. 513 d/ 18 Augt/79

Order No. 513 d/

[Handwritten signature]

[Handwritten initials]

Ordered to be recorded
The District Engineer
without delay,
whether, as directed in
P. O. No. 1979 of 9th
August, the Estimate
of Rs 3150 then sanctioned
was carried out before
the provision, as well as
the work for which Rs 2350

were promised to be allo-
cated by 1560 of
14 June. He will also
report, as formerly in-
structed, on the effects
of what has been done
CSM

122
To The D^r Insp. Tanjong
" Insp. Insp. for P. C. Insp.

W-3-dep. only to D^r Insp. Tanjong 27/1/74
P-C - to be 27/1/74

Ep 4569
Govt. of 1874 Madras.
PUBLIC WORKS.

To The District Engineer
Tanjore

Dated

Recd.

Encl.

G. O., 17th Decr., No. 122.

Nos. 141 & 142

Tanjorehar payees. Passing
orders in letter from the
District Engineer, reporting
in connection with the
protective works at
Tanjorehar.