

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	2288	Press
B.P. No.		Mis. →
Dated	18-8-	1874 195

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
18th August 1874.*

No. 367. Read the following letter from Colonel F. J. MOBERLY, R.E., District Engineer, Chingleput, to Lieutenant-Colonel J. MULLINS, R.E., Chief Engineer for Irrigation, dated Guindy, 22nd July 1874, No. 1,356:—

I HAVE the honor to enclose an estimate for repairing Serusari large tank in Chingleput Taluq for the sanction of Government under revised Chapter IV., paragraph 9, clause II., its amount being above that of the average revenue of the tank in question.

No. 368. ORDER THEREON, 18th August 1874, No. 2,288.

IRRIGATION, No. 03.

THE estimate of Rupees 912 for the repair of the Serusari large tank in the Chingleput District is sanctioned.

2. It is observed that the average revenue is Rupees 555 against an ayacut assessment of Rupees 717, and that the estimate provides for ordinary repairs, of which none appear to have been carried out for 20 years or more. The tank did not breach in 1872, when the rainfall in May was extraordinarily heavy, and it is concluded, therefore, by the local officers that the present escape weir, which has an effective length of about 29½ feet, is sufficient. It will nevertheless be advisable, as early as may be convenient, to compare the drainage basin of the tank and the maximum flood discharge therefrom with the means of disposing of surplus water. The length of the escape seems to be small when the area of cultivation is considered, which is a rough index to the area of the catchment basin.

(True Extract.)

Lieut.-Colonel, R.E.,
Joint-Secretary to Government.

To the District Engineer, Chingleput.
„ Chief Engineer for Irrigation.
„ Officiating Controller of Public Works Accounts,

Exd. S. T. Austin,
Spare Copy.

Memo

Requests to return the estimate
for the repair of Semsari Tank sanctioned in G.O.
2288 dated 18th August 1914.

+ 2 Estimates for Madras Land & Lark.

14/10/14
Chief District Officer
by order 13 October 1914

Chief District Officer

The Chief Assistant and Registrar
to the Secretary to Govt P.W.D.

P. W. 1874 Dept.
 No. 4904
 THE DISTRICT ENGINEER
 CHONGLEPUT

To THE Chief Engineer
 Brigade

Dated 22nd Sep. 1874
 Received 23rd August
 Recd. 5th August
 1874 No. 2582

Enclosure for estimate
 in estimate for
 repairing tank in
 large tank

G.O. No. 2288-18-874

No 364

Public Works Department
 Proceedings of the Madras Govt.
 2288 Read the following
 The Ch. Engineer
 Chongleput (H.O. No. 1356 dated
 22nd July 1874)

and 12 will
 be in order

and 12 will
 be in order
 21/7

The estimate of
 Rupees 912 for the
 repair of the Senisari
 large tank in the
 Chongleput District is
 sanctioned.

2nd It is observed
 that the average re-
 venue is Rupees 556
 against an average
 expenditure of Rupees
 717 and that the
 estimate provides for
 ordinary repairs of
 which none appear
 to have been carried
 out for 20 years or
 more. The tank did
 not break in 1872,
 when

4901

Govt. of 1874 Madras.

PUBLIC WORKS.

To



The Dist. Ingr.
Chingleput

Dated

Recd.

Encl. 1

G. O. 18 Aug 1874, No. 2228

Nos. 367-368.

Serusari Tank

Chingleput District

The Estimate of Rs 9/12
for the repair of the Tank
sanctioned with remarks.