

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works

DEPARTMENT

G.O. No.	3137	Press
B.P. No.		Mis. →
Dated	4-11	1874
		195

Not to be folded or roughly handled

9.

*Proceedings of the Madras Government, Public Works Department,
4th November 1874.*

No. 66. Read the following endorsement of the Chief Engineer for Irrigation,
dated Palamcottah, 6th October 1874, No. 799:—

From W. M. MONTSERRAT, Esq., Assistant Engineer in charge of Madanapally
Range, to Colonel A. S. MOBERLY, R.E., District Engineer, Cuddapah,
dated Madanapally, 25th September 1874, No. 1,141.

I HAVE the honor to report that the undermentioned Government tanks and
road tunnels in the Madanapally Taluq have been damaged by the late heavy
rains:—

In *Guttoo* there has been three Government tanks, by name—

1. Obulnayany tank bund breached.
2. Papanah tank bund breached.
3. Mallinayany tank bund breached.

In *Cottacottah*—

1. Bungaroonayany tank north calingulah apron.
2. Dasavandam tank, close to the Cothacottah large tank, breached.
Rungasamoodrum large tank, part of body wall of calingulah and apron
washed away.

Sampathycottah Sampathycherloo breached.

Pedda Tippiasamoodrum Paracola Calvah temporary bund carried away.

Thatimakala Calvah anicut breached.

Davalacherloo Theroomaladavara tank, rough stone calingulah breached.

Coosoovaripally Byannah tank, close to Moodivade, slight breach to
calingulah apron.

Chinna Tippiasamoodrum large tank, the only injury to this tank
calingulah is the plastering of top of body wall washed away.

2. The damages have been ordered to be repaired at once to the extent of
Rupees 50; ring-bunds have been placed round most of the breaches by the villagers,
the rest by the department. The Reddies of Guttoo refused any help for making
ring-bunds to the breaches of Obulnayany and Papanayany tanks, although the
Tahsildar was on the spot; emergent estimates will be submitted for all these
works without delay.

3. No reports have been received from the sub-division, or Voilpaul Taluq,
up to date with respect to damage of any irrigation works, etc.

No. 1,236.

COMMUNICATED to the Chief Engineer for Irrigation for information.

(Signed) A. S. MOBERLY, Colonel, R.E.,
District Engineer, Cuddapah.

29th September 1874.

SUBMITTED for the information of Government.

(Signed) JOHN MULLINS, Lieut.-Colonel, R.E.,
Chief Engineer for Irrigation.

12-3

Proceedings of the Madras Government, Public Works Department,
4th November 1874.

No. 67.

ORDER THEREON, 4th November 1874, No. 3,137.

IRRIGATION, No. 5.

ORDERED to be recorded.

(True Extract.)

(Signed) G. W. WALKER, Colonel, R.E.,
Secretary to Government.

No. 1141

Madanapally Range Office
25th September 1874

From The Officer in Charge of
Madanapally Range

To

The District Engineer of
Madanapally

Sir,

I have the honor to report
that the undermentioned Government
Tanks and Road Tunnels in the
Madanapally Taluk have been
damaged by the late heavy rains.

In Guttos there has been
three Government Tanks by name—

1. Obulnayany Tank bund breached
2. Papanah Tank — do — do —
3. Mallinayany Tank do do —

In Kottacottah—

1. Bunguroonayany Tank North
falingulah Apron—
2. Dasavandam Tank close to
the Kottacottah large tank breached.

Pungasamoodram Large Tank:
part of body wall of falingulah and
apron washed away.

Sampathycottah Sampathy Cheroo
breached.
Padda Sippasamoodram Paracala Calvath.
Temporary bund. Carried away.

Thaimakala Talva, ancient
breached.
Davalacherro Theroomala dam,
Lank, Rough stone talingulab
breached.

Loosovaripally Dyanna
Lank close to Moodivade.
Slight breach to talingulab
apron.

Chinna Thippasamoodram large
tank, the only injury to this tank
talingulab is the plastering
of top of body wall washed away.

The damages have been
ordered to be repaired at once
to the extent of Rs 50-- Ring bands
have been placed round most of
the breaches by the villagers, the rest
by the Department. The Poddier of
Guttoo refused any help for making
ring bands to the breaches of Obla:
Mayany and Papanayany Tanks
although the Tahsildar was on the
spot; Emergent Estimates will be
submitted for all these works without
delay.

No reports have been received

from the Sub Division of Vailpand
Lalug up to date with respect
to damage of any irrigation works &c.

I have &c.

Signed/ W. M. Montserrat
Assistant Engineer

Tras Extract
No 1235 of 29th September 1874.
Communicated to the Chief Engineer
for Irrigation for information.

Col: R. C.
District Engineer
Cuddalore

P. W. 1874 Sept.
No. 6470

From

The Chief Engr.
for Irrigation

Dated 6 Oct 1874.
Recd. 15 - - 1874.

No. 799

Submitting a letter
from the Dist. Engineer,
Buddapah, reporting
the damage to certain
works in Madanapally
Range.

El. No. 3137. 4-11-74.

66-67.

Recd to Oct 15 Oct 174

Submitted
6 Oct 1874

Submitting Government

No. 1236
From El. No. 1835.
The District Engineer
Buddapah
for submission
Madanapally

Dated 29th October
Recd 15 Oct.

Communicated copy
of letter No. 1141 of 23rd 74
from the Officer in Charge
Madanapally Range
to District Engineer
regarding the damage
of certain works in
Madanapally Range
for information
with endorsement.

3137

Submitted
6 Oct 1874

Submitting Government

Recd 21/10/74
3137

6470
Govt. of Madras.
PUBLIC WORKS.

To

Dated

By

For

G. L. Iyer 3137

No. 66-67.

Damages to certain
Tanks & Road Tunnels
in the Madanapalle
Taluk. Cuddalore Dist.

Endorsement from
the Chief Engr. for
submitting a report from
the S.D.O. regarding
the damages recorded
done by the late heavy rains.

referred