

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	2539	Press
B.P. No.		-Mis.
Dated	8-9-	6874
		-195-

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
8th September 1874.*

Read the following papers :—

No. 148. From Major J. N. HUNTER, R.E., District Engineer, Salem, to Lieutenant-Colonel J. MULLINS, R.E., Chief Engineer for Irrigation, dated Camp at Tripatore, 7th August 1874, No. 91.

WITH reference to your memorandum, No. 267 A., dated 4th April 1874, returning with remarks an estimate for repairing the Annasagaram Hissa Tank, I have the honor to submit an estimate, with plans, etc., amounting to Rs. 3,640, revised in accordance with the instructions contained in your memorandum under reply.

2 Revised estimates.
1 Do. section.
1 Do. plan.
1 Do. irrigation statement.
Remarks by the District Engineer.

2. The statement of particulars accompanying the estimate will give, I think, all the information you require.

Paragraph 3.—The maximum flood discharge calculated on the formula circulated with your No. 61, dated 2nd May 1874, agrees with that given in paragraph 3 of your memorandum.

3. Paragraph 5.—The bund is to be raised to a minimum height of $4\frac{1}{2}$ feet, and it is calculated that with $2\frac{1}{2}$ feet going over the weir the additional length required will be 119 feet nearly.

4. Paragraph 6.—The instructions in paragraph 6 have been noted and will be carried out.

5. Paragraph 7.—In paragraph 7 of your memorandum, notice is taken of the contents of the tank as compared with the irrigation under it.

6. The entry in the irrigation statement which accompanied the first estimate was erroneous and has now been corrected; the storage will, it is thought, suffice for the acreage.

7. I trust now that you will be able to sanction the revised estimate, as I am anxious, if possible, to get the work done this year.

No. 589-B.

No. 148A. *Note by the Chief Engineer for Irrigation.*

An estimate, amounting to Rupees 2,090, for the repair of the Annasagaram Hissa Tank in the Salem District was

* District Engineer's No. 180, 30th March.
† No. 267-A., 4th April.

received* at the end of March last, and was returned† for revision with instructions.

As now re-submitted it provides for—

	RS.
Repairs	2,300
An extended and improved escape under Minor New Works	1,340
	3,640

The tank will with the work now contemplated be rendered safe and efficient and it is supposed that some increase* of cultivation and of revenue will also be obtained, though this has not affected the question of the way in which the tank should be dealt with.

* 80 Acres, 400 Rupees.

23

Proceedings of the Madras Government, Public Works Department,
8th September 1874.

The ayacut area is	...	...	...	...	Acres	420
Do. assessment	...	...	...	...	Rupees	2,125
Average revenue...	...	...	...	...	"	1,832
Expenditure on repairs in the last five years (1869-70)	...	...	...	...	Rs.	631

2. The circumstances of the tank have been considered, and satisfactory results may be anticipated from the expenditure proposed.

3. The District Engineer has been authorized to go on with the repairs and to prepare materials for the surplus weir.

Ootacamund,
18th August 1874.

(Signed) JOHN MULLINS, Lieut.-Colonel, R.E.,
Chief Engineer for Irrigation.

No 149.

ORDER THEREON, 8th September 1874, No. 2,539.

IRRIGATION, No. 22.

THE following estimates are sanctioned for the repair and improvement of the Annasagaram Hissa Tank in the Salem District:—

Repairs	...	...	...	...	...	Rs.
Minor New Work—	...	...	...	...	...	2,300
A surplus weir 242 feet long	...	...	...	...	...	1,340

(True Extract.)

Lieut.-Colonel, R.E.,

Joint Secretary to Government.

To the District Engineer, Salem.
" Chief Engineer for Irrigation.
" Officiating Controller of Public Works Accounts.

Exd. E. C. Shunker.
Spare Copies

589B.
Note by the Chief Engineer for Irrigation
An estimate amounting to Rupees
2,090 for the repair of the Annasa-
garam Hissa Tank in the Salem Dis-

MEMORANDUM.

REQUESTED for reference the under-mentioned papers:—

Letter No. 83-724 July/74 with 1 Encl from the S.B. Salem
referred to in S.B. No. 2394-24 August/74.

Letter No. 1447 77th August/74 with 6 Encl.
Letter No. 2674 1st September/74
Letter No. 2674 30 September/74
Circular No. 1007 Oct/73.
Letter No. 1007 1st September/74
Letter No. 1007 1st September/74

sent with the Ch Engr's
printed with
both referred to
in S.B. No. 2539. 8 Sept/74

Dr. H. Mullins

Head Clerk.

OFFICE OF THE CHIEF ENGINEER
FOR IRRIGATION,

6-10-1874.

To

The Registrar of the *proceed.*

affected the question
in which the tank should be dealt
with

The ayacut area is acres 420.
— assessment Rupees 2,125
— average revenue — 1,832

Expenditure on repairs in the last
5 years (1869-70) Rupees 631.

2. *The circumstances of the tank*
have

Proceedings of the Madras Government, Public Works Department,
8th September 1874.

The ayacut area is	...	...	...	...	...	Acres	420
Do. assessment	...	...	...	...	...	Rupees	2,125
Average revenue...	...	...	...	...	...	"	1,832
Expenditure on repairs in the last five years (1869-70)	...	...	...	...	...	Rs.	631
2. The circumstances of the tank have been considered, and satisfactory							

... for Irrigation.
Officiating Controller of Public Works Accounts.

Ed. E. C. Shunker.
Spate Copies

N. 589B.
Note by the Chief Engineer for Irrigation

An estimate amounting to Rupees 2,090 for the repair of the Annasa-garam High Tank in the Salem District Engineers' tract was received at the end of March last, and was returned # 267 to 4 April for revision with instructions to now resubmitted it provides for Rupees 2,300

Repairs
An extended & improved escape under minor new works ————— 1,340
————— 3,640.

* 80 acres
400 Rupees.

The tank will with the work now contemplated be rendered safe and efficient and it is supposed that some increase of cultivation and of revenue will also be obtained, though this has not affected the question of the way in which the tank should be dealt with

The ayacut area is acres 420.
— assessment Rupees 2,125
— average revenue — 1,832
Expenditure on repairs in the last 5 years (1869-70) Rupees 631.
2. The circumstances of the tank have

have been considered and satisfactory results may be anticipated from the expenditure proposed.

3. The District Engineer has been authorized to go on with the repairs and to prepare materials for the surplus work.

Ootacamund 18th August 1874
 J. H. Mullins Esq. D. H. H.
 Chief Engineer for Irrigation.

To The Secretary to Govt. P.W.D.

21/23 April 11.8
 8788 10/2

unart

the chief of the
 the general of

the chief of the
 the general of

7. 2. 1. 2. 3.

the chief of the
 the general of

the chief of the
 the general of

the chief of the
 the general of

the chief of the
 the general of

2300

340

P. W. 1874 Sept.
No: 5373

From

The Chief Engr.
for Irrigation

Dated 18 August
Reel 26-1874

+ 7 Enclod. 7

Note on the
revised plans and
estimates for the repairs
of the Anasagaram
Hissa tank in the
Salem District -

G.O. No 2539-8-9-74-

No 1480A

Public Works Department
Proceedings of the Madras Government
Read the following
From the S. Engr. (Tel. No 91 dated
Chief Engr. for Salem (Tel. No 1874)
1874 dated 18
Aug 1874)

2539

The following estimates are sanctioned
for the repair and improvement of the Anasagaram Hissa
Tank in the Salem District

Was Col. Mullins deft
Circular has been completed
How are the tanks above
if there are any
State works in the
Salem District

Repairs
Rupees 2,300

Minor new work
A surplus weir
242 feet long

1340

19/8/74

Amr

To The S. Engr. ✓
--- Chief Engr. for Salem ✓
--- Controller of Works ✓
S. Engr. dated 19/9/74.
27-74

5373 ✓

Govt. of Madras.

PUBLIC WORKS.



The District
Salem

dated

Recd.

Encl. 7

G. O. 8 Sept 1914, No. 2539

For 148-149

Annasagarani Area
tank - Salem Dt.

Estimates for the re-
pair & improvement
of the tank, sanctioned.