

(1) Number of pages_____

(2) Date of repair_____

(3) Initials of the Referencer_____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	1076	Press	<i>Original</i>
B.P.—No.		Misr	
Dated	27. 4.	195	78 74

Not to be folded or roughly handled

17371
Govt. of 1874 Madras.
PUBLIC WORKS.

To

The Inspe. Engr
for Buildgs.

Dated

Recd.

Encl.

G. O. 27th April 1874, No. 1076

Nos. 342-343.

St. Paul's Church at
Mangalore - South Canara
District - Letter from the
Dy. Engr. to the Inspe. Engr
for Buildings: reporting
on the state of the roof
of the Church, recorded
with remarks -

Proceedings of the Madras Government, Public Works Department,
27th April 1874.

No. 342. Read the following endorsement of the Inspecting Engineer for Buildings, dated Chepauk, 23rd March 1874, No. 474 :—

From A. C. LAWFORD, Esq., Officiating District Engineer, South Canara, to Colonel E. A. FOORD, R.E., Inspecting Engineer for Civil and Military Buildings, dated Camp at Udipy, 16th March 1874, No. 153.

I HAVE the honour to report, for your information, that the roof of St. Paul's Church at Mangalore has been found by the Range Officer to be in a state of decay. The trusses, which are not correct in principle and are really no trusses at all, throw the whole weight on the tie beams, which are unequal to the burden. The principal rafters are too slight and the reepers are much decayed.

2. An estimate will be submitted with as little delay as possible for the thorough repairs, when a drawing of the existing trusses will accompany.

FORWARDED to the Chief Engineer, Department Public Works, for information.

(Signed) E. A. FOORD, Colonel, R.E.,
Inspecting Engineer for Buildings.

No. 343. ORDER THEREON, 27th April 1874, No. 1,076.

CIVIL WORKS, No. 40.

ORDERED to be recorded: The plan and estimate for a new roof for the Mangalore Church prepared on correct principles and accompanied by full report will be awaited. The Inspecting Engineer for Buildings will inspect the building at the same time that he performs the duty assigned to him in G. O., No. 138, of 17th February 1874.

(True Extract.)

Colonel, R.E.,
Secretary to Government,

To the Inspecting Engineer for Buildings.
.. District Engineer, South Canara;
.. Ecclesiastical Department.

Exd. S. T. Austin.
Spare Copies

N^o 153 District Engineer's Office
South Canara
Camp Udipi 16 March 1871.
From

The Off^r District Engineer
South Canara

To
The Inspecting Engineer
for Civil & Military Buildings

Sir
I have the honor to report
for your information that the roof
of St. Paul's Church at Mangalore
has been found by the Range Officer
to be in a state of decay. The Trusses
which are not correct in principle, and
are really no trusses at all, throw the
whole weight on the tie beams which are
unequal to the burden. The principal
rafters are too slight and the supports
are much decayed.

2. An Estimate will be submitted
with

with as little delay as possible for
the thorough repairs, when per drawing
of the existing trusses will accompany.

Desd. Mangalore. I have the honor Ven.

17 March 1874. Signed / A. C. Law, Jr.

Offg District Engineer
South Canara.

N 474

Forwarded to the Chief
Engineer D. P. W. for information.

Office of the District Engineer
for the District of South Canara
Chapauk R 23rd March 1874

EA and Col R. E.
Inspecting Engineer
for Buildings

To
Colonel G. W. Walker R. E.
Chief Engineer
P. W. Department

Pub: Bonds 1874 22

31

1076

Can B

No: 1737

Thom

1874

for 1874

Chief Engineer

1874

March 1874

1874

1874

1874

1874

1874

1874

342-343

in 28 March 1874

with an order

ordered to be recorded. The plan

is to make for a new road for the

managers of the road and to make

the road and to make the road

the road and to make the road

the road and to make the road

the road and to make the road

the road and to make the road

the road and to make the road

the road and to make the road

the road and to make the road

the road and to make the road

the road and to make the road