

(1) Number of pages_____

(2) Date of repair_____

(3) Initials of the Referencer_____

MADRAS RECORD OFFICE

Government of Madras

Public Works

DEPARTMENT

G.O. No.	1357	Press	<i>Original</i>
B.P. No.		Mis.	
Dated	12-5-	4875	195-

Not to be folded or roughly handled

4

12

*Proceedings of the Madras Government, Public Works Department,
12th May 1875.*

Read the following:—

No. 426.

No. 279. *Note by the Chief Engineer for Irrigation.*

THE following estimate has been
submitted by the District Engineer,
Kurnool:—

Repairing Putlur tank	...	...	...	...	...	Rupees	955
Ayacut area	...	...	...	...	...	Acres	51 93
" assessment	...	...	...	...	...	Rupees	130
Average revenue	...	...	...	...	...	"	104
Highest "	...	...	...	...	...	"	126

With the exception of work already done under this estimate, no repairs have been executed of late years.

2. There has been a good deal of correspondence about this tank, which was not properly dealt with in the first instance. Even now some of the information which should always be attached to such estimates is wanting, but the work remaining to be done is necessary, and the estimate may therefore be sanctioned.

Ootacamund, (Signed) JOHN MULLINS, Lieut-Colonel, R E,
29th April 1875. *Chief Engineer for Irrigation.*

No. 280. ORDER THEREON, 12th May 1875, No. 1,359.

IRRIGATION, No. 29.

THE following estimate is sanctioned:—

Repairing the Putlur Tank, Kurnool District Rs 955

2. The correspondence shows that the requirements of the tank were not properly ascertained and estimated for in the first instance, or its circumstances clearly explained. It is observed that later estimates have been better prepared.

(True Extract)

Major, R E,
Officiating Joint Secretary to Government.

To the District Engineer, Kurnool
" Chief Engineer for Irrigation.
" Controller of Public Works Accounts.

Exd W. J. Lewis.
Spare Copies

Note by the Chief Engineer for Irrigation

No. 2. 9th July 1875.

The following estimate has been submitted by the District Engineer, Kumool

Repairing Putter Tank Pupos 955

Approx Area acres 51.93

Approx Pupos 130

Average Revenue — 104

Highland do — 120

With the exception of work already done under this estimate, no repairs have been executed of late years.

There has been a good deal of Correspondence about this tank, which was not properly dealt with in the first instance. Even now some of the information which should always be attached to such estimates, is wanting, but the work remaining to be done is necessary and the estimate may therefore be sanctioned.

Lt Col. R.C.

Volacand

29th April 1875

Chief Eng^r for Irrigaⁿ

To The Secretary to Government
P.W.D.

Proceedings of the Madras Government
Read the following

Gr. On: 1359 d/ 12th May/75-

The following estimate is sanctioned

Repairing the Putter's Tomb
Kinnool District Rs 955

2 The correspondence shows that the requirements of the tank were not properly ascertained and estimated for in the first instance, or its circumstances clearly explained. It is observed that later estimates have been better prepared.

H. Kinnool
Hughes & Co. White Plains

by 30/4/55

000-1875 deat-
No 426 No 2959

From
The Clothing
Department

To the Secretary &
Government
Jan 29

Date 29th Sept 1895
 High Wycombe
 Enclosure 5

note on the left hand
page regarding the
Dr. H. T. C. H. H. H. H.
on the same page
Dr. H. T. C. H. H. H. H.

12-5/35

C-4-5-75

2679

Handwritten notes at top left, including "279-280" and "District of Madras".

2959

Govt. of Madras

PUBLIC WORKS.

To Mr. D. G. Kurnool

Date

By

For

12 May 1879 No. 279

Nos. 279-280

Puttur Tank - Kurnool

District - The estimate

of Rs. 95.5 for repairing

the ——— sanctioned

with remarks.

Handwritten notes at bottom, including "D. G. Kurnool" and "12 May 1879".