

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works

DEPARTMENT

G.O. No.	1509	Press
B.P. No.		Mis.
Dated	31-5-1955	

Original

Not to be folded or roughly handled

Read the following papers :—

No. 593. Endorsement of the Ecclesiastical Department, dated 19th April 1875.
From the Venerable C. R. DRURY, M.A., Commissary and Acting Archdeacon of Madras, to the Hon. W. HUDLESTON, Chief Secretary to Government, Fort St. George, dated Ootacamund, 19th April 1875.

THE Madras Government in Proceedings, Ecclesiastical Department, dated 14th July 1874, were pleased to order a bell to be supplied to the church at Yercaud in lieu of the bell which they then had, and which was cracked and useless.

2. I have just received a letter from the Church Committee of Yercaud stating that they have received the new bell ordered by Government, but "that it has a very dull sound, and cannot be heard in several places about the station no great distance off."

3. I gather from this that the bell in question is either too small, or is cracked, and, therefore, comparatively useless.

4. I am requested by the Church Committee, under the circumstances, to ask the Government to order another bell to be supplied to Yercaud Church.

FORWARDED to the Public Works Department for disposal.

(Signed) W. HUDLESTON,
Chief Secretary.

No. 174.

FORWARDED to the District Engineer, Salem, for report.

FORT ST. GEORGE, (Signed) G. W. WALKER, Colonel, R.E.,
26th April 1875. *Chief Engineer, D.P.W.*

No. 593-A. From Major J. N. HUNTER, R.E., District Engineer, Salem, to Colonel G. W. WALKER, R.E., Chief Engineer, Public Works Department, dated Camp at Oosoor, 4th May 1875, No. 21.

WITH reference to your endorsement, No. 174, dated 26th April 1875, I have the honor to report that the bell has no crack or flaw, but is too small for the purpose, as it certainly cannot be heard at houses only a very short distance from the church.

2. I beg to recommend that another bell be supplied.

No. 594. ORDER THEREON, 31st May 1875, No. 1,509.

CIVIL WORKS, No. 40.

As the bell supplied to the church at Yercaud is too small, the District

Proceedings of the Madras Government, Public Works Department,
31st May 1875.

Engineer, Presidency, will arrange for exchanging it for one of larger dimensions. The size of the new bell will be settled in communication with the Venerable the Archdeacon.

(True Extract.)

Major, R.E.,
Offg. Joint Secretary to Government.

To the District Engineer, Presidency.
" " Salem.
" Controller of Public Works Accounts.

N. 21

District Engineers Office, Salem.
Camp Ooroor, 4th May 1875.

From

The District Engineer,
Salem.

To

The Chief Engineer,
D. P. W.

Sir,

Enclosure 1
original En-
dorsement on
letter from
Arch Deacon
(returns)

With reference to your Endorsement No. 174, dated 26th April 1875, I have the honor to report that the bell has no crack or flaw, but is too small for the purpose, as it certainly cannot be heard at houses only a very short distance from the Church.

I beg to recommend that another bell be supplied.

I have the honor to be,

Sir,

Your Most Obedient Servant,

J. W. Steere Major, R.E.,

District Engineer, Salem.

Encl.

16
 Ootacamund.
 14th April 1873

To
 The Hon^{ble} W. Huddleston,
 Chief Secretary to Govt
 Fort St. George.

Dear Sir

The Madras Govt in its preceding
 Ecclesiastical Circular dated 14th July 1841
 were pleased to order a bell to be sup-
 plied to the Church at Yercaud in
 lieu of the bell which they then had,
 and which was cracked & useless.

I have just received a letter from
 the Church Committee of Yercaud
 stating that they have received the
 new Bell ordered by Govt but that it
 was a very dull sound, and cannot
 be heard in several places about the
 station no great distance off.

I gather from this, that the Bell
 in question, is rather too small &
 is cracked, and therefore compar-
 atively useless.

I am requested by the Church
 Committee, under the Circumstances
 to ask the Govt to order another Bell
 to be supplied to Yercaud Church.

I am
 Dear Sir
 Your Obedient Servant
 C. R. Dwyer
 Com. & Acting Archdeacon

1873 Aug 4/74 No 706-106 and 107 S. W. 1875 Sept 11.
 1873 Aug 11 " " 235

From No: 2933

The District Engineer,
 Ootacam.

To
 The Chief Engineer,
 Ootacam.

Dated 4th
 Dec: 73
 No: 2933

Reports that the
 Bell at Yercaud
 does not crack, but
 is too small for
 the purpose. Comm.
 Bureau that another
 Bell be supplied.

Re: 2933/75 No 2933/75
 Date: 17/11/75 No 2933/75
 and 30/11/75 No 2933/75

Forwarded to the Public Works
Department for disposal.

L. H. H. H.
Chief Secretary

to the Public Works
19th April 1905. Department

which that the
now will appear to
the Librarian of the
has not been
concluded that no
several officers are
the station, and others
things that another
will be supplied.

10/102

20th 1905
Recd. 19th April 1905

from the Ag. Secretary
of the

14th Aug 1894. Dec 12-13

Lucie (1895) / Dec 12

(1895)

Forwarded

[Faint, mostly illegible handwritten notes and signatures in the upper right section of the document.]

Printed by W. W. Wood

the

Proceedings of the Madras Government
Read the following letters from the
Venerable the Rev. Archdeacon of 19th
April 1875. to the District Engineer.
Palani of 4th May 1875 No. 21.

Order thereon.

It has been ascertained
that the Bell supplied
for the Church at York
was of the size ^{such} 20 x 15
ordinarily provided for
such purposes. The
question will be submitted
for consideration in the
Ecclesiastical Department
as to the necessity or
otherwise of exchanging

It is said that the
Pole is a great
man - I don't know
how large he is - but
that is all right -
He

Curve

John -

292

24-14

[illegible]

Supd to Cols 12-6-75 R. 27-3-125

Public Works Dept.

Proceedings of the Madras Government
Under date the 1875.
2. 2. 1875.

Under the
Read the following:-
Inst of the Leech Dept^{on} on letter^{from} com^{ing} } H. I. No. - dated 17th Apr/75
+ W. Archibald
From
The Dist. Eng. Salem. (H. I. No. 21 of 4th May 1875)

G. O no: 1509 of 31st May / 78.
As the Bell

supplied to the Church:
at Yvercaud is too small
the District Engineer
Presidency will arrange
for exchanging it for
one of larger dimensions.
The size of the new Bell
will be settled in com-
munication with the
venerable the Archdeacon

5 ~~Sec~~ Sec. War. & Dep^{ty} ✓
5 Out. Eng. Presidency ✓
5 " Salern. ✓
5 Genl. P. W. Account ✓

[Faint, illegible handwritten text in a column on the left side of the page]

[Faint, illegible handwritten text in a column in the middle of the page]

[Faint, illegible handwritten text in a large column on the right side of the page]

12593/4

25.5.21
Ch. 29. 1. 175

2999 2606

DEPT. OF HIGHWAYS

PUBLIC WORKS

Mr. H. Ingr,

Presidency

Date

Recd.

11 May 1889 No. 1509

Nos. 593-594

Bell of the Church at

Yreand, Salem. — The

being too small
the District Engineer
Presidency to arrange for
exchanging it for one
of larger dimensions. The
size to be settled in communication
with the Venerable the
Archdeacon.

593/4

25.5.11
08.09.11