

600 of 1875. *Ching*
PUBLIC WORKS.

Ching
Ching

Dated
To
By
22 Sept 1875 2708

Nov. 5 27/8

Murorsambet tank,
Chingleput Dt. the District
amounting to the 820 for
repairing the — — —
with — — —

16
*Proceedings of the Madras Government, Public Works Department,
 22nd September 1875.*

Read the following:—

No. 1,071.

No. 527.

Note by the Chief Engineer for Irrigation.

No. 2,246, 3rd September.

The following estimates have been submitted by the Superintending Engineer, Chingleput:—

	rs.
Muversasambedu Tank—Repairs	645
Minor New Work	175
Total	820
Ayacut area	Acres 76
„ assessment	Rs. 195
Average revenue	„ 194
Highest do.	„ 222

This tank is in the middle of a group receiving the surplus of tanks above and surplus-
 ing into others below, and either estimates for the whole group should have been
 submitted together, or the circumstances of the other tanks should have been stated
 and an illustrative sketch should have been sent in.

2. The catchment basin above the Muversasambedu tank is reported to be $1\frac{1}{2}$
 square miles. It has no surplus work of any kind, and it is proposed to construct an
 escape of rubble masonry 78 feet long at one end of the bund; the appropriateness of
 the design depends upon the nature of the soil, which is described as fairly good.
 The bund of so petty a tank need not be more than 2 feet above M. W. L. which is to
 be 2 feet above F. T. L.

Ootacamund,
 17th September 1875.

(Signed) JOHN MULLINS, Lieut.-Colonel, R.E.,
Chief Engineer for Irrigation.

No. 528.

ORDER THEREON, 22nd September 1875, No. 2,748.

IRRIGATION, No. 48-B.

Account.

The following estimates are sanctioned:—

	Revenue.	Capital.
	RS.	RS.
Muversasambedu Tank	645	175

2. It should not have been necessary after the instructions given to point out to
 the Superintending Engineer that individual tanks of a group cannot be effectively
 treated apart from the other members of the group.

(True Extract.)

Major-General, R.E.,
Secretary to Government.

To the Chief Engineer for Irrigation.
 „ Controller of Public Works Accounts.
 „ Superintending Engineer, Chingleput.
 Exd. S. T. Kustin.
 Spare Copies

No. 1071.

Note by the Chief Engineer for Irrigation.

No. 3346-3444. The following estimates have been submitted by the Superintendant Engineer.

Enclosures 4. Inuvassambodu tank Repairs Rupees 645
Minor New Work " 175

Total Rupees 820

Irrigated area acres 76

" assessment Rupees 175

Average revenue " 174

Highest do " 232

This tank is in the middle of a group receiving the surplus of tanks above and surplus into others below, and either estimates for the whole group should have been submitted together or the circumstances of the other tanks should have been stated and an illustrative sketch should have been sent in.

The catchment basin above the Inuvassambodu tank is reported to be $1\frac{1}{2}$ square miles. It has no surplus work of any kind and it is proposed to construct an escape of rubble masonry 8 feet long at one end.

end of the land; the appropriateness of
 the design depends upon the nature of the
 soil, which is described as fairly good. The
 bank of so fatty a bank need not be
 more than 2 feet above M.W.L. which is to
 be 2 feet above F.T.L.

Subordinates
 Chief Engineer for Irrigation

Ootacamund
 19th Sept 1875

To The Secretary of Government
 S.H.

No 527

Recd from 21-9-75

No 2748

S.H.

Pro. of the Madras Government

Under date 12th Sept 1875

Read the following:-

Lch. Engr for Irrigation (N.E. No 1071 of 14th Sept 1875)

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

of estimated

tract

new Capital
 5-175

has been

the instruc

point out

near that

No of a

be effec

first from

is of the

of Chingleput
 with orig
 100 papers
 Chingleput
 17

20/9

50 Sep - 8-10-75

end of the land; the appropriateness of
the design depends upon the nature of the
soil, which is described as fairly good. The
land of so petty a tank need not be
more than
be a few

P. W. 1875 Sept.
No: 6149

From

The Chief Engr.
for Irrigation.

Dated 17th Sept. 1875.
Recd. 24th — 1875.

E. 4. No: 1071.

Notes on Est. for the
repairs of Kurnam tank,
Chingleput Dist.

No. 2748. 22-9-75

To The Secretary to Government
S.H.C.

No 527

No. 2748

S.H.C.

Pro: of the Madras Government

Under date the 22nd Sept 1875

Read the following:-

From

The Ch. Engr for Irrigation (H. E. No: 1071 of 17. Sept 1875)

The following estimates
are sanctioned.

Chingleput District.

Revenue - Capital

Muvrasambudu tank No 605 - 175

It should not have been
necessary after the instructions
given to point out
to the Superintendant that
individual tanks of a
group cannot be effec-
tively treated apart from
the other members of the
group.

Rev: Deptt

Colr of Chingleput

Chief Engr

Estimate with

for Chingleput

with orig
papers
estimate

Price 17

20/9

sc sep - 8 - 10 - 75