

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	301	Press	Original
~~B.P.~~ No.		Mis.	
Dated	3 . 2 .	195	1875

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
3rd February 1875.*

No. 78. Read the following Endorsement of the Chief Engineer for Irrigation, dated Camp at Sooramungalum, 21st December 1874, No 1,080.

Supplemental List of Tanks breached during the late Rains in the Cuddapah District

Taluq	Village	Name of Tank, etc	Whether Government or Dasa-bandam	Nature of Breach	Remarks
Kadry	Numbula Poolikunta Reddipully	Peddachervoo	Govt	Calingulah washed away	It appears that the Overseer has done some repairs
		Do	Do.	Calingulah washed away and the bund requires repair	
	Putnum	Mullumma-coonta	Do	The bund breached and water passes away	
	Oopalapadoo	Yerracoonta.	Do	Gaps have been caused in the calingulah and the bund in some parts came down	
	Kullasamudrum	Tank	Do	Breached and water passes away	
	Nullachervoo	Kothacoonta	Do	The northern calingulah is out of order	
	Obaladavorachervoo	Peddachervoo	Do	Some of the stones of the calingulah washed away, and the bund also requires repairs	
	Kadry	Vittalarayanichervoo.	Do	Water passes away through gaps in the bund	
	Panatulachervoo	Peddachervoo	Do	Breached	
	Tavalum	1. Mubbuvaipully calva 2. Narayana-chervoopully calva	Dasabandam. Do	The sluices of these channels at the Paupugnee washed away, and the cultivation under them is now drying for want of water	
	Kakuntty	1 Peddachervoo	Govt	Stones to a distance of 20 yards have been carried away, and the southern calingulah and another to a distance of 57 yards in the central one	
		2 The supply channel from Paupugnee river to Timina, Nayanichervoo	Do	..	
	Mooklapooram	Large tank ..	Do	...	
	Luckasamudrom	Luckasemichervoo	Do	...	
	Mallavomala . Mullayully	Large tank ... Nullachervoo	Do Do		Do Do

CUDDAPAH,
15th December 1874

(Signed) A S MOBERLY, Colonel, R E,
District Engineer, Cuddapah

Proceedings of the Madras Government, Public Works Department,
3rd February 1875.

Submitted for the information of Government in continuation of this Office
No. 999-B, dated 2nd December 1874.

2. The District Engineer should have stated what arrangements he has made
to provide for the supply of water at the river channels, which need not be
affected by the destruction of the head sluices.

(Signed) JOHN MULLINS, Lieut.-Col, R.E.,
Chief Engineer for Irrigation.

No. 79 ORDER THEREON, 3rd February 1875, No. 301.

IRRIGATION, No 3.

ORDERED to be recorded.

(True Extract)

Colonel, R.E.,

Secretary to Government.

To the Chief Engineer for Irrigation
" Revenue Department
" District Engineer, Cuddapah.

Supplemental list of Tanks breached during the late rains in the Cuddapah
District.

Village	Name of Tank & Government	Whether Government Tank	Nature of Breach
Mumbala	Paldia Chervoo	Government	Calingulab washed away.
Paldia	Paldia Chervoo	Government	Calingulab washed away and the bund requires repair.
Paldia	Paldia Chervoo	Government	The bund breached and water flowing gaps have been caused in the Calingulab and the bund in some places have come down.
Paldia	Paldia Chervoo	Government	Breached and water flows away.
Paldia	Paldia Chervoo	Government	The northern Calingulab is out of order.
Paldia	Paldia Chervoo	Government	Some of the stones in the Calingulab washed away and the bund also requires repairs.
Paldia	Paldia Chervoo	Government	Bund flows away through gaps in the bund.

It appears that
the Government has done
some repairs.

What? Village

June 27th 40

Robert
General
Washington

Failure of Breach

Revised

Samuelachewen Polak Cherico Governor

Paradise, Melbourne, Australia

Calua } Dances the slaves of these chambers.
2 Marymachoon } at the Ponging was the living.
fully Calua } And the Callation under them

Full, Calua

Lucy, Calua -

fully Calves } and the Cullation under them
is now drying for want of water
Rabbits which

Raf. Pimentel, Vol. da Chap. — Goumit.

[illegible]

2. The duplicate

[illegible]

renew to consider.

Mayami Cheever

The right honorable
Complained to the
Collector that
some of these are
early repaired the
cannot send them
would be left in the

Most Riparian Large Faults

Luchanthes lucida d.

Malabar Large Jamb - do

Nullapulle, Tallacherro do

Reported to be
in damaged state

Reported to be in
dangerous condition

2

—

Lucidafab Distinct
Engineers Office
15th December 1874

W. H. C. G. Col. R. G.
District Engineer of Louisiana

Cal. R. Co.

27. 1. 1900

152

10



... ..

1

2

Year	Percentage of Population Aged 65 and Over
1950	7%
1960	8%
1970	9%
1980	10%
1990	11%
2000	12%

2

2

1

2

P. W. 1875 Dept.
Proc of Govt for February
No: 64

From
The Chief Engineer
for Irrigation

To The Secretary to
Govt P.W.D.
N 1080

Dated 21 Dec 1874 }
Recd 6 Jan 1875 }
Encls 1

Submits with re-
marks supplemental
report on the tanks
breached during the
late rains in the Cal-
claph. Dist.

L.P. No. 301. 3-2-75.

Oct 75

P. W. Dept
Proceedings of the Madras Government
Read the following:-

From the Chief Engineer
for Irrigation } (N 1080 d/21st Dec/74).

301

Ordered to be recorded

MJ
15/7

W. J. P.
2/4/75

To The Chief Engineer for Irrigation ✓
Revenue Dept. ✓
District Engineer (uddapah) ✓
Sept 4/2/75.

64

Govt. of 1875: Madras
PUBLIC WORKS.

To

The Chief Engineer
for Mysore

From

Secy

G.O. 3 Feb 1876. No 301

No: 78-79

Danks - Gudalapah S.

Supplemental Report
of the damages done
to Danks during the
late heavy rains, re-
corded —