

*Proceedings of the Madras Government, Public Works Department,
19th November 1875.*

No. 424. Read the following letter from Colonel A. S. MOBERLY, R.E., District Engineer, Cuddapah, to Major-General G. W. WALKER, R.E., Secretary to Government, Public Works Department, dated Peddatippasamudram, 9th November 1875, No. 1,758 :—

I HAVE the honor to forward, for approval and sanction, the accompanying plan, abstract estimate, specification report, and a list, amounting to Rupees 230, for repairing the Public Works Department bungalow and out-houses at Rajampett, and to state that a rent of Rupees 7-8-0 will be charged on the building when repairs are completed for the same. There are no funds at my disposal for carrying out this work.

2. The building was constructed about fifteen years ago as a Public Works Department bungalow, it is near the junction of the Royachoty and Rajampett road with the Madras road; its present value is given as Rupees 400, and as the old public bungalow at Pullumpett has been taken away from the Public Works Department the putting this building in order will give the Overseer a residence.

No. 425. ORDER THEREON, 19th November 1875, No. 3,298.

CIVIL WORKS, No. 28

THE repairs may be carried out and the expenditure met from the sum of Rupees 700 transferred from Godavery to Cuddapah under Repairs Civil Buildings in G.O., No. 3,270, dated 16th November 1875.

(True Extract)

Major-General, R.E.,
Secretary to Government.

To the District Engineer, Cuddapah
„ Controller of Public Works Accounts

Exd E C Shunker
Spare Copies

Stause Officer

ABSTRACT ESTIMATE.

Cuddapah District

Work Repairing Pullumputt S P H Bungalow
Room and Piry

Quantities	Description of Work.	Rate	Amount.	Amount of each part
40.77 1/2	Repairing Pullumputt S P H Bungalow			
41.74 1/2	White washing with Chunan 1 coat	2 6	6 5 11	
11.21 3/4	Plorning with brick Saly 1 Chunan	3 15	41 15 2	
20.42 3/4	Roofing with 1 foot grass/Bamboos/Bamboos Mats	3 5 6	79 14 9	
5 1/4	Stone and Chunan	2 10	10 6	
3 23 1/2	Chunan Plastering 1 coat	2 10	8 12 7	
132 3/16	Stone and Mud	9 6	31	
4 53 1/2	Concrete flooring 6" thick	2 10	8 10 11	
11 1/2	Jungle Wood wrought 1/2 put up	1 15	20 15 2	
1.87	Mud Plastering	8 6	15 10	
	Repairing Room			162 13 8
2 1/2	Concrete flooring 6" thick	2 10	14 10 4	
388 1/2	Plastering & rebuilding Stone & Mud	4 8	1 4	
4.43	Plastering with Chunan	1 4	5 8 11	
3.24	Shatching with old grass bamboo 1/2 per	1 11	5 14 5	
	Piry			24 1 7
2 1/2	Concrete flooring 6" thick	2 10	2 3 4	
9 1/2	Jungle Wood wrought 1/2 put up	1 15	14 15 5	
277 1/2	Plastering & rebuilding Stone & Mud	4 5	12 6	
3.77	Plastering with Chunan	1 4	4 11 8	
1.85	Shatching with old grass bamboo 1/2 per	1 11	2 14 5	
	Total Repair			223 11 5
	Less Dis at 5 per Cent			11 7 2
	Grand Total of the Estimate			235 10 3
				230

I do hereby certify that this Estimate provides for every necessary item and that no Supplemental Estimate will be required hereafter.

W. A. G. S. Schorrey
Camp Workman
S. Schorrey
P. Schorrey

N: 1758 of 1875-76.

Cuddalore District Engineer's
Office Camp Poddalippasamudram
Dated 9th November 1875.
Despatch 15 — 20

From

The District Engineer
of Cuddalore

The Chief Engineer
Public Works Department.
Fort St. George

Sir

I have the honor to forward for approval and sanction, the accompanying plan, — Abstract Estimate, Specification, Report and a list — amounting to Rupees 230-0-0 for repairing the D. P. W. Bungalows and out-houses at Rajampett and to state that a rent of Rs 4-8 will be charged on the building when repairs are completed for the same. There are no funds at my disposal for carrying out this work.

2. The building was constructed about 15 years ago as a D. P. W. Bungalow. it is near the junction of the Poyachoty and Rajampett Road.

1885-86
Lieutenant
Rang

Abstract of Estimate Amounting
to Rs 235-
for repairing the Bungalows
at D. P. W. Bungalows
Rajampett and out-houses.
Dated 27th October 1885.
Received
1885-

MT 1334/15

with the Madras Road: its present value is
given as Rs 100 and as the old Public Bungalow
at Pullumpett has been taken away from the D.P.W.
the putting this building in order will give the
Overseer a residence

I have the honor to be
Sir
Your Most Obedient Servant.
W. Webb Col. P.E.
District Engineer of Cuddapah.

17th May 1861
To the
District Engineer
Cuddapah

From
The
District Engineer
Cuddapah

17th May 1861
To the
District Engineer
Cuddapah

From
The
District Engineer
Cuddapah

17th May 1861
To the
District Engineer
Cuddapah

From
The
District Engineer
Cuddapah

17th May 1861
To the
District Engineer
Cuddapah

From
The
District Engineer
Cuddapah

17th May 1861
To the
District Engineer
Cuddapah

From
The
District Engineer
Cuddapah

17th May 1861
To the
District Engineer
Cuddapah

From
The
District Engineer
Cuddapah

17th May 1861
To the
District Engineer
Cuddapah

From
The
District Engineer
Cuddapah

17th May 1861
To the
District Engineer
Cuddapah

From
The
District Engineer
Cuddapah

7334
Govt. of 1875 Madras.
PUBLIC WORKS.

To

G. E. Suddapah

Dated

Issued

Recd

Encl

G O.

19 Nov

1875,

No 3798

Nos. 426-428

Reamphat Bungalow
Chiddapah Dist: Echmick
of Rs 230 for repairing the
—, sanctioned for Ex-
-cution —