

(1) Number of pages_____

(2) Date of repair_____

(3) Initials of the Referencer_____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	3342	Press
B.P. No.		Mis

Dated 22.11.

195
1875

Not to be folded or roughly handled

J

*Proceedings of the Madras Government, Public Works Department,
22nd November 1875.*

Read the following paper —

No 1,349

No 510 *Note by the Chief Engineer for Irrigation*

THE following estimates have been submitted by the District Engineer,
Presidency

No 3,396, 4th November 1875

The estimates are for some of the tanks in the neighbourhood of Madras, for which, on a representation being made by the President of the Municipal Commission of their dangerous state, were ordered to be repaired and afterwards transferred to the charge of the Deputy Collector of Madras. It was anticipated that the outlay then sanctioned would have sufficed for many years, but there appears to be a probability of a demand for expenditure out of proportion to the revenue of these works

Nungambakum Tank	Rupees 220
Area of irrigation	Acres 161
Quit-rent	Rupees 747

Expenditure in the last four years, Rupees 5,105

The work provided for is an extension of the bund across ground now intersected by a ravine, by which the tank water escapes into the Cooum, and the levelling of the ground for 200 feet beyond the intended end of the bund to allow of the escape of water on the occurrence of very heavy rainfall

Mylapore Tank	Rupees 930
Area of irrigation	Acres 887
Quit-rent	Rupees 3,811

Expenditure of the last four years, Rupees 6,346

The work to be done is of the ordinary description and requires no remark

Spur Tank	Rupees 70
Area of irrigation	Acres 25
Quit rent	Rupees 157

Expenditure on repairs (1873-74), Rupees 1,206

The estimate provides for trifling repairs which probably are mainly rendered necessary by the traffic on and over the bund

Veyaserpady Tank	Rupees 1,000
Area of irrigation	Acres 493
Quit-rent	Rupees 1,207

Cost of repairs in the last four years, Rupees 10,824

The only item that calls for notice is the rate, Rupees 1-12-0, for fully backing for revetment, which, seeing that this tank is not far from the hills whence this material is obtainable, appears to be about double the proper rate

CAMP AT PEDDATHIPP00-

SAMUDRAM,
9th November 1875

(Signed) JOHN MULLINS, Lt-Col, R E,
Chief Engineer for Irrigation

Proceedings of the Madras Government, Public Works Department,
22nd November 1875.

No 511. ORDER THEREON, 22nd November 1875, No 3,342.

IRRIGATION, No 51		THE following estimates are sanc-	
Account		tioned —	
<i>Presidency District</i>			
Nungambakum Tank	..	.	Rs 220
Mylapore do	..	...	931
Spur do	.	..	70
Veyaserpady do	.	...	1,000

The attention of the Revenue Board will be requested to the cost of the upkeep of these tanks, on which a similar rate of expenditure cannot be provided for in the future without depriving other irrigation works of the money required for ordinary and moderate repairs costing on the average about 8 or 10 per cent of the revenue

2 The District Engineer should examine into the rate allowed in the Veyaserpady Tank estimate for backing to the revetment.

(True Extract)

Major-General, R E,
Secretary to Government

To the District Engineer, Presidency
" Board of Revenue
" Revenue Department
" Controller of Public Works Accounts
" Chief Engineer for Irrigation

Exd E C Shunker
Spare Copies

No 1349 30

Note by the Chief Engineer for Irrigation —

The following estimates have been submitted by the District Engineer, Presidency.

The estimates are for some of the Tanks in the neighbourhood of Madras for which, on a representation being made by the President of the Municipal Commission of their dangerous state were ordered to be repaired and afterwards transferred to the charge of the Deputy Collector of Madras. It was anticipated that the outlay then sanctioned would have sufficed for many years, but there appears to be a probability of a demand for expenditure out of proportion to the Revenue of these works.

Nungambakum Tank — Rupees 220

Area of irrigation — 161 acres

Quit rent — 747 Rupees

Expenditure in the last 4 years Rupees 5105.

The work provided for is an extension of the bund across ground now intersected

by

No 3396-4 No.
November 1875.

Enclosures 8

Pro: Madras
Government No.
82 dated 13th
August 73

by a ravine, by which the tank water escapes into the Coorn, and the levelling of the ground for 200 feet beyond the intended end of the bund to allow of the escape of water on the occurrence of very heavy rain-fall.

Mylapore tank — Rupees 930

Area of irrigation — acres — 887.

Quit rent — Rupees 3811.

Expenditure of the last 4 years Rupees 6346.

The work to be done is of the ordinary description and requires no remark.

Spur Tank — Rupees 70.

Area of irrigation — acres 25

Quit rent — Rupees 157.

Expenditure on repairs (1873-74) Rupees 1206.

The estimate provides for trifling repairs which probably are mainly rendered necessary by the traffic on and over the bund.

Vyaserpadly Tank — Rupees 1000

Area of irrigation — acres 493

Quit rent — Rupees 1207

Cost of repairs in the last 4 years Rs. 10824.

The only item that calls for notice is the rate Rupees 1-12-4 for fully backing for

87:05

revetment, which seeing that this Tank is not far from the Hills, whence this material is obtainable, appears to be about double the proper rate.

Campat Pedda
thippoo sannidrauni
9 November 1875

Colundunius Lieut. Col. R.E.
Chief Engineer for Irrigation

To
The Secretary to Government
P.W.D.

48 no 82 9/13 Aug 73 hrs:

P. W. 1895 Sept.
No: 7383

From

The Chief Engr.
for Irrigation.

Dated 9th Nov. 1895.
Recd. 18th Nov. 1895.

G. S. No: 1349

Note on Estimates
for repairing certain
Tanks in the Presidency
District.

X R. S. S. S.
S. S. S. S.

G.O. No 3342 22/11/75

14570

Cir 19-11-75

No 3342

P. W. 1895
Proceedings of the Madras Government
Under date the 22 Nov 75
Read the following:-

From

The Chief Engineer
for Irrigation } (No 1349 dt 9 Nov 75)

The following estimates
are sanctioned -

Presidency District

Nungumbakam Tank Repairs 220
Mylapore — do — " — 900
S. S. — do — " — 700
Vengaloorpady — do — " — 1000

The attention of the
Revenue Board will be re-
quested to the cost of the
upkeep of these tanks, on
which a similar rate of
expenditure cannot be pro-
vided for in the future —
without depriving other
irrigation works of the money
required

required for ordinary and moderate repairs costing on the average about 8 or 10 per cent of the revenue -

2 The District Engineer should examine into the rate allowed in the Vayaserpa, tank estimate for backing to the revetment.

My. 10/11

Govt. of 1875 Madras.
PUBLIC WORKS.

To

J. E. Presidency
2/11

Dated

Issued

Read

Encl

G. O. 22 Nov 1875, No. 334

Nos 510-511

For the Presidency Est
Estimates amounting to Rs
2220 for repairing certain
Sanctioned -

To The District Engineer, Presidency
Board of Revenue.
Revenue Dept.
Controller of Govt. Accounts
Chief Engineer for Irrigation

No 570-571

* with 8 Enclosures

Drpd - 3-12-75

Drpd - 3-12-75

Cir 19-11-75