

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works

DEPARTMENT

G.O. No.	3370	Press
B.P. No.		Mis.
Dated	26-11	1875 195

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
24th November 1875.*

No. 569. Read the following Proceedings of the Madras Government in the Ecclesiastical Department, dated 13th November 1875, No. 270 :—

ABSTRACT.—*Churches—England.*—Orders passed on the estimate submitted for repairing and improving the Church at Chicacole.

No. 570. ORDER THEREON, 24th November 1875, No. 3,370. ' .

CIVIL WORKS, No. 36.

THE estimates reduced in amount to Rupees 90, Rupees 9, and Rupees 20, respectively, are sanctioned.

2. The District Engineer will provide the necessary funds from the grant at his disposal under Repairs Civil Buildings Provincial.

(True Extract.)

Major-General, R.E.,
Secretary to Government.

To the District Engineer, Ganjam.

„ Controller of Public Works Accounts.

Ed. E. C. Shunker.

Spare Copies

*Proceedings of the Madras Government, Ecclesiastical Department,
13th November 1875.*

Churches—England.

No. 15. Read the following letter from the Venerable C. R. DRURY, M.A., Archdeacon of Madras, to the Hon. D. F. CARMICHAEL, Officiating Chief Secretary to Government, Fort St. George, dated Madras, 4th November 1875, No. 352:—

I have the honor to forward estimates for repairs of the Chancel walls at the Church at Chicacole, and a new Holy Table, and new matting, and also for work required in the Cemeteries of Chicacole and Kimedy. And to solicit early sanction of Government for the necessary repairs to the Chancel at Chicacole. I also enclose a letter from the Chaplain of Vizianagram, forwarding the estimate to me. I trust that this application will be favorably received by Government.

From the Rev. D. W. KIDD, M.A., Chaplain of Vizianagram, to the Venerable C. R. DRURY, M.A., Archdeacon of Madras, dated Vizianagram, 27th October 1875.

I have the honor to enclose, herewith, estimates for necessary repairs to the Church and Cemetery at Chicacole, and to the Cemetery at Kimedy.

2. The Executive Engineer in charge of the Chicacole Range writes to me that "two large cracks have taken place in the Chancel walls which must be supported with buttresses to prevent further giving," and also that the Holy Table and the mats in the Church require to be replaced by new ones. I quite concur with him.

3. Under these circumstances, I beg that you will obtain the early sanction of Government for effecting the estimated repairs.

No. 16. ORDER THEREON, 13th November 1875, No. 270.

Under the Resolution of the Government of India, dated 9th July 1875, No. 87, the following items which are included in the estimate for repairing and improving the Church at Chicacole are inadmissible, viz:—

	RS.	A.	P.
Re-covering footstools with cloth	1	8	0
Carpet	30	0	0
Matting	8	12	0

2. In the estimate for repairs to Cemetery at Chicacole, the charges for—

Weeding	Rs. 1
and Removing trees	„ 1

should be excluded as they are debitable to Provincial Services—Minor Establishments, Cemeteries, Miscellaneous.

3. The same remarks apply to the item—

Weeding	Rs. 2
---------	-------

in the estimate for the Burial-ground at Kimedy.

4. With these remarks the estimate will be transferred to the Public Works Department for disposal.

(True Extract.)

To the Public Works Department, with Enclosure
 „ Venerable the Archdeacon of Madras.
 „ Accountant-General.
 Exd T. O'Connor.

[Signature]
 Officiating Chief Secretary.

Detailed Estimate No 57 of 1875/76
 Ganjam District
 Lalug Cherisole
 Voon Cherisole
 Estimate for improvements and Repairs to Pro-
 testant Church at Cherisole

Detailed of work	Assumed				Cubed feet	Cyd ^s
	No	ft	in	in		
Concrete under foundations of Buttresses	2	4	4	$\frac{1}{2}$	16	
Cyd ^s of Concrete in Chancel					16	$\frac{16}{27}$
Foundation and Basement to Buttresses	2	4	4	7	224	
Buttresses above	2	4	2	9	192	
Cyd ^s of Brick in Chancel					416	$15\frac{11}{27}$
Squares of Plastering in Chancel						2
Decorating foundations &c.						
New Oak wood Communion table						1
Recovering foot stools with cloth						6 Sqs
Carpet to Chancel						1
Matting Church throughout						7 Sqs
Contingencies						

2020 Cherisole
 Range Office
 3^d October 1875

W. H. M. P. & C
 Executive Engineer

Abstract Estimate No 57 of 1875/76
 District Gangan
 Taluk Chinnole
 Local Chinnole
 Last Repair Repairs
 Estimate for Improvements and Repairs to Protestant
 Church at Chinnole

Quantity	Description of work	Rate	Per Unit	Amount	Total
$\frac{16}{27}$	Cyds of Concrete in Chinnole	1 1/4	Cyds	1 1/4	19
$\frac{15 11}{27}$	Do of Brick work in Do	3	Do	46	36
2	Squares of Plastering in Do	2	Sqr	4	
	Decorating foundations &c			2	
1	New Teak wood Communion Table	30	each	30	
6	Sqrs of Recovering foot stools with cloth	4	Sqr	1 8	
1	Carpet to Chancel	30	each	30	
7	Sqrs of Matting Church throughout	1 1/4	Sqr	8 1/2	
	Contingencies	5	Cent	6 69	
	Total Estimate Repairs				120

No 2 or Chinnole
 Range Office
 October 1875
 Geo. P. P.

Geo. P. P.
 b6
 Sweeney & Pugin

District of Columbia
 Valay Cheasole
 Good Cheasole
 Last Repair
 Repairs to Cemetery at Cheasole

Number	Description of work	Rate	Per Item		Amount	Total
154	Cyds of Graveling	" 8 ⁰⁰	Cyds	7	117	
9	Fencing Gate			1	"	
	Working Cemetery			1	"	
	Removing trees grown over grasses and in the road			1	"	
	Contingencies			"	45	
	Total Estimate Repairs					1100

No 200 Cheasole
 Range Office
 3rd October 1875
 C. D. Allen

Res. Wm. H. H. & C.
 Executive Engineer

Detailed Estimate of 1875-76
 District Garijan
 Taluk Chicacole
 Town Chicacole
 Last Repair
 Repairs to Crumty at Chicacole

Particulars	No	Measurement			Cds or Lys
		La	B	W	
Graveling walks	1	213	6	$\frac{1}{4}$	819 $\frac{1}{2}$
Graveling walks	1	130	9	$\frac{1}{4}$	97 $\frac{1}{2}$
Total Cb of graveling or					417
Cds					15 $\frac{4}{9}$

Estimate No. 20 of 1875-76

District Ganjam

Salub Khindz

Low Khindz

Estimate for making a ^{dark red iron} wooden railing gate to the burial ground at Khindz

No	Permanent			Caled Cont.	Cps or Sq. ft.	Description of work	Rate			Amount	Total
	Rs	As	P				Rs	As	P		
7	4	2			31 1/2	Sq. ft. of wooden railing gate	2	10	0	19	11
						Yardwork				5	
						Masonry				2	0
						Total Estimate Rs				26	11

The old wooden railing gate is much rotten & not worth repairing. It is therefore proposed to make an entirely new one.

Khindz Sub
Divisional Office
Camp Khindz

Khindz
Superintendent

No. 2 Khindz
Range Office
3rd October 1876

Mr. M. S. S. S.
Executive Engineer

GB-24 Khindz
No. 519

No 3370

Public Works Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the

24th Nov 1875

Read the following:—

Pro: Ecclesiastical Dept. (H.C. No. 270 of 13th Nov 1875)

The Estimates are reduced in amount to Rs 90, Rs 9 and Rs 20 respectively are sanctioned.

The District Engineer will provide the necessary funds from the grant at his disposal under Repairs Civil Buildings Provincial.

W. G. G. G. G.
Controller.
Venerable the archdeacon

Sept - 1 - 12 - 75

11/11: 24/10/75

GO 24 Nov 1875
sub B. K. 569

Op 74/10

of 1875
PUBLIC WORKS.

J. E. Gauguier

To

For

By

By

24 Nov 3370

Nos. 569 - 570

Church at Chicanele,
Carson St. — The reduced
estimates for repairing and
improving the —, sanctioned
& funds provided from the
grant at the Mayor's disposal
under Repairs Civil Build-
ings Provincial.