

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.

3472

Press

B.P. No.

Mis.

Dated

7 - 12

195

Not to be folded or roughly handled

No 90

Superintending Engineer's Office
Coimbatore 23rd Novr. 1875.

From

The Superintending Engineer
Coimbatore

To

The Chief Engineer for Irrigation
Coimbatore

Sir,

Incls.
1 Estimate

With reference to G.O. No 50,
dated 8th June 1875, I have received
from the Collector the accompany-
ing estimate of Rs. 400, for repair-
ing the Kannimollur aicut,
which amount will be disbursed
to the Revenue Department
by whom the repairs are to be
carried out, if the estimate
is approved of.

2. As the amount of the
above estimate is, and those of
future ones will be in excess
of the local limit of sanction
(G.O. No 299 of 7th Feby. 1874) I
have the honor to request that
you will be so good as to let
me know whether all future
estimates for up-keep of the
aicut should be submitted

for the sanction of Government
 or whether I can pass them
 for execution and disburse
 the amounts to the Collector.

I have the honor
 to be, Sir,
 Your most obedient servant

W. H. P. [Signature]
 Superintendent Engineer

1897-1898
 1st 100-100
 2nd 63-65
 3rd 203-204
 4th 159-160
 5th 60-60
 6th 11-11

1897-1898
 1st 100-100
 2nd 63-65
 3rd 203-204
 4th 159-160
 5th 60-60
 6th 11-11

1897-1898
 1st 100-100
 2nd 63-65
 3rd 203-204
 4th 159-160
 5th 60-60
 6th 11-11

1897-1898

1897-1898

1897-1898
 1st 100-100
 2nd 63-65
 3rd 203-204
 4th 159-160
 5th 60-60
 6th 11-11

Measurement in yards	Width	Height	Area	Description	Cost	Rate	Amount
12 1/2	252			Breach to the South of main wall			
8	64			Breach to the south of the 1st breach			
31 6				Old stone wall	2		632
				From here to further the stone			
				to one another so that they may			
				not be rooted up	60	6	228
				Lead	2	4	8
				to of holes the made	12	1	78
				For masonry			3
				For miscellaneous works viz			
				Cowbarn (dam) etc			7
							180
				The rights agree to pay			200
				Balance to be sanctioned			488

W. H. P. [Signature]
 Collector

1897-1898
 1st 100-100
 2nd 63-65
 3rd 203-204
 4th 159-160
 5th 60-60
 6th 11-11

No. 3472. Public Works Dept.
 Proceedings of the Madras Government
 Under date the 7th Decr 75

Read the following:-

From
 The Superintending Engineer,
 Secunderabad. (M.S. No 90 dt 23rd Novr 1875)

The estimate of Rupees
 680 for the repair of the
 Kanimpolluru Aqueduct in
 Secunderabad is sanctioned.
 It is observed that Rupees
 200 are to be contributed
 by the ryots, so that the
 amount to be provided from
 Agricultural repair funds
 is Rupees 480.

The estimates for the
 maintenance of this irriga-
 tion work, while under the
 management of the Revenue
 Officers

Handwritten note in left margin, partially illegible.

For a letter from the
 Secy (Engineering)
 Secunderabad to the
 Secy (Engineering)
 for Secunderabad
 dated 11th Novr 75
 No 90 dated 23rd Novr 75
 Estimate for
 for maintaining
 the Kanimpolluru
 Aqueduct in
 Secunderabad
 Rs 680-0-0


Officers, will be dealt with under the rules, but the Superintending Engineer will consider himself authorized, on the receipt of estimates, to place any reasonable amount at the disposal of the Collector in anticipation of the sanction of the estimate.

3 The particulars of past and proposed expenditure are to be given with each estimate, as also the Revenue.

They are to the present time as follows-

	Expenditure.	Estimate.	Revenue.
1870-71	—	—	947
1871-72	1577	—	158
1872-73	3837	—	1157
1873-74	3631	—	1114
1874-75	1565	—	not reported
1875-76	—	480	—

* Estimate of District comm. for 1875-76

Dec. 29/11


To The Deputy Secy Gen
 Chief Secy for
 Controller of
 Collector of
 Revenue

Officers, will be dealt

✓

Bill of 1875
PUBLIC WORKS

Supp. Aug
Comptroller

7 Dec 3472

Laminated Quail
Comptroller bit — The
— trial of the 680 for repair
to the — sanctioned with
from the.