

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	502	Press
B.P. No.		Mis. →
Dated	20 - 2 -	CE 75 195

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
20th February 1875.*

No. 529. Read the following letter from Major J. BEATTY, R.E., District Engineer, Godavery District, to Colonel G. W. WALKER, R.E., Secretary to Government, Public Works Department, dated Dowlaishweram, 4th December 1874, No. 2,832:—

IN continuation of my letter, No. 2,176, dated 9th October 1874, I have the honor to forward herewith two detailed estimates, amounting to Rupees 2,053 and Rupees 2,065, for repairing sea punts Nos. 3 and 5 respectively, and to request you will be good enough to obtain sanction of Government to these repairs and return me the estimates at your earliest convenience. The cost may be met from the allotment of Rupees 8,769 provided for the repairs of harbour plant.

No. 530. ORDER THEREON, 20th February 1875, No. 502.

ACCOUNT, No. 32.

SANCTIONED.

2. Funds will be available by transfer of Rupees 5,000 from the allotment for improvements to Mangalore Harbour, Item 100 of the current year's Budget now under consideration in the Financial Department.

(True Extract.)

Colonel, R.E.,
Secretary to Government.

To the District Engineer, Godavery.
" " South Canara.
" Financial Department.
" Controller of Public Works Accounts.

Exd. W. J. Lewis.
Spare Copies

DETAILED ESTIMATE.
GOVERNMENT WORKSHOP.

Work. *Repairing Sea Punk No. 5*

Particulars of Work.	Number.	MEASUREMENT.			Square or Running feet.	Length per Foot.	Cubic Contents.
		Length.	Breadth.	Height.			
1	2	3	4	5	6	7	8
<u>Iron work.</u>							
Sheet Iron for bottom	18	11.3	2.6	0.0 1/4	506 1/2	✓	
do for keels	2	8.2	2.6	0.0 1/4	41 1/2	✓	
Cover plates under ribs	17	1.2	0.8	0.0 1/4	13 1/4	✓	
do for bottom sheels	10	2.6	0.8	0.0 1/4	16 1/2	✓	
Patches to hull	2	3.3	2.6	0.0 1/4	16 1/2	✓	5936 1/2
Buildge plates	2	5.2	0.8	0.0 3/8	69 1/2	✓	
Repairing rudder	1	2.0	3.0	0.0 3/8	75 1/2	✓	1130
L Iron for fitting safe-plants	1	0.0	2.2	0.0 1/4	50	✓	225 1/2
Round Iron for bolts for do	25	1.0	1/2	du	225	✓	18 1/2
do for rivets	5000	0.3	1/8	du	1250	✓	1328 1/2
Total Iron work above							8638 1/2
<u>Teak wood work</u>							
Deck planking	1	50	12.6	0.0 1/2	—	✓	130.2-6
Binding piece	4	6	2.6	0.0 1/2	—	✓	52-6
Safe planking	1	10	0.9	0.0 1/2	—	✓	5
Total Teak work							137.8-6
Caulking	—	—	—	—	Off	✓	1100
Painting outside	—	—	—	—	500	✓	8 1/2
Tarred inside	—	—	—	—	—	✓	8 1/2
Docking & Launching	—	—	—	—	—	✓	—

Abstract.

Quantity.	Description of Work.	Rate.	Amount.	Total.
1	2	3	4	5
8638	lbs Wrought Iron	26	1349 10	✓
137 $\frac{2}{3}$	cft Oakwood wrought put up	2 50	275 54	✓
1100	Reft Caulking - - - - -	3 00	33 00	✓
8 $\frac{1}{2}$	Squares Painting - - - - -	3 80	29 120	✓
8 $\frac{1}{2}$	do Tarring - - - - -	1 80	12 120	✓
	Docking & Raunching - - - - -	-	20 00	✓
	Centago - - - - -	20	Cent.	344 75
	Total Expenses			2065 00

Government Workshop
 Office Godanery
 18th November 1894

A. M. S. on hand Capt. R. E.
 Executive Engineer Godanery
 Godanery

John Enom
 Sub Engineer

Exd
 456

R. Beatty Major R. E.
 District Engineer Godanery.

GOVERNMENT WORKSHOP

WORK.

Repairing Sea Bunk No. 3

Particulars of Work.	Number.	MEASUREMENT.			Square or Running feet.	Length per Foot.	Cubic Contents.
		Length.	Breadth.	Height.			
1	2	3	4	5	6	7	8
<u>Iron work</u>							
Sheet Iron for bottom	18	1-3	2-6	$\frac{1}{4}$	506 $\frac{1}{4}$		
do for ends	2	8-3	2-6	$\frac{1}{4}$	41 $\frac{1}{4}$		
Cover plates under ribs	17	1-2	0-8	$\frac{1}{4}$	13 $\frac{1}{4}$		
do bottom	10	2-6	0-8	$\frac{1}{4}$	16 $\frac{2}{3}$		
Patches to hull	2	3-3	2-6	$\frac{1}{4}$	16 $\frac{1}{4}$	10	5936 $\frac{1}{4}$
Bulge plates	2	52	0-8	$\frac{3}{8}$	593 $\frac{3}{8}$		
Sheet Iron for repairing keelson	1	3-0	1-0	$\frac{3}{8}$	3	15	1085
L. Iron for fitting safe plank	1	50	2x2	$\frac{1}{4}$	50	1 $\frac{1}{2}$	205
Round Iron for rivets	5000	0-3	$\frac{5}{8}$	dia	1250	$\frac{1}{16}$	1328 $\frac{1}{4}$
					Total wrought iron		857 $\frac{1}{4}$
<u>Woodwork</u>							
Deck Planking	1	50	12-6	$\frac{1}{2}$			130-2-6
Beaming keelson	4	6	0-6	$\frac{1}{2}$			2-6-0
Repairing safe plank	1	40	0-9	$\frac{1}{2}$			5-0-0
					Total cft.		137-8-6
Coaling							110-0
Painting outside							8 $\frac{1}{2}$
Carving inside							8 $\frac{1}{2}$
Backs & Lascas							

Abstract.

Quantity.	Description of Work.	Rate.	Amount.	Total.
1	2	3	4	5
85 7/12	th Wrought Iron work.	26	1339 12 3	✓
113 7/3	cfk Oakwood wrought patch	20	2275 5 4	✓
1100	cfk Caulking. 10 ft	3	33 00	✓
8 1/2	Leaves painting.	3 80	29 12 0	✓
8 1/2	" Tarring.	1 80	12 12 0	✓
	Docking & Launching		20 00	1710 9 7
	Centage	20	342 6 3	✓
	Total Dupon		2053 00	✓

Government Workshop

Office of the Engineer

18th November 1874.

John Conon
Sub Engineer

W. S. Onman Esq
Superintendent
Launches & Docking

L. Beatty Major R.E.
District Engineer Godavary

DOWLAISEWARUM, ^{#9}~~4~~ December 1874.

From

Major J. Beatty R.E.

District Engineer

Godavery District

To

Colonel G. W. Walker R. E.

Secretary to Government D. P. W.

MADRAS

SIR,

Enclosures Two

2 Estimates.

Exhibit 6.57

7/2/2004-06

1944

In continuation of my letter No. 2176 dated 9th October 1874 I have the honor to forward herewith 2 detailed Estimates, amounting to Rupees 2053 and Rupees 2065 for repairing Sea Ponto Nos 3 and 5 respectively, and to request you will be good enough to obtain sanction of Government to these repairs and return me the Estimates at your earliest convenience. The cost may be met from the allotment of Rupees 8769 provided for the repairs of Harbour Plant.

I have the honor to be
Sir

Your Most Obedient Servant
L. Beatty - Major R.E.
 District Engineer Godanery.

Compd
1822

P. W. D.

Proceedings of the Madras Government,

Under date the

187

Read the following:—

From
The District Engineer
Godavery

(R.E. No 2832 of 4th Dec/71)

Sanctioned.

Funds will ~~be~~ ~~be~~ be available by transfer of Rs 5,000 from the allotment for improvements to Mangalore Harbour, item 100 of the Current year's budget now under consideration in the Financial Department.


To

The District Com ^r	Godavary
"	"
"	Sub ^d Comm ^r
"	Financial Dept.
"	Controller of P.W.D.

Doc/P 23-2145

Wm

To Mr Secretary
 Government
 O.P.O.
 Madras
 Dated 4th
 Dec 12.3 Secunder
 1874
 No 2832
 Encls. 2 V
 Towards Estimate
 for repairing Nos 345
 Sea Buks for the
 Vaccination of Mysore
 - coast.
 Rb. No. 522. 20-2-95



7791
Govt. of Madras.
PUBLIC WORKS.

20

The Dist. Engr.
Godavery

Date:

Recd.

Encl. 2

G. O. 20 Febry. No. 100

502

Nos. 525-530

Ports - Godavery.

Estimate for repairs
Nos 3 and 5 see Ports
sanctioned - ~~with sanction~~
Funds to be available
by transfer of Rs. 5000
from the allotment for im-
provements to Mangalore
Harbour now under con-
sideration in the Financial
Department.