

(1) Number of pages \_\_\_\_\_

(2) Date of repair \_\_\_\_\_

(3) Initials of the Referencer \_\_\_\_\_

## MADRAS RECORD OFFICE

### Government of Madras

*Public Works* DEPARTMENT

|                     |         |       |                 |
|---------------------|---------|-------|-----------------|
| G.O. No.            | 581     | Press | <i>Original</i> |
| <del>B.P. No.</del> |         | Mis.  |                 |
| Dated               | / . 3 . | 1955  | 18/5            |

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,  
1st March 1875.*

No 31. Read the following letter from Colonel F. J. MOBERLY, R.E.,  
Superintending Engineer, Chingleput, to Colonel G. W. WALKER, R.E.,  
Secretary to Government, Public Works Department, dated Camp at  
Singaperoomal Covil, 10th February 1875, No 3,797 —

I HAVE the honor to submit, for the sanction of Government, and for an  
allotment of funds, an estimate for the  
1 Estimate repairs of the Overseer's Bungalow at  
Tripasore in Trivellore Taluq, amounting to Rupees 200, or more than one-fourth  
of the value of the building by Rupees 75

2. This building was once a Travellers' Bungalow, and was made over to  
this department in November 1865,\* it  
\* G O, No 3,532, dated 22nd November 1865 has been occupied as an office and resi-  
dence by the Overseer in charge of the Trivellore Taluq since 1872, on a monthly  
rent of Rupees 3 8 0 It has not been repaired for many years, and consequently  
is in very bad order It was severely tried by the cyclone of May 1872 and the  
subsequent storms The roofs of the building and out-houses are very leaky and  
walls are cracked, the basement round the bungalow requires to be concreted  
and sloped outward to keep the water of the surrounding part of the rampart  
outside from lodging and soaking into the walls and floor of the rooms The  
estimate provides for everything necessary at present, to put the building in good  
and habitable order.

No. 32. ORDER THEREON, 1st March 1875, No. 581.

CIVIL WORKS, No. 3.

The estimate, amounting to Rs 200,  
for repairing the Overseer's Bungalow  
at Tripasore, is sanctioned The Super-  
ntending Engineer will provide the necessary funds from the Provincial Budget  
grant for 1875-76 under repairs to Civil Buildings.

(True Extract)

(Signed) G. W. WALKER, Colonel, R.E.,

*Secretary to Government*

To the Superintending Engineer, Chingleput  
" Controller of Public Works Accounts

Exd A Grubert  
Spare Copies

*Carried Over*

Civil Building Detailed Estimate No. of 1875-76 Repairs  
 District Chengalpattu Taluk Trivellore  
 Village Truppapore

Work Repairing the old Travellers Bungalow at Truppapore.

Value of Building Rs 500

Date and Cost of last repairs not known

Proposed by the Range Officer

Sanctioned by

Necessity or object of work. Leaks badly, walls are cracked and dirty

### Abstract Estimate

| Quantity | Description of Charges                                                                                  | Rate | Per    | Amount | Total |
|----------|---------------------------------------------------------------------------------------------------------|------|--------|--------|-------|
| 24       | Squares of whitewashing                                                                                 | 2    | Square | 3      |       |
| 12       | D. Color washing                                                                                        | 3    | D.     | 2      |       |
| 9        | D. Plastering                                                                                           | 2 8  | D.     | 22     |       |
| 19       | D. Removing and repacking tiles<br>with $\frac{1}{8}$ new tiles & new Chunnam<br>borders                | 2 8  | D.     | 48     |       |
| 4        | Cubic yards of concrete round base of<br>main building on top of bastion                                | 3 8  | Cyds   | 14     |       |
| 24       | Squares of filling crevices in bastion on<br>which the Bungalow stands & pointing                       | 1 8  | Square | 36     |       |
| 4        | D. of filling crevices with concrete<br>and plastering East face of ramparts<br>below Office & Bathroom | 3    | D.     | 12     |       |
| 5        | Cubic yards Bricks in chunnam                                                                           | 4    | Cyds   | 20     |       |

Carried Over

|   |                                                                             |    |     |
|---|-----------------------------------------------------------------------------|----|-----|
| 3 | Squares of Green Paint to doors and windows of Bungalow                     | 3  | 9   |
| 8 | Pieces of Red wood for binding cracks                                       | 18 | 12  |
|   | Repairing doors and windows putting in fresh bolts hooks &c where necessary | 8  |     |
|   | Removing and rooting out trees &c in bastion                                | 3  |     |
|   | Gundries                                                                    | 11 |     |
|   | Total Rupees                                                                |    | 200 |

No. 1 Range Office  
21<sup>st</sup> January 1873

Signed / Mr Beeby Selig Covert

Wt. Sgt. Capt. C. C. C.

No 1 Range' Chongjak Basha

*J. M. Coker*

Work Repairing the Old Travellers Bungalow at Trichappore

Value of Building R<sup>o</sup> 500 —

Date & Cost of last Repair Not known

Proposed by the Range officer.

Sanctioned by

Necessity or object of work leaks bed, walls are cracked + dnf.

| Particulars of work            | Measurements in feet |        |         | Contents                          |
|--------------------------------|----------------------|--------|---------|-----------------------------------|
|                                | No                   | Length | Breadth |                                   |
| White washing                  |                      |        |         |                                   |
| Main wall inside               | 95                   | 13     |         | 1235                              |
| Crop walls both sides          | 4                    | 11     | 7       | 308                               |
| D <sup>o</sup> D <sup>o</sup>  | 2                    | 13     | 11-6    | 299                               |
| Pillar                         | 19-6                 | 8      |         | 156                               |
| Verandah Outside               | 13                   | 11     |         | 143                               |
| D <sup>o</sup> end walls       | 2                    | 9      | 9       | 162                               |
| Cornees Outside                | 107                  | 1-3    |         | 133-9                             |
| Total Square feet whitewashing |                      |        |         | 2436-9                            |
| Or Squares D <sup>o</sup>      |                      |        |         | 24 <sup>31</sup> / <sub>100</sub> |
| Colour washing Light Blue      |                      |        |         |                                   |
| Main Building Outside          | 110                  | 10-6   |         | 1155                              |

Verandah walls outside 2 9- 9- . 162- .  
 Total Square feet 1317- .

Deduct windows in main Building } 4 5- 4- " . 80- .

Total Square feet color washing 1237- .  
 Or Squares 12  $\frac{27}{100}$

Plastering Floor of Hall 31- 11- . 341- .

Rooms together 29- 8- . 232- .

Verandah 7- 12- . 84- .

Bath room floor 24- 5- . 120- .

Cracks in main & out Buildings 100- .

Total Square feet Plastering 877- .  
 Or Squares 8  $\frac{77}{100}$

Removing and repacking tiles with  $\frac{1}{8}$  New tiles and new chunnam borders

Main Building 61- 19- . 1159- .

Verandah 16- 10- . 160- .

Cookroom 44- 13- 6 594- .

Total square feet removing & repacking tiles with  $\frac{1}{8}$  New tiles 1913- .  
 Or Squares 19  $\frac{13}{100}$

Filling basement round bungalow with concrete and sloping it outward to keep the water from lodging about & soaking into the walls

100- . 3- . " 4  $\frac{1}{2}$  112- 6  
 Total cubic feet concrete 112- 6  
 Or Cubic yards 4  $\frac{4}{27}$

Filling crevices in bastion with concrete and pointing joints

Round Bungalow 124- 18- . 2232- .

Between main Building and Bathroom C. face 15- 11- . 165- .

Total Square feet of filling crevices 2397- .  
 Or Squares 23  $\frac{27}{100}$

Filling crevices with concrete and plastering } 36- 9- . 324- 6  
 C. face rampart under Bath room }  
 Do Do 10- 4- . 40- .

Total Square feet filling crevices &c 364- 6  
 Or Squares 3  $\frac{64}{100}$

Binding wall at top of roof of cookroom 2 44- 1- 6 1- 132- .

Total cubic feet Brick in chunnam 132- .  
 Or Cubic yards 5- .

Painting Windows of Bungalow both sides 4 5- 7- . 140- 6

Do frames of above 4 21- 9- . 63- 6

Front door of Bungalow 7- 7- 6 52- 6

Do frames 21- 9- . 15- 9

Total Square feet of green painting 271- 3  
 Or Squares of 2  $\frac{71}{100}$

W. Taylor Captain Engineer  
 No. 1 Range Bangalore

No 3797.

Superintendent's Office Chingleput  
Camp Sengaperoomaleenul  
10<sup>th</sup> February 1875  
Desd 12

From  
The Superintending Engineer  
Chingleput.

To  
The Secretary to Government  
Department Public Works.

Sir,  
I have the honor to submit  
for the sanction of Government and  
for an allotment of funds an Estimate  
for the repairs of the Overseer's  
Bungalow at Sengaperoomaleenul  
Taluk amounting to Rs 200; or more  
than  $\frac{1}{2}$  of the value of the building,  
by Rs 75.

2 This building was once a  
Traveller's Bungalow and was made  
over to this Department in November  
1865. It has been occupied as an office  
and residence by the Overseer in charge  
of the Sengaperoomaleenul Taluk since 1872. on a  
monthly rent of Rs 3-8-0. It has  
not been repaired for many years and  
consequently is in very bad order. It  
was severely tried by the Cyclone of May  
1872 and the subsequent storms. The  
roofs of the building and outhouses  
are very leaky, and walls are  
cracked; the basement round the  
bungalow requires to be concreted

No 3532  
22<sup>nd</sup> Nov/65

Enclosure,  
Estimate

From

The Officer in Charge

No 18 Range Chingleput Dist.

To The District Engineer

Chingleput District

Estimate No 9 1875-76

Estimated and abstract

Contract Chingleput

Taluk Sengaperoomaleenul

Village Sengaperoomaleenul

For Repairing the old  
Traveller's Bungalow  
at Sengaperoomaleenul

The Deputy District Engineer  
3797. desd 12<sup>th</sup> Feb/75

Estimate No 200  
1875-76



Govt. of Israel  
Jerusalem

PUBLIC WORKS.

70 The bookkeeper  
Chicago, Ill.

Hand  
G O 1 near 1875 A 2 587

NO. 91-22.

Quoted to me  
at the time - Chm.  
about \$7 estimate  
of \$2.200 for the re  
pairing of the  
dam - ~~the~~ with amount  
regarding the provision of  
funds for the work.

P<sup>r</sup> W 1875 Del<sup>d</sup>  
 Mrs J. G. Smith  
 No. 973  
 The Department of Agriculture  
 Wash. D.C.  
 Dr, Mr Secretary  
 The Secretary of the  
 P. M. Dept  
 No. 3747

No. 3747

Dist 10  
Dec'd 10 } Feb 1875

11-1-11

du et de l'homme  
-marche en l'homme

for the Relief of the

Wardens' Discharge

at the office for

at the expense of

John J. Drake

Wm. Lloyd Garrison  
Care of Mr. West

2-2-3-2-2

ring

581  
The estimate amounting to \$2000  
for repairing the Overland Runsgallop  
pat. (Engines) is estimated at \$2000  
day Engineer will provide the necessary  
-any work from the Government  
Bridget ground for 1895-96 under separate

Walt

31-32

616-2-75