

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	859.G.	Press	<i>Original</i>
B.P. No.		Mis.	
Dated	31-3-	1875	
		195	

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
31st March 1875.*

No. 678. Read the following letter from Lieutenant-Colonel R. A. ROBERTS, R E, Superintending Engineer, Tanjore, to Colonel G. W. WALKER, R E., Secretary to Government, Public Works Department, dated Tanjore, 23rd March 1875, No 3,425 :—

UNDER paragraph 102, Chapter V., of the Public Works Code, I have the honor to forward, for the sanction of Government, an estimate of Rupees 150 for repairing the Post Office at Mienbussel in the Puttoocottah Taluq of the 5th range of this district, as the estimated amount exceeds one fourth the value* of the building.

1 Estimate of Rupees 150
1 Specification

* Rupees 360-14-10.

2. Provision is made in the estimate for replastering, where necessary, the walls of the building, taking up and relaying the roof, which leaks badly owing to the decayed condition of the wood-work, and for constructing a floor of brick on edge in chunam. The existing floor being entirely of mud, becomes very damp after rain.

3. As there is a sum of Rupees 70 available in the current year's budget under "Repairs, Civil Buildings, Imperial," I have authorized the Supervisor to undertake the work in anticipation of the sanction of the above estimate.

No. 679. ORDER THEREON, 31st March 1875, No. 859-G.

CIVIL WORKS, No. 44.

SANCTIONED, the sum of Rupees 70 being expended as proposed in 1874-75, and the balance Rupees 80 in 1875-76.

(True Extract)

(Signed) G. W. WALKER, Colonel, R.E.,
Secretary to Government.

To the Superintending Engineer, Tanjore,
.. Controller of Public Works Accounts.

Exd S T Austin.
Spare Copies

with one coat of rough plaster and one coat of fine plaster

Specification

To accompany Estimate for Repairing the Post office at Mumbasole in Puthosethah Taluq of No 5 Range Tanjore District.

Amount of Estimate Rupees (150) one hundred and fifty as per Estimate accompanying, and consisting of the following items, Viz

Brick chimneys	Rs 32 - 4 - 0
Repairing Roof	88 - 3 - 2
Plastering	11 - 4 - 0
Wood work in window shutter	1 - 8 - 0
do in door	2 - 8 - 0
Lock and Key	1 - 0 - 0
Wood work in posts	3 - 8 - 0
Sundries and contingencies	8 - 12 - 7

Total Rupees 150

1 The present mud flooring is to be removed and replaced with brick on edge in chunam to a depth of 6 inches. The floor will be laid with the best country made bricks in chunam of two parts of sand to one of lime.

2 The roof is a simple Malabar truss and will be repaired with half new Pambles and one fourth new Palmyrat rafters & supports with new nails and chunam borders complete.

3 The building throughout is to be repaired with one coat of rough plaster and one

fine plaster and made up of the ordinary lime procurable in the neighbourhood.

4 The Door, shutter, and Verandah Posts, are to be of the best country wood.

5 The lock and key to be of the ordinary pattern.

6 This Estimate includes all necessary repairs and it is confidently expected that no supplemental works will hereafter be required.

Camp Kordachery
15 December 74

C. Littlewood
Superior in charge No 5 Range.

Note. The Build is to be colour washed inside and out with a pale buff colour as per Standard Specification, with a margin of 6 inches of white round the doors & windows. Not

J. Veggak R. S. C.
Executive Engineer in charge
Supr Engrs office Tanjore.

Supr Engrs office
Camp Kordachery
29 January 1875

Revised
Supr Engrs office
Cuddalore.

11/2/75

Building : Tanjore District : Repairs
No 5 or Manargoodly Range
Pulloorcollal Taluk
Detailed and abstract Estimate No. of 1874/75
Repairing the Post office Building at
Mimbasal.

Measurement	Particulars of work	Rate per amount
13 ft 4 in	Brickwork	
12 ft 1/2 in	Flooring to room	
4 ft 1/2 in	to Verandah	
4 ft 1/2 in	to Sides	
1 1/2 ft 1/2 in	Underpinning near walls inside above basement	
17 3/4 ft	Rebuilding wall on top on account of placing new rafters	
20 1/2 ft	left of Brickchimney (2) - 26 ft 32 in	
16	Repair to Roof	
16	Front portion	
10 1/2	Rear (2)	
16	Sides (2)	
882	8 1/2 ft Repairing roof with half the quantity of new tiles & 1/4 the quantity of Palmarah rafters & supports	
10	complete	88 3/2
20 1/4	Plastering	
90	Portion of front & rear walls of room inside above floor level	
20 13/4	do do on top	
12 1/4	do Sidewalls of room inside	

23 13/4 . 40/4 On front wall of room outside
 above floor level.
 2 13/4 13/4 . 47/4 On sidewall of room outside side
 2 4/2 2 . 18 Portico of end wall of Veranda
 32 3 . 96 Portico of rear wall outside
 above basement
 26 1/4 . 32 1/2 Cornices in rear.
 448 " 1/2 sq of plastering - course 2 & 3 . 11 1/2
 1 Shutter complete for the window and
 south side } 1 8 . each 1 8 "
 1 On On for the Corridor . 3 8 . 2 8 "
 1 Paddock and key for 1 . 1 "
 2 Country made "nails for Veranda
 5 1/2 ft long 7 1/2 diameter } 1 12 . 2 8 "
 141 3 5
 8 17 1/2
 Sundries etc . 8 17 1/2

Total Estimated Expense 150 - -

Estimate prepared by
 Sub-Commissioner

7 December 1874

J. Pittendrigh
 Supervisor, Bangalore District Range.

Supd. Office
 Bangalore
 29 January 1875.

Messrs. A. & Co.
 Contractors, Bangalore.
 Supd. Office, Bangalore.

M. S. S. S.
 Inspector of Public Works
 Bangalore

No. 3425. Supt Engineer's Office
 Bangalore 23rd March 1895

From Lieut Col R. H. Roberts R.E.
 Supt Engineer - Mysore

To Colonel C. W. Walker R.E.
 Secretary to Govt P.W.D.

Sir, Under para 102, Chapter V
 of the P.W. Code, I have the honor
 to forward, for the sanction of
 Government, an Estimate of Rs 100
 for repairing the Post Office at
 Aliambussu in the Puttur Taluk
 Taluk of the 5th Range of this
 District, as the estimated
 amount exceeds one fourth the
 value of the Building.

Provision is made in the
 Estimate for replastering where
 necessary the walls of the
 Building, taking up and relaying
 the roof which leaks badly
 owing to the decayed condition
 of the woodwork, and for painting
 a floor of brick on edge in
 the existing floor being entirely
 of mud, becomes very damp
 after rain.

For repairs to
 80 ft or more
 of the building
 estimated to
 be 100 ft
 of the building
 estimated to
 be 100 ft

Preparatory to
 office building
 estimated to
 be 100 ft

Estimated Rs 150

Technical and specific
 estimate for repairing
 the Post Office at
 Aliambussu.

100-2001/15
 2/15

1895
 Secretary to Govt
 P.W.D.

12678-677

As there is a sum of
Rs 70 available in the current
years Budget under "Repairs
Civil Buildings, Imperial" I
have authorized the Supervisor
to undertake the work in anti-
cipation of the sanction of the
above Estimate.

I have the honor to be

Yours most obedt Servant

Wm. N. N. N.
Superintendent

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-7-75

15-

7001
Govt. of Madras.

PUBLIC WORKS.

Sept 18 1875

Order

31 March 1876

648. 649.

Post Office at Meer-

hasseel, Tanjore St

Ref. for a pair of the

have been with remarks.