

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	1514	(W)	Press
B.P. No.			Mis.
Dated	19-6-		1876

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
19th June 1876.*

Read the following papers :—

No. 299. Proceedings of the Madras Government in the Ecclesiastical Department, dated 21st April 1876, No. 108 :—

ABSTRACT.—*Cemeteries*.—Estimate, amounting to Rupees 944, for raising and repairing the cemetery wall at Jagannaikpur, Godavery District, sanctioned.

No. 299-A. From the Executive Engineer in charge of Godavery District, dated Camp at Dowlaishweram, 8th June 1876, No. 684.

No. 300. ORDER THEREON, 19th June 1876, No. 1,514.

CIVIL WORKS, No. 47.

COMMUNICATED to the District Engineer, Godavery, who will provide funds from the grant at his disposal under Repairs, Civil Buildings, Provincial.

2. The sanction accorded in the above Proceedings has been registered as Provincial No. 69 W. of 1876-77.

(True Extract.)

Colonel,
Offg. Under Secy. to Govt., P.W.D.

To the District Engineer, Godavery.
„ Examiner of Public Works Accounts.
„ Ecclesiastical Department.

Exd. A. Grubert.
Spare Copies

Ch 308
Retired 3.5.76

No 17/138 of 5 May 1876

Wale No. of 1875-76

MEMORANDUM.

Letter Number 24

dated the 3 April 1876

from the District Engineer of the Eastern
to the Honorable Commissioners
of Madras.

With reference to the letter
forwarded with the letter
above quoted the D.E.
with the regard as to report
on the cause of the

Rates in the District
being in excess of those
of the District Schedule
by the amount stated below

For P.K. in Madras - 0-0-10

- Plantain & Cash
Yellow - 8-12-0

- White & Cash
2000 } 0-0-0

By order

W. J.

Detailed Estimate of 1875-76

Godanery Eastern Delta

Work Repairing the Compound Wall of Cemetery at Jagannikpoor

Particulars	Measurement			Contents
	Length	Breadth	Depth	
Repairing existing Coping of Compound Wall	178	1 1/2	1/2	133 1/2
	192	1 1/2	1/2	144
	358	1 1/2	1/2	268 1/2
	189	1	1/2	94 1/2
	189	1	1/2	94 1/2
	344	1	1/2	172
			cft.	907 1/2
Leys Repairing old masonry				33 1/2
Raising the wall 2 ft high	370	1 1/2	2	1110
	358	1 1/2	2	1074
or pilasters	60	1 1/2	1 1/2	270
or wall between pilasters	2	165	1	660
or	302	1	2	604
Coping to do	728	1 1/4	1	910
or	60	1 1/2	1 1/4	112 1/2
or	2	165	1	330
or	302	1	1	302
			cft.	5372 1/2
Leys Brick in mud				199
Plastering				
Inside of wall on East Side	358	3		1074
or of do do North Side	178	3		534
or of do do South Side	192	3		576
Plastering the raised portion of wall	2	728	3	4368
				6552

Abstract Estimate

Plastering pilasters 60 1 1/2 6 540 5 1/2 1875

Do walls between pilasters 2 165 5 1/2 1875

Do - - - - - 302 5 1/2 1661

Total 10569

Squares Plastering with 1 coat of Chumam Whitewashing

Wall on west side 2 354 7 4956

Do on north side 2 367 7 5138

Do on east side 2 358 6 4296

Do on south side 2 379 6 4927

Gate Pillars 4 7 5 1/2 154

Lombs 200 20031

Squares whitewashing with 2 coats of Chumam

Painting the gates and contingencies at 7 1/2 per cent

Total 20031

20031

Work - Repairing the Compound walls of Cemetery at Jagannathpur

Quantity Description of work Per Rate Amount Total

33 16 27 Cypso Reowning the Compound walling 8 16 1291

177 Do - Brick in road do 2 12 5474

10568 Sqr Plastering with 1 coat of Chumam Sqr 2 3 26432

20031 whitewashing with 2 coats of Chumam do 4 4 5013

87852

Painting the gates and contingencies out 8 651010 944

Northern Sub-Office

Camp Mammur

24 September 1875

Attest
Superior or in charge
H. S. S. S. S.

L. P. Scatty - Major & Chancellor
Offr Supr Engineer Corps 26/9/75

W. M. Babington
(Chaplain)

SP No 125
 From, The Officer in charge Eastern D.D.
 Godavery District

To, The District Engineer
 Godavery District

Dated 3
 Recd 6 } June 1876.
 Encl.

Dist. Eng^r No 503 dated 29 May 1876.

Has the honor to state that the rates in the estimate for raising the wall of the Cemetery at Jagannaikpuram include the additional cost of carriage which is not provided in the Schedule of rates & hence the excess is as follows:-

For brick in mud Rs -10- per Cyp.
 " Plastering 1 Coat } " -2- per Square
 of chunam }
 Whitewashing 2 coats " -a-b- do -

2. The original Memo No 138 dated 5th ultimo
 from

P. No 3064/76

Estimated No. of 1875-76
 Budget No. 2 - Provincial
 Public Works Department.
 Civil Building.
 District of N. & S. Mysore
 The Commission of the
 Cemetery at Jagannaikpuram
 Estimate for Repairing
 the Compound Wall of
 Jagannaikpuram
 amounting to Rs 944

amounting to Rs 944.

Recd 26th September 1876

The Assistant Engineer
 in charge N. & S. Mysore

The District Engineer
 N. & S. Mysore

1 Recd 1-10-76

1 Recd 1-10-76

from the D4. Chief Engineer is herewith
returned as requested.

/s/ D. W. Neil Campbell L. E.
Executive Engineer.

(True Copy)
J. M. W. Campbell Lieut. R.E.
Executive Engineer in charge God. D.

P. N. 4243/76

Proceedings of the Madras Government, Ecclesiastical Department,
21st April 1876.

Cemeteries.

No. 24. Read the following letter from the Venerable C. R. DRURY, M.A., Archdeacon of Madras, to the Hon. W. HUDLESTON, Chief Secretary to Government, Fort Saint George, dated Madras, 11th April 1875, No. 395:—

I have the honor to forward a letter and estimate from the Officiating Superintending Engineer of the Godavery District, in reference to G.O., Ecclesiastical Department, dated 31st January 1876, No. 21, stating that the compound wall of the Jagannaikpur Cemetery is composed of rough stone in mud, and that wood or iron cannot therefore be fixed upon it.

From Major J. BEATTY, R.E., District Engineer of the Godavery District, to the Venerable C. R. DRURY, M.A., Archdeacon of Madras, dated Dowlaishweram, 3rd April 1876, No. 24.

With reference to your letter of the 4th February 1876, and the Order of Government which accompanied it, I have the honor, in retransmitting the estimate for raising the compound wall of the cemetery at Jagannaikpur, to inform you that it is not possible to erect railings on the wall because it is composed of rough stone in mud, and wood or iron standards cannot therefore be fixed upon it.

No. 25. ORDER THEREON, 21st April 1876, No. 103.

Under the circumstances stated by the District Engineer the estimate, amounting to Rupees 944, for raising and repairing the cemetery wall at Jagannaikpur, is sanctioned.

2. The necessary orders for the provision of funds and execution of work will be issued in the Public Works Department:

(True Extract.)

W. H. Hudleston
for Chief Secretary.

To the Venerable the Archdeacon.

- Collector of the Godavery District.
- Public Works Department, with estimate.
- Accountant-General.

Exd. J. Wright.

Comp
ms

1052

P. W. 1876 Department

No. 3064

Ch. Engr. No. 138 of 5 May
1876.

No. 299

Recd. at 17-1-11

No. 684

District Engineer's Office Gory
Camp Dowlaishwaram 8 June 1876.

From

Lieutenant D. M. Niel Campbell R.E.
Executive Engineer in charge Gory Dt.

To

Colonel W. Farewell
Offg. Dy. Chief Engineer D. P. W.
Madras.

Sir,

I have the honor to forward here
with a copy of a letter from the Officer
in charge of Eastern Delta Division by
which you will see that the excess in
rates referred to by you is owing to the
extra distance the materials had to
be carried.

I have the honor to be,
Sir,

Your most obedient Servant
D. M. Niel Campbell Lieut R.E.
Executive Engineer in charge G. Dt.

Comp
Pass

S. H. 1876 Department

88-1243

No 1514

Public Works Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the 19th June 1876.
Read the following:—

Pro. Madras Government.
Ecclesiastical Department } (H.C. No 108 of 21 April 1876)
Executive Engineers in charge
Godavery Dist. } (G.O. No 684 of 8 June 1876)

Communicated
to the District Engineer,
Godavery, who will
provide funds from
the Grant at his dis-
posal under Repairs
Civil Buildings, Provincial
Providence.

10.6.76.

The sanction accorded
in the above Proceedings
has been registered as
Provincial No 684 of
1876-77.

J. Godavery
Secy to Secy
Ecclesiastical Dept
Dated 17/7/76

From

The Executive Engineer
in charge Godavery Dist.

To the District Engineer
Godavery Dist.

Dated 8th June 1876,
Received 14th June 1876,

No 604

Encls: one

Government
Compendium of the
Country etc. Inform that
the cause of excess of rates
in the Godavery for no is
owing to extra distance the
materials had to be carried.

76-9-11-1876

1299a

3064
4243

Govt. of Madras

PUBLIC WORKS.

The D. & Godavery

19 June 1874

No. 299-300

Cemetery wall at Sagan-
naikpur - Godavery D.

Pro: in the Ecclesiastical
Dept^y sanctioning an Estimate
of Rs. 944 for raising &
repairing the ———— and
to the D^y Engineer

W. P. S. S. S.
27-7-76

11-11-76