

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works

DEPARTMENT

G.O. No.	1702	Press	<i>Original</i>
B.P. No.		Mis.	
Dated	5. 7.	195	18/6

Not to be folded or roughly handled

Read the following :—

No. 60 W.

No. 75. *Note by the Chief Engineer for Irrigation.*

THE Officiating District Engineer, Tinnevelly, forwards, with his letter marginally
No. 21, dated 24th April 1876. noted, an estimate in connection with the
Ninarcolum tank situated in the Tinnevelly
Taluk, Tinnevelly Range.

2. The nature of the work proposed for execution and the heads of account to
which it is chargeable are as follow :—

Removing the existing calingulah and reconstructing a weir	Rs.
in its stead. Ordinary Agricultural—Original Works.	1,340
Raising and repairing the bund where necessary. Ordinary	
Agricultural—Repairs	260
Total ...	1,600

3. The following particulars of this tank are recorded :—

Ayacut area	Acres 632
Assessment	...
Average revenue	Not given.
Highest do.	Do.
Expenditure during the previous four years ...	Rupees 605.

The area of the catchment basin is .5 square miles ; the maximum flood supply is
calculated at 1,150 cubic feet per second, for discharging which as surplus there is a
calingulah 113 feet in length, effective 40 feet.

It is proposed to replace the calingulah by a weir 117 feet in length, as the
former is very old and irregular, and the repairs would cost nearly as much as to
construct the weir. The particulars of assessment, average revenue, &c., are not stated.
It will be necessary to return estimates which do not give information which is so
important.

OOTACAMUND,
22nd May 1876.

(Signed) A. DEC. SCOTT, Major, R.E.,
Depy. Chief Engineer for Irrigation,
for Chief Engineer for Irrigation.

Proceedings of the Madras Government, Public Works Department,
5th July 1876. No. 1,702.

No. 76. ORDER THEREON, 5th July 1876, No. 1,702.

IRRIGATION No. 6.
Account.

THE following estimate from the Tinnevelly Range, forwarded by the Officiating District Engineer, Tinnevelly, is sanctioned :—

NINARCOLUM TANK.

Irrigation.

Group or Project.	Fund.	Class.	Particulars of Work.	Amount.
Tambrapurny Irrigation.	Ordinary Agricultural.	Original Works.	1. Reconstructing the escape of the Ninarcolum tank ...	RS. 1,340
Tinnevelly Section.	Do.	Repairs.	2. Repairing the bund of the Ninarcolum tank	260

To be carried out by the Public Works Department Officer in charge, Tinnevelly Range.

2. This sanction has been registered as No. 57 I. of 1876-77.

(True Extract.)

Colonel,

Offg. Under Secy. to Govt., P.W.D.

To the District Engineer, Tinnevelly.
„ Collector of Tinnevelly.
„ Chief Engineer for Irrigation.
„ Examiner of Public Works Accounts.
„ Revenue Department.

Exd. A. Grubert.

Spare Copies

E. I. Form No. 9.

OFFICE OF THE CHIEF ENGINEER
FOR IRRIGATION,

22nd May 1876.

No. 60-W.

Note by Chief Engineer for Irrigation.

THE Offg. District Engineer, Tinnevelly forwards, with his letter marginally noted, an Estimate in connection

No. 21
Dated 24th April 1876
Enclos. 5
with the Ninarcolum Tank situated in the Tinnevelly Taluq, Tinnevelly Range.

2. The nature of the work proposed for execution and the heads of account to which it is chargeable are as follow :—

Removing the existing Kalingulak and reconstructing a weir in its stead—	} — Rupees 1340
Revenue Repairs.	
Raising and repairing the bund where necessary— Revenue Repairs—	} — 260
Total Rupees 1600	

3. The following particulars of this Tank are recorded—

Ayacut area. 632 Acres
Assessment. —
Average revenue. Not given
Highest do. —
Expenditure during the previous four years. 605 Rupees

The area of the catchment basin is .5 square miles; the maximum flood supply is calculated at 1150 cubic feet per second for discharging which, as surplus there is a Kalingulah 113 feet in length, effective 40 feet.

It is proposed to replace the Kalingulah by a weir 117 feet in length as the former is very old and irregular and the repairs would cost nearly as much as to construct the latter Weir. The particulars of the proposed coverage revenue so. are not stated. It will be necessary to return estimates which do not give information if it is so important. *Chief Scott.* Major R.E.

*Deputy Chief Engineer for Irrigation
for Chief Engineer for Irrigation*

E. I. Form No. 4.

No 1702
Public Works Dept.
Proceedings of the Madras Government
Under date the 5 July/76.
Read the following

Note by the Chief Engineer for Irrigation
No 60 W. of 22nd May 1876.

The following Estimate from the *Tinnevely* Range forwarded by the District Engineer, *Tinnevely*, is sanctioned:—

Tank.

Kinarcolam

Irrigation.

Group or Project	Fund	Class	Particulars of Work.	Amount Rs.
<i>Tambrapurny Irrigation Tinnevely Section</i>		<i>Ordinary Agricultural</i>	<i>Reconstructing the escape of the Kinarcolam Tank.</i>	<i>1,340</i>
			<i>Repairing the bund of the Kinarcolam Tank —</i>	<i>260</i>

To be carried out by the P.W. Department Officer in charge Tinnevely Range.

Sd/- Tinnevely
Collection - dy. H.
C. R. for 1 with 5 Enclot ✓
Ex. P. W. D.
Heads of
2. This sanction has been registered as No. *57*. I. of 1876 -77.

Despatched by July 27/76

Recd

FORNKE CASES.

No. of 187 .

Issue Case.

I. E. Form No. 31.

P. W. 1876. Department
from *8-1-850*
Chief Engineer for Irrigation.

RECEIPT No. *2677*

Dated *28 April* 1876.

dated 22-5-76
Received 7-7-76

8-60 W.

Issue No.

Dated

LATER CASES.

No. of 187 .

Subject:—
Ninarcolum Tank.
Tinnevely District. Sub.
mits estimates amty.
to Rs. 1600 for repairs
to the

Sent to Government with No.

W. of

18

Printed with G. O. No.

dated

ENCLOSURES.

1876 letter No. 21 of 21, 21/7/76
3 plans. do.
1 Sheet Report, with photograph of tank.
Report, & 2 letters to the Secy.

REMINDERS ISSUED.

No. 1, dated	187 .
" 2, "	"
" 3, "	"
" 4, "	"
" 5, "	"

1275-76

KEEP-WITHS.

Aug 7-76 Mtd 5-7-76
P. R. Sheet 52 June

4850 M.

Govt. of 1876 Madras
PUBLIC WORKS.

To

Mr. H. G. Limerick

Dated

Issued

Recd

Encl.

G. O., #5 July 1876, No. 1702

Nos. 75-76

Ninacolum Tank

Sinnivelly District

Estimate of Rs.

1600 for certain repairs

yet to be ————

Est. no. 112
29-7-76