

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works

DEPARTMENT

G.O. No.	1910	Press
B.P. No.		Mis.
Dated	27 - 7 -	195
		6876

Not to be folded or roughly handled

No. 34
Mangalore 17th July 1874
The District Engineer
South Canara
The Secretary to Government
S. P. W. Madras.

Sir,
I have the honor to report for the information of Government that a second case has occurred in this District of a bridge suffering destruction by the roots of a tree entering the masonry.

2. The first case was reported by me to the Offg. District Engineer in letter No. 226 of 2nd December 1873 and is that referred to in G. O. No. 78 of 13th January 1874.

3. In the present instance a Peepul tree situated 11 yards from the Elmoodi Bridge on the Mangalore and Moreara road, has thrown out a root of 3 in diameter that has cracked the bridge in a manner similar to that in the previously reported case.

4. On this coast nothing short of the uprootal of all trees, that possess lateral roots, growing within 50 yards of bridges, will save further destruction of this sort,

3013-1-74 No 78.

P. W. 1876 Dept
No 5179

No 1910

Public Works Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the 29th July/76.
Read the following:—

From
The District Engineer
South Canara } (H.C. No 34 of 17th July/76)

Communicated
with G.O. No. 78 of 13th
January 1874 to the
Financial Department
for information of all
local Fund Boards.

From
The District Engineer
South Canara
To
The District Engineer
South Canara
No. 2143 of 17th July 1876
By
Order of
The District Engineer
South Canara
Respecting the
matter of the
Government
No. 2143 of 17th July 1876
By
Order of
The District Engineer
South Canara
Respecting the
matter of the
Government
No. 2143 of 17th July 1876
By
Order of
The District Engineer
South Canara

No 468

All District Engineers
Finl. Dept. with G.O. No 78 of 13-1-74
Chief 10-5-76

Recd - 28.7.76 P.W. 27.7.76
Dec 2 to 21-7-76

N^o 51795

Govt. of 1870

PUBLIC WORKS.

M. J. C. Lopez
Jill.

1870

1871

1872

U. S. G. O. 1870

Nov. 21/70

Intd. in Reg. 11-2-71

Section of a bridge -
Repairing masonry on a bridge
from the S. E. South
Canal, repairing a
second case of, by the
roots of a tree entering
the masonry -