

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No. 2106 (w) Press
B.P. No. Mis.

Dated 14-8-1876.

Not to be folded or roughly handled

Read the following letters :—

No. 310. From Captain R. R. E. BROCKMAN, R.E., District Engineer, Tanjore, to Major-General G. W. WALKER, R.E., Secretary to Government, Public Works Department, dated Tanjore, 19th June 1876, No. 1,124.

In reference to G.O., No. 209, dated 29th April 1876, I have the honor to forward, for the sanction of Government, the enclosed estimate amounting to Rupees 250 for the repair of the S.P.G. Mission Church at Tanjore, prepared in communication with the Minister in charge. The amount of the estimate may be met from the allotment in the current year's budget, Provincial, on account of "Repairs to Civil Buildings."

2. I request instructions as to whether the work is to be carried out by this department or by the Mission Agency, the amount of the estimate being paid to the Minister in charge. The latter course was followed when repairs were last carried out to the Church, and towards which the Government sanctioned a grant-in-aid of Rupees 250 in G.O., No. 907, dated 21st March 1866.

No. 310-A. From Captain R. R. E. BROCKMAN, R.E., District Engineer, Tanjore, to Colonel W. T. F. FAREWELL, Officiating Deputy Chief Engineer, Public Works Department, dated Tanjore, 2nd August 1876, No. 1,439.

In reference to your memorandum, No. 463-P, dated 27th June 1876, requiring explanation as to the apparently high rates charged in the estimate for repairing the S.P.G. Mission Church at Tanjore for painting and for scaffolding and sundries, I have the honor to submit the explanation furnished by the Range Officer, as follows :—

2. The rate charged for painting is said to be necessary on account of the small quantity of the work to be done. The rates entered in the district schedule would appear to be those ruling where the quantity of work to be done is large, the rates increasing proportionally as the quantity of work to be done is small.

3. The charge on account of scaffolding and sundries, *viz.*, Rupees 46-1-2 is divided into Rupees 30 for scaffolding and Rupees 16-1-2 for sundries. It is considered necessary that sufficient scaffolding requiring at least 100 bamboos at 20 or 25 Rupees should be put up at one time for the efficient carrying out of the work and to prevent cutwashes in putting on the colored wash. Rupees 30 for this item would therefore appear to be not too much. Rupees 16-1-2 are said to be required for sundries to admit of the walls, &c., of the building being thoroughly cleaned and scraped before the fresh coat of wash is applied. Lieutenant Smart observes that, though taken as a percentage on the estimate, the charges for these items appear large; they are actually not so.

4. With the above explanation I beg to resubmit the estimate, which I trust may be passed.

Proceedings of the Madras Government, Public Works Department,
14th August 1876. No. 2,106.

No. 311. ORDER THEREON, 14th August 1876, No. 2,106.

CIVIL WORKS, No. 29.

(a) Heads of Service.—Provincial.

Fund.—Ordinary.

Class.—Repairs.

Main-head.—Civil Buildings.

Sub-head.—K. Ecclesiastical Department.

Section.—I, Churches.

Name of Work.—Repairing English Church at

Tanjore.

Amount.—Rupees 250.

To be carried out by the Public Works Department.

THE estimate of Rupees 250 for repairing the English Church at Tanjore is sanctioned. Funds will be provided as pointed out in the 1st paragraph of letter No. 1,124 of 19th June 1876 from the District Engineer, and the work carried out by the Public Works Department.

2. The sanction accorded in these Proceedings has been registered as Provincial No. 105-W of 1876-77.

(True Extract.)

Colonel,

Offg. Under Secy. to Govt., P.W.D.

To the District Engineer, Tanjore.

„ Examiner of Public Works Accounts.

„ Ecclesiastical Department.

Exd. E. O. Shunker.

Spare Copies

Provincial
Tanjore District
No 105 Tanjore Range
Tanjore Taluque
Repairs

Civil Buildings Ecclesiastical Department
Churches

Work Repairing the English Church at Tanjore
Estimate No. I. J. of P. W. D. No. 250

Quantity	Description	Rate	Per Amount
5360	Speck of Exterior Colored washing	at 4	Rs 13 6 4
6700	Do Interior whitewashing	at 3	Rs 12 9
4343	Do Painting 2 coats cements paint	at 3 8	Rs 152
865 1/2	Do Varnishing	at 3	Rs 25 15 6
			203 16 10

Scaffolding & Sundries 48 1 2
Total Estimate Rupees 250

No 1 Range office
Tanjore 8 June 76

Signed, A. W. Smart Lt. R. E.
Assistant Engineer for Range

Signed, James F. Fearns
Offg. Chaplain

District Engg. office
Tanjore 19 June 1876

Per J. S. Murray Esq. R. E.
District Engineer Tanjore

Chas. H. 183
copy 26/6
163-27 June/16
MEMORANDUM.

Letter Number *243 1124*
 dated the *26/6/16*
 from the District Engineer of *Bagmati*

The District Engineer has been informed that the following items have been received from the District Engineer of Bagmati:
1. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.
2. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.

3. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.
4. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.
5. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.
6. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.
7. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.
8. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.
9. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.
10. A letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.

5593
P. H. 4423/46

Concluded in the letter from the District Engineer of Bagmati dated 26/6/16, regarding the work done on the Bagmati River, and the work done on the Bagmati River, and the work done on the Bagmati River.

Receiving the English Branch of the Bagmati.

District Engineer's Office
 San Jose 19th June 1876

Captain W. R. E. Brockman R.E.
District Engineer, Sanjona

Major General G. W. Walker R.E.
Secretary to Government.
D. P. W.

In reference to G. O. No. 209 dated 29th April 1876 I have the honor to forward for the sanction of Government, the enclosed estimate amounting to Rs. 250 for the repair of the S. P. G. Mission Church at Tanjore, prepared in communication with the Minister in charge. The amount of the Estimate may be met from the allotment in the current year's Budget, Provincial, on account of "Repairs to Civil Buildings".

2 I request instructions as to whether the work is to be carried out by this Department or by the Mission Agency, the amount of the Estimate being paid to the Minister in charge. The latter course was followed when repairs were last carried out to the

Church

Church and towards which the
Government sanctioned a grant
- in - aid of Rs 250 in Feb. 1907
dated 2nd March 1906.

I have the honor to be

Yr
Your most obedient servant

Mellorham Captain R.E.

District Engineer Tanjore.

270 4483

Am 2. 11.

Public Works Department.

Fund.

Class.

Main-head.

Sub-head.

11000

Name of Work.

Amount. *242.00*

To be carried out by the P. W. Department.

Print in the margin of G.O. N. 21060 of 14-8-76-

1860 will amount to \$637.27 1/2
 toward the same then
 an estimate of \$175.250
 for the repair of the
 N. E. E. Ch. door
 almost at naught

No 1124
Endowment Socy

Paid 19: 2
 Received 25: 2
 June 13/76

From,
The President Engineer
Tampine
to, The Secretary to Govt.
P. O. R.
Malacca.

C. E. No. $\frac{2}{463}$ of 27th June 1876.

au - 11.8.76 P.T. 14.8.76
 Despatched to Colly 8-8-76

8. 4. 1876 10.

No 2106

Public Works Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the 14th Aug 76

Read the following:—

From
The Dist Engr Sanyal - (H.E. No. 1124 of 19th June 76)
" Do Do Do (" " 1439 of 2nd Aug 76)

The estimate of Rs 250 for repairing the English Church at Sanyal is sanctioned. Funds will be provided as provided out in the first para of letter No. 1124 of 19th June 76 from the District Engineer and the work carried out by the Public Works Department.

2. The sanction accorded in these proceedings

Dist Engr Sanyal has been registered as
By an M. M. M. Provincial Govt of 18/6/76
Ecclesiastical Dept.

17
Disd 19/8/76

Cd - 11-0
Desd to Govt 8-8-76

5599
4483

GOVT. OF HONG KONG
PUBLIC WORKS.

Mr. A. G. Langford

17/11

14" deep - 2106

No 210-211

English Church at
Tanjore - Estimate of
No 250 for repairing
the ———— covered

20/11/11