

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	2137	Press
B.P. No.		Mis. —
Dated	16. 8. 195	C876

Not to be folded or roughly handled

Read the following :—

No. 134-W.

No. 370. *Note by the Chief Engineer for Irrigation.*

THE District Engineer, South Arcot, forwards, with his letter marginally noted, estimate in connection with the Spring Pond and Thereovamoor Channel situated in the Cuddalore taluq, Cuddalore range.

2. The nature of the work proposed for execution and the heads of account to which it is chargeable are as follow :—

ORDINARY AGRICULTURAL.

Repairs.

Clearing the Spring Pond and a portion of the Channel...	...	...	rs. 190
Total ...			190

3. The following particulars of this tank are recorded :—

Ayacut area ...	...	...	...	...	...	...	...	Acrea	30
Assessment ...	...	...	...	...	...	...	...	Rupees	177
Average revenue ...	...	...	...	...	...	...	...	..	211
Highest do. ...	...	...	...	...	...	...	...	Not stated.	
Expenditure during the previous four years ...	...	...	...	...	...	...	...	Nil.	

4. The Spring Pond and Channel were seriously injured by the floods of 1874. The estimate provides for clearing the pond and deepening the channel to a distance of 700 feet up to the bed of the Malathaur river from where further clearing is unnecessary.

5. It is stated that the ryots have themselves done a considerable amount of work in repairing the damage, and that the Collector concurs in the opinion of the District Engineer that Government funds should be given in aid.

6. The estimate is recommended for sanction.

(Signed) A. DE C. SCOTT, Major, R.E.,

Deputy Chief Engineer for Irrigation,

for Chief Engineer for Irrigation.

OOTACAMUND,

9th August 1876.

To the Secretary to Government, Public Works Department.

Proceedings of the Madras Government, Public Works Department,
16th August 1876. No. 2,139.

No. 371.

Order numbers, 16th August 1876, No. 2,139.

IRRIGATION, No. 35.

Amount.

The following estimate from the
Cuddalore range, forwarded by the
District Engineer, South Arcot, is sanc-
tioned:—

IRRIGATION.

Group or Project	Kind	Class	Name of Tank, Canal, or Channel	Particulars of Work	Amount
Nil	Ordinary Agricultural	Repairs	Terrestrial Channel	Clearing the Spring Pond and a portion of the Channel	Rupies 190 To be carried out by the Public Works Depart- ment Officer in charge Cuddalore Range.

2. This sanction has been registered as No. 106-I. of 1876-77, and will be
considered Special.

(True Extract.)

Colonel,

Offg. Under Secy. to Govt., P.W.D.

To the District Engineer, South Arcot.
„ Collector of do.
„ Chief Engineer for Irrigation.
„ Examiner of Public Works Accounts.
„ Revenue Department.

Exd. E. C. Shunker.

Spare Copies

E. C. Form No. 4.

OFFICE OF THE CHIEF ENGINEER
FOR IRRIGATION,

19th August 1876.

No. 134-IV.

Note by Chief Engineer for Irrigation.

Serial 3 The District Engineer, South Arcot
forwards, with his letter marginally noted, Estimate in connection
No. 59. with the Spring pond & Terrestrial channel Tank situated in the
Dated 27th June 1876. Cuddalore Taluq, Cuddalore Range.

2. The nature of the work proposed for execution and the heads of account
to which it is chargeable are as follow:—

*Ordinary Agricultural
Repairs
Clearing the spring pond and a
portion of the channel Rupies 190
Total Rupies 190*

3. The following particulars of this Tank are recorded:—

Ayacut area. 30 acres
Assessment. 177 Rupies
Average revenue. 211 Rupies
Highest do. Not stated
Expenditure during the previous four years. Nil

The area of the catchment basin is square miles; the maximum flood supply is calculated at cubic feet per second for discharging which, as surplus there is

The spring pond and channel were seriously injured by the floods of 1874. The estimate provides for clearing the pond and deepening the channel to a distance of 700 feet up to the bed of the Malathaur river from where further clearing is unnecessary.

It is stated that the ryots have themselves done a considerable amount of work in repairing the damages and that the Collector concurs in the opinion of the District Engineer that Government funds should be given in aid.

The estimate is recommended for sanction.

W. S. S. S.

Majors R.

Sd/- Chief Engr. Farquhar
for Chief Engr. Farquhar

To the Secy. to Govt. of India

P.W.D.

1876

N. 1. 1. 1.

From

The Chief Engr. for Bangalore

Dated 9th August

Received

Rs. 13 1/2

Encl: 3. given to Amudunooli
Brook

State so a letter from the District Engr. for the district, submitting estimate for repairing the spring pond and channel of the Malathaur in the bed of Malathaur, and also Bangalore.

21

Issue No. _____
Dated _____

FAVOR CASES

No.	of 187
"	"

Sent to Government with No. _____ W. of _____

18 _____

Printed with G. O. No. _____ dated _____

REMINDERS ISSUED:

No. 1, dated	187
" 2, "	"
" 3, "	"
" 4, "	"
" 5, "	"

KEEP-UPPER

L. E. Form No. 31.

Chief Engineer for Navigation.

RECEIPT No. _____

Dated 12/12/1874

Subject: _____

Spring pond and Ther-
vador channel. South
brook st

WINGS OF THE FUTURE

3. *Carduus* *gemma*

Cui - 14.8.76 V. 16.8.76
 2. 14.8.76

Issue Case.

1874

E. f. Form No. 1

No. 2139 P. W. Dept.
Proceedings of the Madras Government
1870-71

Under date the 18 Aug/78.

Read the following

Note by the Chief Eng^r for Irrigation No 364
of 9th Augt 1876.

THE following Estimate from the *Guddalore* Range forwarded by the District Engineer, *South Arcot* is sanctioned :—

Irregularities

Group or Project	Fund Class	Name of Tank, Canal or Channel	Particulars of Work	Amount Rs.
		Ordinary Agricultural		
		Repairs.		
		Thosavannur Channel		
			Cleaning the Spring pond & a portion of the channel	190
			To be covered put by the Dist. Officer in charge Cuddalore Range	

2. This sanction has been registered as No. 106 L. of 1876-77. and will

S. G. S. Arch. has considered special
Collector - do
C. G. for S. G.
En. Plow, N. 1/2 1/2 1/2 1/2

5965

Coll. of 1870: Hydro.
PUBLIC WORKS.

The R. E. Southport

18th August 2189

270-370

Cleaning the spring pond
& a portion of the Thero:
Wander Channel
South West at Co
tunate for —
sandstone

South West
27-40