

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works

DEPARTMENT

G.O. No.	2163	Press
B.P. No.		-Mis-
Dated	18-8	1876
		195

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
18th August 1876. No 2,163*

Read the following —

No 138-W.

No 416 *Note by the Chief Engineer for Irrigation*

THE District Engineer, Cuddapah, forwards, with his letter marginally noted, an estimate in connection with the Budicherla Mahomed Bhai tank, situated in the Sidhout taluq, Sidhout range

2 The nature of the work proposed for execution and the heads of account to which it is chargeable are as follow —

ORDINARY AGRICULTURAL
Repairs

Repairing the sluice and weir	...	...	...	Rs
				270
Total				270

3. The following particulars of this tank are recorded —

Ayacut area	...	Acres 30	{ Circar	29
			{ Inam	1
Assessment	...	Rupees 126	{ Circar	124
			{ Inam	2
Average revenue	...	" 146	{ Circar	145
			{ Inam	1
Highest	"	" 223	{ Circar	222
			{ Inam	1
Expenditure during the previous four years				Nil

The area of the catchment basin is 2 square miles, the maximum flood supply is calculated at 840 cubic feet per second, for discharging which as surplus there is a weir 90 feet in length.

The head and tunnel of the sluice are reported to be in ruins, and the apron of the weir in bad order, owing to the damages it sustained during the heavy rains of 1874 The estimate provides for reconstruction in both cases. The length of weir is sufficient for the calculated supply.

OOTACAMUND,
15th August 1876

(Signed) A DEC SCOTT, Major, R E,
*Dy Chief Engineer for Irrigation,
for Chief Engineer for Irrigation.*

To the Secretary to Government, Public Works Department

No 417. ORDER THEREON, 18th August 1876, No 2,163

IRRIGATION. No 42,
<i>Account</i>

The following estimate from the Sidhout range, forwarded by the District Engineer, Cuddapah, is sanctioned. —

Budicherla Mahomed Bhai Tank.
IRRIGATION
ORDINARY AGRICULTURAL,
Repairs

Repairing the sluice and weir	..	..	...	...	...	Rs
						270
Total						270

Proceedings of the Madras Government, Public Works Department,
18th August 1876. No 2,163

2 This sanction has been registered as No 111-1 of 1876-77

(From Extract)

Colonel,
Offg Under Secy to Govt, P.W.D.

OFFICE OF THE CHIEF ENGINEER
FOR IRRIGATION,

Rotacamund 15th Aug 1876.

No 138-W.

Note by Chief Engineer for Irrigation

Encls 7

No 561

Dated 30 May
1876

THE *District* Engineer, *Luddapah*

forwards, with his letter marginally noted, an Estimate in connection
with the *Budichula Mahomed Chai* Tank situated in the
Sidhout Taluq, *Sidhout* Range.

2 The nature of the work proposed for execution and the heads of account
to which it is chargeable are as follow —

Ordinary Agricultural
Repairs

Repairing the sluice and weirs. Rs 270

Rupees 270

3 The following particulars of this Tank are recorded —

Ayacut area.	30 Acres	{ Clear 29 } Acres
Assessment.	126 Rupees	{ Clear 124 } Rs
Average revenue.	146 Rupees	{ Clear 145 } Rs
Highest do.	223 Rupees	{ Clear 222 } Rs
Expenditure during the previous four years	Nil	

The area of the catchment basin is 2 square miles, the maximum flood supply is calculated at 840 cubic feet per second for discharging which, as surplus there is a weir 90 feet in length

The head and tunnel of the sluice are reported to be in ruins and the apron of the weir in bad order owing to the damages it sustained during the heavy rains of 1874. The estimate provides for reconstruction in both cases. The length of weir is sufficient for the calculated supply.

Ans. S. C. S.

Major A. C.
Deputy Chief Engineer for Irrigation
for Chief Engineer for Irr.

To
The Secretary to Government
Public Works Department

C. S. S.

P.W.D.

21 AUG 76

No

From

The Chief Engineer for Irrigation

To

The Secretary to Govt
P. W. D.

Dated 15th } August 1976
Recd 15th }

Encls 7.

No 138-W

Budicherla Mahomed Bhan
Tank - Cuddapah District
Note forwarding for sanction
Estimate for Rs 270 for repairs
to the —.

No 416

E I Form No 4

No 2163

Mrd

Proceedings of the Madras Govt

Under date the 18 Aug 76.

Read the following

From the Chief Eng for Irrigation
No 138, W. D. 15 Aug 76

The following Estimate from the Budicherla Mahomed Bhan Tank
by the District Engineer, Cuddapah is sanctioned.—

Budicherla Mahomed Bhan Tank

Irrigation,

Ordinary Agricultural
Repairs

Repairing the sluice and weir. Rs 270

Total Rupees 270

2. This sanction has been registered as No III I. of 187 -7.

C. E. Cuddapah
Collection - do
C. E. for J. with Encls
for tank
Revised file
Dated 14/9/76

Amf
15-0
G.M.V.

Govt. of 1876 Madras.
PUBLIC WORKS.

2)

No. 16. Lund & Lapham

1944

June 2

Rec'd

...

G. O. 18th Sept 1950

215

NO. 416-47

Budicherla allahomab
Tshar Jank - Cuddapah

$\hat{D}_{ii}$ - Estimate for separation
the — sanctions of —

100