

(1) Number of pages \_\_\_\_\_

(2) Date of repair \_\_\_\_\_

(3) Initials of the Referencer \_\_\_\_\_

# MADRAS RECORD OFFICE

## Government of Madras

*Public Works*

DEPARTMENT

|          |       |       |                 |
|----------|-------|-------|-----------------|
| G.O. No. | 2349  | Press | <i>Original</i> |
| B.P. No. |       | Mis.  |                 |
| Dated    | 2. 9. | 1957  |                 |
|          |       | 1876  |                 |

Not to be folded or roughly handled

Read the following:—

No. 164-W.

No. 20. *Note by the Chief Engineer for Irrigation.*

THE District Engineer, Cuddapah, forwards, with his letter marginally noted, an estimate in connection with the Budicherla Venkata Krishnapully tank situated in the Sidhout Taluq, Sidhout Range.

2. The nature of the work proposed for execution and the heads of account to which it is chargeable are as follow:—

|                                                    |        |
|----------------------------------------------------|--------|
| Repairing the sluice—Ordinary Agricultural Repairs | Rs. 60 |
| Total                                              | 60     |

3. The following particulars of this tank are recorded—

|                             |     |   |        |     |     |           |
|-----------------------------|-----|---|--------|-----|-----|-----------|
| Ayacut area, 62 Acres       | ... | { | Circar | ... | 47  | } Acres.  |
|                             |     |   | Inam   | ... | 15  |           |
| Assessment, 337 Rupees      | ... | { | Circar | ... | 248 | } Rupees. |
|                             |     |   | Inam   | ... | 89  |           |
| Average revenue, 118 Rupees | ... | { | Circar | ... | 109 | } "       |
|                             |     |   | Inam   | ... | 9   |           |
| Highest do. 132             | ... | { | Circar | ... | 118 | } "       |
|                             |     |   | Inam   | ... | 14  |           |

Expenditure during the previous four years 137 Rupees.

The area of the catchment basin is 3 square miles; the maximum flood supply is calculated at 1,026 cubic feet per second for discharging which, as surplus, there is a rough stone escape 108 feet in length.

The head of the sluice is reported to be in a ruined condition, and the estimate provides for dismantling and reconstructing it. It is recommended for sanction.

(Signed) A. DEC. SCOTT, Major, R.E.,  
Dy. Chief Engineer for Irrigation,  
for Chief Engineer for Irrigation.

OOTACAMUND,  
29th August 1876.

To the Secretary to Government, Public Works Department.

No. 21. ORDER THEREON, 2nd September 1876, No. 2,349.

|                      |
|----------------------|
| IRRIGATION, No. 1-A. |
| Account.             |

THE following estimate from the Sidhout Range, forwarded by the District Engineer, Cuddapah, is sanctioned:—

Repairing the sluice of Budicherla Venkata Krishnapully Tank.

|                               |     |     |           |
|-------------------------------|-----|-----|-----------|
| Ordinary Agricultural Repairs | ... | ... | Rupees 60 |
| Total                         | ... | 60  |           |

Proceedings of the Madras Government, Public Works Department,  
2nd September 1876. No. 2,349.

2. This sanction has been registered as No. 136-I. of 1876-77.

(True Extract.)

Colonel,  
Offg. Under Secy. to Govt., P.W.D.

To the District Engineer, Cuddapah.  
" Collector of Cuddapah.  
" Chief Engineer for Irrigation.  
" Examiner of Public Works Accounts.  
" Revenue Department.

Exd. W. H. French.  
Spare Copies

E. I. Form No. 9.

OFFICE OF THE CHIEF ENGINEER  
FOR IRRIGATION,

Stacament 29th August 1876.

No. 104-W.

Note by Chief Engineer for Irrigation.

Encls. 6. THE District Engineer, Cuddapah  
No. 502 forwards, with his letter marginally noted, an Estimate in connection  
Dated 30 May 1876 with the Bundicherla Venkata Krishnapur Tank situated in the  
Sidhant Taluq, Sidhant Range.

2. The nature of the work proposed for execution and the heads of account  
to which it is chargeable are as follow:—

Repairing the sluice { Ordinary Agricultural Repairs  
Repairs - 60--  
Total Rs 60--

3. The following particulars of this Tank are recorded—

Ayacut area. 62 Acres { Circar 473 acres  
Assessment. 337 Rupees { Circar 248 Rs.  
Average revenue. 118 Rupees { Circar 109 "  
Highest do. 132 Rupees { Circar 118 "  
Expenditure during the previous four years. 137 Rupees

50  
The area of the catchment basin is 3 square miles; the maximum flood supply is calculated at 1026 cubic feet per second for discharging which, as surplus there is a rough stone escape 108 feet in length.

The head of the sluice is reported to be in a ruined condition and the estimate provides for dismantling and reconstructing it. It is recommended for sanction.

Audatt  
Major R. L.  
Sr. Chief Engineer for Irrigation  
for Chief Engineer for Irrigation.

70

The Secretary to Govt. P. W. D.

1876. P.W.D. 4 SEP 76

From the Chief Engineer for Irrigation  
To the Secretary to Govt.  
P.W.D.

Dates 29 } August 1876  
Sept 30 }

Encls. 6.

N. 164-W.

Budicherla Venkata Krishnapully  
Tank - Cuddapah District -  
- Note forwarding for sanction  
estimate for Rs. 60 for repairing  
the sluice of -

20

E. I. Form No. 4.

No 2349 Mo  
No. of the Madras Govt.  
Under date the 2 Sept. 76  
Read the following  
From the Chief Engineer (No 164 W)  
(1876, 29 Aug 76)

The following Estimate from the Sidhant Range forwarded  
by the District Engineer, Cuddapah, is sanctioned :-

Repairing the sluice of Budicherla Venkata  
Krishnapully Tank.

Irrigation.

Ordinary Agricultural Repairs } — Rupees 60-0-0

Total Rupees. 60-0-0

2. This sanction has been registered as No. 136. I. of 1876-77.

S. E. Cuddapah  
Collector - do  
C. E. for S. with Encls  
En. P. W. D.  
Recd Sept 21/9/76

Desd 21/9/76

6410 CH

Govt. of 1876 Madras.

PUBLIC WORKS.

To

The H. E. Cuddalore

Dated

Issued

Recd.

Encl.

G. O., 1<sup>st</sup> Sept. 1876, No. 2349

Nos. 20-21

Shree of Budachurda  
Kankata Krishna pully  
Sanki - Cuddalore D.

Estimate for re  
pairing the —

Sanction of —

Sanctioned  
22-7-76