

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	236	(2)	Press
B.P. No.			Mis.
Dated	28/1		1876

Not to be folded or roughly handled

Read the following —

No 59

From the Chief Engineer for Irrigation.

No 507

District Engineer, No 77, dated 1st Dec 1875

THE District Engineer, Salem, for-
wards the following Estimate —

Repairing the Thappasanapully Kanasamoodrum Tank, Oosoor
Range, Oosoor Taluq. and constructing an additional sluice Rs 1,968

The following are the particulars furnished of this work —

Ayacut area		Acres	53 39
Assessment		Rs	274
Average revenue		"	200
Highest revenue		"	266
Cost of repairs during the previous four years		N/	

2 The tank is the lowest one of a series of nine, only four of which are Govern-
ment property The tank immediately above the one now under reference is a
private one, and consequently not under Government control, and it is reported to
have insufficient discharging capacity The Revenue Authorities having no power
to enforce the carrying out of the additions or repairs which may be necessary to
ensure not only the safety of the private works, but that of those belonging to Govern-
ment, and into which the private tanks surplus, the measures which can be taken by
the Public Works Department can be but partially effective

In this as in similar cases all possible means should be taken to induce the
owners of the private tanks to carry out the necessary repairs The Range Officer
has asked for, and will doubtless receive, the aid of the Revenue Authorities in this
direction.

3 It is stated that the immediate result of the proposed repairs and improve-
ments will be an increase of Rupees 500 to the revenue ; the villagers having engaged
to take up additional land to the extent represented, if the work is carried out A
surplus escape 150 feet in width is to be formed and an additional outlet sluice
provided. The drainage basin is 18 square miles Present means of discharging
surplus, an opening 25 feet wide The bund has been extensively breached.

FORT ST GEORGE,
18th January 1876

(Signed) A. DEC SCOTT, Major, R E,
for Chief Engineer for Irrigation.

Proceedings of the Madras Government, Public Works Department,
28th January 1876.

No 508 ORDER THEREON, 28th January 1876, No 236

IRRIGATION, No. 34
Account

THE following estimates are sanctioned —

	Capital	Revenue
	Rs	Rs
Repairing the Thappasanapully Kanasamoodrum Tank, Oosoor Range, Oosoor Talug, Salem District ..	.	1,390
Providing a surplus escape and outlet sluice to the same tank	578	
	578	1,390

Total Rs 1,968

(True Extract.)

Major-General, R E.
Secretary to Government

To the District Engineer, Salem
" Collector of Salem
" Chief Engineer for Irrigation
" Controller of Public Works Accounts
" Revenue Department

f. Engineer 77 8
December 1875.

N. 59
The District Engineer, Salem, for-
wards the following estimate.

Repairing the Thappasanapully Kanasa-
-moodrum Tank, Oosoor Range, Oosoor
Talug, and constructing an additional
sluice Rs 1968

The following are the particulars furnished
of this work.

Adjacent area Acres 53.39
Assessment Rupees 274
Average Revenue " 200
Highest " 266
Cost of repairs during the previous 4 years. Rs. 2

The tank is the lowest one of a
series of nine, only four of which are Govern-
-ment property. The tank immediately
above the one, now under reference, is a private
one and consequently not under Govern-
-ment control, and it is reported to have
insufficient

insufficient discharging capacity. The Revenue authorities having no power to enforce the carrying out of the additions or repairs which may be necessary to ensure not only the safety of the private works but that of those belonging to Government and into which the private tanks surplus, the measures which can be taken by the Public Works Department can be but partially effective.

In this as in similar cases all possible means should be taken to induce the owners of the private tanks to carry out the necessary repairs. The Range Officer has asked for and will doubtless receive the aid of the Revenue authorities in this direction.

3. It is stated that the immediate result of the proposed repairs and improvements will be an increase of Rs 500 to the revenue - the villagers having engaged to take up additional land to the extent represented, if the work is

carried out. A surplus escape 150 feet in width is to be formed and an additional outlet sluice provided. The drainage basin is 18 square miles. Present means of discharging surplus are opening 25 feet wide. The bank has been extensively breached.

Amalote
Major R.E.

Saint George
18 January 1896

For Chief Engineer for Irrigation

To
The Secretary to Government
Public Works Dept.

C.H.S.

FORMER CASES

Current No of 187
 " " " " " "

M WORKS FORM No 3

Current No 584

From
 The Chief Eng^r for
 Irrigation

No. 59
 Dated 18th 3rd Jan. 1876
 Recd 28th 3rd Jan. 1876

Subject —

Notes on the plan &
 estimates for repairing the
 Thappasanaipully Kanas-
 samoodram tank, Salem
 District.

LATER CASES

Current No of 187
 " " " " " "

ENCLOSURES 12

From to
 " " " "

Sl. No 236 28-1-76
 Orders and Proceedings in file

Depart- ment.	No	Date	ENDORSEMENTS		
			Depart- ment.	No	Dated

Recd 28th Jan 76 Bd 507

Ar 25-1-76

No 236

P.W. Dept

Proceedings of the Madras Government
 28th Jan 76
 Read the following

From

The Chief Eng^r for Irr. (R. No 59 of 18 Jan 1876)

The following estimates
 are sanctioned.

Repairing the Thappasanaipully
 Kanasamoodram tank,
 Coesoor Range - Coesoor Taluk
 Salem District - Capital Revenue
 ————— 1390

Providing a surplus
 escape and outlet
 sluice to the same
 tank ————— 578

578-1390

Total 1968

Ans

D. E. Salem - 5
 Collyer do 5
 C. J. do 5
 C. J. do 15
 Rem. Dept 17
 578
 with 12 Enclos
 17 Dispd-9-2-76

By 24/1 1876

2nd
55th

Govt. of H.S. of India.

PUBLIC WORKS.

G. E. Saleem

31/7

10. 20th July 1885

307 + 508. --
177 - 508

Sup. Panna Agency -
"Lamara" - same work
as the Panna & Co.
Reduction of the
the - 4000 panna
a similar result. and
But let alone to the same
Sanctioned.