

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works

DEPARTMENT

G.O. No.

B.P. No.

3166

Press

Mis-

Dated

27-11

CE 76

195

Not to be folded or roughly handled

100

*Proceedings of the Madras Government, Public Works Department,
27th November 1876. No. 3,166.*

Read the following:—

No. 252 W.

No. 462. *Note by Chief Engineer for Irrigation.*

THE Superintending Engineer, Kistna, forwards, with his letter marginally noted,
an estimate in connection with the Marri-
pallem Degalpallem tank supply-channel,
situated in the Bunder Taluq, Masulipatam Range.

2. The nature of the work proposed for execution and the heads of account to
which it is chargeable are as follow:—

ORDINARY, AGRICULTURAL.
Repairs.

Repairing the supply-channel banks	...	...	...	...	...	Rs.
						200
					Total	200

3. The following particulars of this tank are recorded—

Ayacut area	...	...	...	...	...	...	Acres	140
Assessment...	...	...	...	...	...	...	Rupees	614
Average revenue	...	...	...	...	...	...	„	336
Highest do.	...	...	...	...	...	...	„	583
Expenditure during the previous four years	...	...	...	...	...	...	„	166

The area of the catchment basin is — square miles; the maximum flood-supply is
calculated at — cubic feet per second for discharging which as surplus there is no outlet.

The head of the supply-channel was destroyed by the floods of 1874, and the
banks in their whole lengths were breached, the tank in consequence did not receive
its supply so that the land under it had to be kept uncultivated last year.

The estimate provides for repairing the tank supply-channel.

The channel is in Divi.

The estimate is recommended for sanction.

FORT ST. GEORGE, (Signed) JOHN MULLINS, Lt.-Col., R.E.,
16th November 1876. *Chief Engineer for Irrigation.*
To the Secretary to Government, Public Works Department.

No. 463. ORDER THEREON, 27th November 1876, No. 3,166.

IRRIGATION, No. 39-A.

Account.

THE following estimate from the
Masulipatam Range forwarded by the
Superintending Engineer, Kistna, is sanc-
tioned:—

MARRIPALLEM DAGALAPALLEM TANK SUPPLY-CHANNEL.
Irrigation.

Group or Project.—

Fund.—Ordinary Agricultural.

Class.—Repairs.

Name of Tank, Canal, or Channel.—Marripallem Dagalpallem tank supply-channel.

Particulars of Work.—Repairing the supply-channel banks.

Amount.—Rupees 200.

To be carried out by the Public Works Department Officer in charge Masulipatam
Range, I.

Proceedings of the Madras Government, Public Works Department,
27th November 1876. No. 3,166.

2. This sanction has been registered as No. 181 I. of 1876-77.

(True Extract.)

Major-General, R.F.,
Secretary to Government.

To the Superintending Engineer, Kistna.
" Collector of
" Examiner of Public Works Accounts.
" Chief Engineer for Irrigation.
" Revenue Department.

Exd. S. T. Austin
Spare Copies

E. I. Form No. 9.

OFFICE OF THE CHIEF ENGINEER
FOR IRRIGATION,

Fort Saint George 16 November 1876.

No. 252-10.

Note by Chief Engineer for Irrigation.

Index 3

No 85

Dated 14
18.11/76

THE Superintending Engineer, Kistna
forwards, with his letter marginally noted, an Estimate in connection
with the *Mariyallam degala palem* Tank, situated in the
Bunder Taluq, *M. Mahabalan* Range.

2. The nature of the work proposed for execution and the heads of account
to which it is chargeable are as follow:—

Ordinary Agricultural
Repairs

Repairing the supply channel to do Rupees 200
Total Rupees 200

3. The following particulars of this Tank are recorded —

Ayacut area. 140 Acres
Assessment. 6.4 Rupees
Average revenue. 336 Rupees
Highest do. 553 Rupees
Expenditure during the previous four years. 166 Rupees

The area of the catchment basin is — square miles; the maximum flood supply is calculated at — cubic feet per second for discharging which, as surplus there is no outlet

The head of the supply channel was destroyed by the floods of 1874, and the banks on their whole lengths were breached, the tank in consequence did not receive its supply so that the land under it had to be kept uncultivated last year.

The estimate provides for repairing the tank — supply channel.

The channel is in —

The estimate is recommended for sanction.

W. H. Williams

Lt Colonel R.E.

Chief Engineer for Irrigation

To
The Secretary to Government
Public Works Department

29-76 h₂ 2593.

P.W.D.
1876. 17 NOV 76.
No 8359
from
The Chief Engr. for Irrig.

Dated 16 }
Decr. 17 } Nov. 1876

Encls 3

No. 252-10.

Marripallem Dagalapalem
Tank Supply Channel - Kistna
District - We recommend
for sanction Estimate for Rs. 200
for repairs to the —.

in

E. I. Form No. 4.

No 3166 ^{Intm} ~~Act~~ P.W. Dept.

Proceedings of the Madras Government
27 Nov 1876 Read the following -

from
The Chief Engineer for Irrigation (H.E. No 252 W 916th Nov 1876)

THE following Estimate from
the Marrupalem Range
forwarded by the District Engineer,
Kistna is sanctioned:—

Marrupalem Dagalapalem Tank.
Supply Channel.

Irrigation.

Group or Project.	Fund.	Class.	Name of Tank, Canal, or Channel.	Particulars of Work.	Amount. Rs.
	Ordinary Agricultural	Repairs	Marrupalem Dagalapalem Tank supply channel	Repairing the supply and channel banks	200

To be carried out by the P.W. Department Officer in charge of the Range.

Sr. Kistna
Collector of Kistna
Ex. P.W. Dept.
Chk. for Encl. with 3 Enclosures.
Revenue Dept.
This sanction has been registered as No. 181- I. of 1876-77.

C.T.H.

Despd: 7-12-76

Govt. Secy. 17/11

1876

8280
Gobi. of 1876 Madras.

PUBLIC WORKS.

To

The Suptg. of the

Dated:

Issued:

Recd.:

Encl.:

G. O. 27th Nov. 1876, No. 2156

Nos. 142 - 463

Marripallen - Javalan

- palen - Pauli, Kinnia, etc.

Rebate of Rs. 2000

repaying the Supply Comm.

- vol. of the - sanctioned

Left in file