

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works **DEPARTMENT.**

G.O. No. 1148 (W)

Press
Mis.

Dated 5-4-1877.

Not to be folded or roughly handled

10

*Proceedings of the Madras Government, Public Works Department,
5th April 1877. No. 1,148.*

No. 97. Read the following letter from Major ROSS THOMPSON, R.E., District Engineer, Presidency, to the Acting Joint Secretary to Government, Public Works Department, Buildings and Roads Branch, dated Fort St. George, 22nd March 1877, No. 6,640 :—

Under the provisions of the chapter of the new Code, paragraph 9, Clause II, issued with G.O., No. 1,535, dated 11th June 1873, I have the honor to submit One estimate. for sanction an estimate, amounting to Rupees 960, for repairing the quarters occupied by the Barrack Serjeant in Fort St. George, which has been approved of by the Deputy Assistant Quartermaster-General, C. D.

2. The work has been carried out on emergency and in anticipation of Government sanction to the estimate and provision of funds from the current year's grant for Military Repairs, Imperial, at my disposal.

3. The amount of the estimate is in excess of one-fourth the value of the building; consequently I am unable to sanction the expenditure on my own responsibility.

No. 98. ORDER THEREON, 5th April 1877, No. 1,148.

MILITARY WORKS, No. 3-A.

SANCTIONED.

2. This sanction has been registered as Imperial No. 2—W of 1877-78.

Fund.—Imperial Funds, Ordinary.

Class.—MILITARY, NORMAL.

Main-Head.—REPAIRS.

Head.—(4), Staff and Miscellaneous.

Work.—Repair of Barrack Serjeant's Quarters, Fort St. George.

Amount.—Rupees 960.

Carried out by the Public Works Department.

(True Extract.)

(Signed) W. FAREWELL, Colonel,
Acting Joint Secy. to Govt., P.W.D.,
Buildings and Roads Branch.

To the District Engineer, Presidency.
" Examiner of Public Works Accounts,
" Military Department.

Exd. E C. Shunker.
Spire Copies

Correspondence

20/1/73

(a) Heads of Service

Fund. Imperial Fund, Ordinary
 Class. Military
 Main-head. Repairs

Sub-head. (4) Staff & Miscellaneous
 Section. Nil

Name of Work. Repair of Barrack Sergeant's quarters
Fort St George

Amount. Rs 960

To be carried out by the P. W. Department.

Print in the margin of G.O. No 1148 of 5/4/77-

No 495 of 1876-77.
 Head of Service. Imperial
 Fund. Ordinary
 Class. Repairs
 Main-head. Military Building
 Sub-head. Nil
 Name of work. Repairing Quarters occupied by the Barrack
Sergeant, Fort Saint George, vide District Engineers &
4/1/78 of 15 November 1876.
 Amount. Rs 960
 To be carried out Departmentally

Measurements.						Rate		Amount		
Number	Length	Breadth	Depth	Height	Volume	Pay	Cart	Pay	Cart	Pay
1	31	18			558					
Coat for putting the wall and removing the terrace, joints beams, plaster, public & complete						2		11	2	7
Coat for fixing the ends of the 2 new beams and 11 joints with brickwork in chunam plastering								10		
Complete										
1	50	1	1	3	62 1/2	3	6	13	10	9
Terracing with bricks on edge in chunam 3 jelly 3 Courses flat tiles and plastering 3 coats chunam to the ceiling and to top of the terrace						28		133	15	8
1	88	1	9	1	15 1/2	2	7	24	13	10
Brick work in chunam for binding wall										
1	88	3	9		330	2	6	7	13	5
Plastered walls with 2 coats chunam for binding wall										
Carried over Pt								201	8	3

Brought forward Pt. 201 8 3

1 50.2-3 112 1/2 Plastering cornice with 2 coats
Chunam 3 10. 11 1 3

2 16 SF 3. 24 New pine planks with elbows
and new clamps complete 59 11 8

2 3 SF 3. 24 Dr. Dr. Elbows 59 2 2 6

2 New J. Dr. Ventilators 3 6 6

Coat for fixing 4 pine
planks and 2 ventilators
with brick work in Chunam
complete. 3

2 17.6 12.9 24.3 Teakwood beams 24.3

35 11. 6. 3 15.4.6 Dr. Dr. joints.
Total 71.7.6

4 1.9 1.3 29 1/4 New teak wrought shut up 3 1. CF. 219 57

Single venetian shutters and
fixing with new iron folding
hinges fastenings & screws 13. 24 29

Coat for removing the
wooden top and partition
doors and planks of the
new roof 2 8

Coat for putting the wall
and fixing the ends of the 2
bressummer and 10 joints
of the verandah with brick
work in Chunam plastering
complete. 10

1 17.6 11. 245 Laying 1 course of brick jelly
3 coats 3 courses of flat tiles and
plaster 3 coats Chunam over the plaster
Carried over Pt. 524 11 2

Brought forward Pt. 524 11 2

2 11.6 6.5 6.6 New teakwood bressummers 3

3 1.9 20.1 1.11.9 Dr. Shelly planks

Total 8.2.3

20 6.6 1/2.3 12.23 New teak wrought shut up 3 1. CF. 21.9

10.6 1/2.3 5.7.6 Old teakwood joints

3 2.6 4.3 7.6 Dr. Dr. Dr.

Total 18.5.3 Dr. Repackets for shell

1 17.6 13.6 236 1/4 Old teak wrought shut up 9 6 10 15 2

Laying new teakwood planks
1 inch over the joints with
screws complete. 30 12. 72 10 11

Coat for removing the old
batten windows and refixing
new venetian windows with
brick work in Chunam 2 4

Coat for removing old
batten door and seat plank
refixing 2 batten doors and
seat plank with bricks
work in Chunam plastering
complete. 5

Coat for repairing the
drain with sand and cement 2

2 1.6 5.6 19 1/2 New teakwood venetian
windows with frames iron
braces folding hinges & screws 1 10 8 SF. 82 8

1 2.9 6.3 17 3/6 New batten door with frames
hooks and hinges & complete 13 9 14 12 8

Carried over Pt. 741 2 4

9

2 10 R.F. 3 D²

70 1/2

10 1/2

26

11

3 1/4

1 1/4

1 1/2

8 1/2

6 1/4

2 1/2

Brought forward Pt.
Cost for cutting the wall and
fixing 6 Brackets and 3 shelf
planks with brick work in
Chunam complete

Murging sprouts for verandah

Scraping and rubbing the walls
with granite stones

Whitewashing walls with 2 Coats

Bluewashing walls with 2 D²

Yellowwashing walls with 2 D²

Repairing walls with 2 Coats Chunam

D² blue Chunam 2 Coats

Repairing the floor with new
8" sq bricks in Chunam

Pointing to 8" sq bricks with
frontland cement

Pointing to 6" sq bricks with
frontland cement

Cost for tarring 2 Coats to Sun
shade, salimgah rafters and
iron chimney 8" complete

Removing tiled roof, and
replacing with 1/3" new plank
and flat tiles and Chunam
borders complete

Cost for repairing 10 doors and
12 windows with required men
teakwood brass hasps folding
hinges and screws

Carried over Pt.

741 24

11 2 4

5 9 R.F. 7 3

1 6 sq 6 9 9

2 11 7 6 1

3 8 5 15 11

3 10 15 11

2 7 7 14 9

2 8 6 3 2 7

7 2 6 10 11 9

1 3 10 1 6

1 4 7 15 6

5 11 16 3 6

8 2 12

844 9 5

18 1/2

9 1/4

6 1/2

3

Brought forward Pt.
Cost for beams & joints
Paint 2 Coats for
doors and windows
Paint 2 Coats for
doors and windows
Paint 2 Coats
Painting the doors
and windows for paint
Sun charges

90

844 9 6

16 8 3

19 10 6

15 13 6

6 6

10

17 11

960

No 688 of 15 March 1877
March 1877
Barack Master
No 419 of 10 March 1877
No 61353

Approved

By order
of the
District
Residency

16 March 1877

Mr. Baddley Lieut R.E.
Assistant Engineer
Fort Raig.

Maj R.E.

Residency

Last repairs were executed by the Barrack Master's Department.
Value of the Building is Rs 2130/-
Comd By
1-3-77

No 6640,
From,

110

The District Engineer,
Presidency.

To,
The Chief Engineer,
Buildings and Roads.

Sir,

Under the provisions of the Chapter of
the New Code para 9, clause II, issued
with G.O. No. 1535, dt. 11 June 1873, I have
the honor to submit for sanction and
estimate amounting to Rs 960 for repair-
ing the quarters occupied by the Barrack
Sergeant in Fort St George - which has
been approved of by the Deputy-Assistant
Quarter Master General, C.D.

2. The work has been carried out
on emergency and in anticipation of
Government sanction to the estimate and
provision of funds from the current
year's grant for military repairs
Imperial.

Encl.
Estimate.

25 MAR 77

3114

Received

Dated 21st

Received 21st March 1877

No 4950 dt. 18/4/77

Estimate for repairing
quarters occupied by the
Barrack Sergeant
in Fort St George.

Estimated Rs 960

G.O. No 1353

16 March 1877

G.O. 5th April 77 J.B.H. 97

Imperial at my disposal.
3. The amount of the estimate is in excess of one fourth the value of the building, consequently I am unable to sanction the expenditure on my own responsibility.

I have the honor to be
Sir,

Your most obedient servant.

W. Thompson Maj. R.E.
District Engineer,
Presidency.

Fort St. George
22 March 77

Recd.
W.

Buildings and Roads.

25 MAR 77

No. 3114

Ind. No.

No. 114035 April 77

Sanctioned

W. H.
This sanction has been 29.3.77.
registered as Imperial
No. 2 W. of 1877-78.

From,

The District Engineer,
Presidency.

No. 6640

Dated 22 March 1877.

No. of Enclosures 1.

O.W. 9.0.11 - June 1873 & 1535.

4.0.5. April 77 S.D. No. 97

H. P. Reidy ✓

Ex. P. W. A. ✓

Mil. Dept. ✓

Dr. 20-4-77

Barrack Sergeants quarters,
Fort St. George -

Forwards repair
estimate of Rs 960. for
sanctioned.

With adin

29.3.77.

Imperial at my disposal.

3. The amount of the estimate is in excess of one fourth the value of the building, consequently I am unable to sanction the expenditure on my own responsibility.

I have the honor to be
Sir,

Your most obedient servants.

M. Thompson Major R.E.

District Engineer,
Presidency.

Fort St. George
22 March 77

Recd.
W

Buildings and Road I.

W.D.
23 MAR 77
No 3114

Ind. work

No 114075 April 77

Sanctioned

This sanction ^{W.D.}
has been 29.3.77.
registered as Imperial
No 2 W. of 1877-78

From,
The District Engineer,
Presidency.

No. 6640

Dated 22 March 1877.

No. of Enclosures 1.

O.W.D. 11 June 1873 No 1535

4.0.5. April 77 J.B.H. 97

H. Presidency ✓

Ex. & W. A. ✓

Mily. Dept. ✓

Drpd 20-4-77

Barrack Sergeants' quarters,
Fort St. George -

Forwards repair
estimate of Rs 900. for
sanctioned.

With adin

Imperial at my disposal.

3. The amount of the estimate is in excess of one fourth the value of the building, consequently I am unable to sanction the expenditure on my own responsibility.

I have the honor to be
Sir,

Your most obedient servants.

M. Thompson Major R.E.

District Engineer,
Presidency.

Fort St. George
22 March 77

Recd.
W

Buildings and Road I.

W.D.
23 MAR 77
No 3114

Ind. work

No 114075 April 77

Sanctioned

This sanction ^{W.D.}
has been 29.3.77.
registered as Imperial
No 2 W. of 1877-78

From,
The District Engineer,
Presidency.

No. 6640

Dated 22 March 1877.

No. of Enclosures 1.

O.W.D.O. 11 June 1873 No 1535

4.0.5. April 77 J.B.H. 97

H. Presidency ✓

Ex. & W. A. ✓

Mily. Dept. ✓

Drpd 20-4-77

Barrack Sergeants' quarters,
Fort St. George -

Forwards repair
estimate of Rs 900. for
sanctioned.

With adin

No 3111
Govt. of 1877 *11/15*

PUBLIC WORKS.

To

The P. & C. Presidency

Dated

Issued

Recd.

Encl.

G. O. *5th April* 1877, No *1148*

Nos. *97-98*

*Barrack Subordinate Quarter
Fort St. George. The estimate
of Rs. 960 for repairs to the
— sanctioned.*

*Sanctioned
11/15*