M.R.O. 1—77,006—8-6-37.

(1) Number of pages_____

(2) Date of repair_____

(3) Initials of the Referencer_____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 2069 (W) Press Mis.

Dated 12-12- 1877.

Not to be folded or roughly handled

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

13th December 1877, No. 2,069 W.

Buildings and Roads.
Civil Works.

Read the following paper:—

No. 113. From Major H. R. MEAD, R.E., District Engineer, South Arcot, to the Chief Engineer, Public Works Department, dated Camp, Porto Novo, 15th November 1877, No. 180.

I HAVE the honor to request supplemental sanction for Rupees 582 for the work of repairs to the Collector's Cutcherry at Munjacooppum. This work was originally sanctioned in G.O., No. 296, dated 25th February 1875, for Rupees 5,110; this was in G.O., No. 1,472, dated 1st July, increased to Rupees 5,590 as a portion of the Cutcherry was found to require more repair than originally estimated for. The work has been more than two years in hand owing to sufficient funds not being available, and therefore there was nothing done to it from August 1875 to February 1877. The work is now nearly completed.

One Comparative Statement.

2. This extra sanction is required in consequence of extra work being found necessary in the Press-room and in Rupees 132 being lost from mortar being prepared but not made use of in 1875, and therefore useless owing to the stoppage of the work. There are differences in the other portions of the estimate, but the increase and decrease are nearly the same.

3. For the excess in the Press-room I forward a comparative statement. The chief items are brick-work and concrete, this is in consequence of it being found that the front retaining wall of the verandah, which has been enclosed, to have had only $1\frac{1}{2}$ feet foundations, this had to be taken up and 3 feet foundation on concrete put down.

4. More plastering than estimated had to be renewed and the rates for doors and windows were not sufficient, the total increase amounting to Rupees 450, which amount together with the Rupees 132, the loss in mortar, total Rupees 582, can be met with from the funds allotted to the district for repairs.

No. 114. ORDER THEREON, 13th December 1877, No. 2,069 W.

THE supplemental estimate of Rupees 582 for repairing the Collector's Cutcherry at Munjacoopum is sanctioned.

2. Funds will be provided by the District Engineer from the source indicated by him in paragraph 4 of the foregoing letter.

3. This sanction has been registered as Provincial No. 235 B of 1877-78.

(True Extract.)

Colonel, R.E.,
Secretary to Government, P.W.D.

To the District Engineer, South Arcot.
" Examiner of Public Works Accounts, with one Estimate.
" Revenue Department.

Erd. S. T. Austin
Spare Copies

D. P. W.
SOUTH ARCOT. No. 180

DISTRICT ENGINEER'S OFFICE.

Camp Porto Novo
Dated 15th November 1897

FROM

Roads & Buildings

THE DISTRICT ENGINEER,
SOUTH ARCOT.

TO

THE CHIEF ENGINEER

D. P. W.

Enclosures

1 Comparative Statement

Sir,

I have the honor to request supplemental sanction for Rs 582 for the work of repairs to the Collectors Cutcherry at Munjacoopram, this work was originally sanctioned in G. O. No 296 dated 25th Feby. 1895 for Rs 5110, this was in G. O. No 1492 dated 1st July increased to Rs 5590 as a portion of the Cutcherry was found to require more repair than originally estimated for, the work has been more than 2 years in hand owing to sufficient funds not being available and therefore there was nothing done to it from August 1895 to Feby 1897, the work

is now nearly completed.

2. This extra sanction is required in consequence of extra work being found necessary in the Press room and in Rs 132 being lost from mortar being prepared but not made use of in 1895 and therefore useless owing to the stoppage of the work, there are differences in the other portions of the estimate but the increase and decrease are nearly the same.

3 For the excess in the Press room I forward a comparative statement the chief items are Brick work and concrete this is in consequence of it being found that the front retaining wall of the verandah which has been enclosed ~~by fence~~ to have had only 1½ ft. foundations. this had to be taken up and 3 ft. foundation put down.

4 More plastering than estimated had to be removed and the rates for

doors and windows were not sufficient, the total increase amounting to Rs 450, which amount together with the Rs 132 the loss in mortar total Rupees 582 can be met with from the funds allotted to the District for Repairs.

I have the honor to be
Sir
your most obedient servant

Maj RE
Distt Engineer

Mis: 7th Jany 1875 No 47.
Mis: 22nd Feby 1875 No 186.
Mis: 8th March 1875 No 61.
Mis: 30th April 1875 No 33
Mis: 26th July 1875 No 20.

Roads and Buildings

FROM DISTRICT ENGINEER,
SOUTH ARCOT.

No. 180

Dated 15th
Despatched 16th March 1877
Received

No of Enclosure 1

Collectors Cutcherry and Post Office at Vriyanoor from — Under the 4th Standard furnished, requesting Supplemental Sanction for Rs 582 for Repairs to the — & forwarding a Comparative Statement for the Latter

Rc 13th Dec. D 1886-115

Cir 6-12

No. 2069 Civil Works
Public Works Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 13th Dec 77.

Read the following :—

From
The District Engineer
South Arcot

} (D.O. No. 180 dy 15th March 77)

The supplemental estimate of Rs 582 for repairing the Collector's Cutcherry at Vriyanoor is sanctioned.

Funds will be provided by the District Engineer from the source indicated by him in para 4 of the foregoing letter.

WH
10.12.77.

This sanction has been registered as Provincial No. 235B

To the D.C. South Arcot
Examiner P.W.D.
Secy Dept

with one Estimate

18-12-77

(1.11.20)

Cobl. di {1677} Lucca.

PUBLIC WORKS.

To Lo. R. B. Scott-Siret

Paid

Rec'd

Rec'd.

G. O., 13 Dec. 1877, No. 266/6

Nos. 113-114

Collection Catalogue of Manufactures, Models, Canadian Implements &c. Returned for Exhibition &c. ——

Sub. Pur. Dept. &c.