

(1) Number of pages 8

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No.	353 (2)	Press Mis.
Dated	22. 2.	1877

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
2nd February 1877. No. 353.*

No. 77. Read the following letter from W. A. GOODCHAP, Esq., District Engineer, Kurnool, to Major-General G. W. WALKER, R.E., Chief Engineer and Secretary to Government, Public Works Department, dated Kurnool, 25th January 1877, No. 5:—

With reference to G.O. of the 27th September 1876, No. 2,597, paragraph 2, I have the honor to report that the Revenue Department state that it is necessary to close the natural escape of 69 feet on the west end of the Markapur tank, as the discharge from it injures the cultivated land under the tank to the extent of acres 43.57, and that there is no other way of preventing the injury.

2. From my inspection of the tank and surplus channel on the 29th December 1876, I concur in that opinion.

3. The maintenance of the last twenty years, including that provided in the recently sanctioned* estimate for repairs, amounts to Rupees 6,298.

* In G.O., No. 1,370, of 1st June 1876.

4. A copy of a letter* received from the Acting Head Assistant Collector, Kurnool, on the subject is subjoined for information.

* No. $\frac{A}{89}$ of 2nd January 1877.

With reference to your letter* No. 135, dated 23rd October last, I have the honor to inform you that the Tahsildar of Markapur thinks it necessary to close the natural escape at the west end of the bund. The Tahsildar's report† is herein enclosed for your perusal and return. The discharge of water over the

* Enclosure returned.

† Arzee No. 418, dated 29th November 1876.

escape does no harm to the houses, but injures the cultivated land (acres 43.57) under the tank. The Tahsildar says there is no other way of preventing this injury than that of closing the escape finally. He suggests that a sluice may be erected, in case the escape is closed, to admit of the lands under the calingulah being cultivated.

No. 78.

ORDER THEREON, 2nd February 1877, No. 353.

IRRIGATION, No. 7-A.

ORDERED to be recorded.

(True Extract.)

Lieut.-Colonel, R.E.,
Secretary to Government.

To the District Engineer, Kurnool.
„ Chief Engineer for Irrigation.
„ Revenue Department.

Exd. S. T. Austin.

Spare Copies

No. 5

From,

To,

Sir,

District Engineer's Office
Karnool 25th January 1877.

The District Engineer
Karnool.

The Chief Engineer
P. W. Department

With reference to G.O. of the 27th September 1876 No. 2597 para 2 I have the honor to report that the Revenue Department state that it is necessary to close the natural escape of by gut on the west end of the Markapur Tank, as the discharge from it injures the cultivated land under the tank to the extent of acres 43.57 and that there is no other way of preventing the injury.

2. From my inspection of the Tank and Surplus Channel on the 29th December 1876 I concur in that opinion.

3. The maintenance of the last 20 years + In G.O. No. 1/2 including that provided in the recently sanctioned estimate for repairs amounts to

1370 Rs. 2 paise 1876.

Papers 6298.-

4. A copy of a letter received from the Acting Secy. Assistant Collector, Kurnool, on the subject is subjoined for information.-

13/89
27 January 1897

With reference to your letter No. 25 of 23rd October last, I have the honor to inform you that the Sahildar of Kurnool states it necessary to close the natural escape at the west end of the band. The Sahildar's report is herein enclosed for your perusal and action. The discharge of water over the escape does no harm to the houses but injures the cultivated land (acres 13.57) under the Tank.

Enclosure
returned.

13/89
27 Jan 1897

The Sahildar says there is no other way of preventing this injury than that of closing the escape finally. He suggests that a sluice may be erected, in case the escape is closed, to admit of the lands under the Calingula being cultivated.

Sir,

Your Most Obedient Servant

L. P. Goodchap
District Engineer.

Go No 2597-9 27 Sept 56
 " 1370- " 1- Jan 56

P.W.D.
 29 JAN 77
 No 833

No 5
 The above is a bill
 for some that it is
 necessary to close the
 present account of the
 - but it is for the same
 stated, perhaps the same:
 - some other for the
 last 20 years on that
 and

1877.
 The District Engineer
 to
 The Chief Engineer
 to
 Dated 25th January 1877
 Recd.

No 353 272 Feb 77
 Received
 Jan 24/1

D.R. Rinaldi ✓
 Ch. for Irig ✓
 Revenue Dept.
 Dec 9-2-77

Coir 31-1-77-

Go to
"

Examine entry for the
last 20 years in that
book

10 233

Sept. of 1877
PUBLIC WORKS.

The B. B. Harwood

2nd Feb. 1878

No. 77-78

Markapur Tent, Harwood
Dr. Letter from the B. B. Harwood
reporting that it will be
necessary to close the present
season of —, recorded

sent in 1878

Case 31-1-77-