

(1) Number of pages 6

(2) Date of repair

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No.

35

Press
Mis.

Dated

5-1

1877.

Not to be folded or roughly handled

Read the following:—

No. 6 W.

No. 66. *Note by the Chief Engineer for Irrigation.*

THE District Engineer, Cuddapah, forwards, with his letter marginally noted, an estimate in connection with the Gurrumcondah Syed Imam Tank, situated in the Voipaud Taluq, Madanapully Range.

2. The nature of the work proposed for execution and the heads of account to which it is chargeable are as follow:—

ORDINARY AGRICULTURAL.		
Original Works.		
Constructing an irrigation sluice	...	Rs. 80
Repairs.		
Raising and repairing the bund	...	" 142
Repairing an irrigation sluice	...	" 43
Total		Rs. 265

3. The following particulars of this tank are recorded:—

Ayacut area	...	Acres 27	{	Circar 20 0 0	Acres.
Assessment	...	Rupees 258	{	Inam 7 0 0	
Average revenue	...	" 199	{	Circar 176 0 0	Rupees.
Highest do.	...	251	{	Inam 82 0 0	
			{	Circar 192 6 4	"
			{	Inam 6 3 2	"
			{	Circar 234 0 0	"
			{	Inam 17 0 0	"
Expenditure during the previous 5 years ... Nil.					

The area of the catchment basin is 2 square miles; the maximum flood supply is calculated at 672 cubic feet per second, for discharging which as surplus there is a rough stone escape 70 feet in length, which is sufficient for the surplus discharge.

This tank has been allowed to get in very bad order, the bund in two or three places is very low and weak and the slopes cut up.

There is but one low level irrigation sluice, out of order, in this tank and it is proposed to repair it.

A high level sluice is required for the irrigation of the higher land, which has hitherto been supplied by a cut on the bund, and it is anticipated that additional irrigation will result.

There are thirty-one high lying tanks, out of which six are under Government control. Only two of these are reported to have adequate surplus works.

The estimate provides for raising and strengthening the bund, repairing a low level sluice, and constructing a high level sluice.

It is recommended for sanction.

(Signed)

A. DEC. SCOTT, Major, R.E.,
Dy. Chief Engr. for Irrigation,
for Chief Engr. for Irrigation.

2nd January 1877.

To the Secretary to Government, Public

Proceedings of the Madras Government, Public Works Department,
5th January 1877. No. 35.

No. 67. ORDER THEREON, 5th January 1877, No. 35.

IRRIGATION, No. 10.

Account.

THE following estimate from the
Madnapully Range, forwarded by the
District Engineer, Cuddapah, is sanc-
tioned:—

Gurumcondah Syed Imam Tank.

IRRIGATION.

Group or Project.	Funds.	Class.	Name of Tank, Canal, or Channel.	Particulars of Work.	Amount.
..	Ordinary Agricultural.	Original Works.	Gurumcondah Syed Imam Tank.	Irrigation sluice ..	80
		Repairs.		Repairing the bund ..	142
				Repairing an irrigation sluice ..	43
				Total ..	265

To be carried out by the Public Works Department Officer in charge, Madanapully Range.

2. This sanction has been registered as No. 251—I. of 1876-77.

(True Extract.)

Major-General, R.E.,

Secretary to Government.

To the District Engineer, Cuddapah.
„ Collector of Cuddapah.
„ Chief Engineer for Irrigation.
„ Examiner of Public Works Accounts.
„ Revenue Department.

E. I. Form No. 4-A.

No 35-75 Jan 77

Trunk Engineer Rights [H.S. No 61472 Jan 77]

THE following Estimate from the

Madnapully Range

forwarded by the
District Engineer,
is sanctioned:—

Gurumcondah Syed Imam Tank.

Irrigation.

Group or Project.	Fund.	Class.	Name of Tank, Canal, or Channel.	Particulars of Work.	Amount. Rs.
	Ordinary Agricultural	Original Works	Gurumcondah Syed Imam Tank.	Irrigation sluice ..	80
		Repairs		Repairing the bund ..	142
				Repairing an irrigation sluice ..	43

To be carried out by the P. W. Department Officer in charge, Madanapully Range.

Total Rupees 265.

2. This sanction has been registered

as No. 251. I. of 1876-77.

Collector Cuddapah
Collector do
Collector do

Govt. of 1876 Madras.
PUBLIC WORKS. ✓

To

The P. & C. Cuddapah

Dated

Issued

Recd.

Encl.

G. O. ~~5-11-1876~~ 1876, No. *35*

Nos. 66 & 67.

Suramcondah Road
Imam Gaur, Cuddapah
Dist - Abnate of Rs
25 for repair & etc -
Sanctioned

Ant. P. P. P.