

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

29th September 1877, No. 809 W.

Buildings and Roads.

Civil Works.

Read the following papers:—

No. 252. From Colonel F. J. MOBERLY, R.E., Superintending Engineer Chingleput, to the Chief Engineer, Public Works Department, dated St Thomas' Mount, 15th August, 1877, No. 1,884.

I HAVE the honor to forward, for the sanction of Government, approved by His Grace the Governor, an estimate, amounting to Rupees 460, for reconstructing drain leading from main building to the cistern in rear of kitchen at Guindy Park.

One Plan.
„ Estimate.

Grace the Governor, an estimate, amounting to Rupees 460, for reconstructing drain leading from main building to the

No. 252-A. From the same Officer, dated St. Thomas' Mount, 29th August 1877, No. 2,061.

IN reply to your memorandum No. 2,467 of 28th instant, I have the honor to report that the drain appears to have been built before the estimate was sent to me on a requisition from the Military Secretary to the Government to the Executive Engineer at the Mount.

One Estimate.
„ Plan.

report that the drain appears to have been built before the estimate was sent to me on a requisition from the Military

2. The Overseer informs me that they were desired to make an open drain, because the roots of banyan trees, which are numerous in the neighbourhood, would injure a covered drain without any observation, and also it was preferred that the Government House servants should be able to clear it out from time to time.

No. 252-B. From the same Officer, dated St. Thomas' Mount, 5th September 1877, No. 2,169.

IN reply to your No. 2,542 of 3rd instant, I have the honor to observe that the word reconstructing was an error; the drain is a "new work," and, as such, required the sanction of Government. There was formerly only an open shallow channel, and the drain, for which estimate, &c., are now sent, was intended to replace this. The Executive Officer, to whom the Military Secretary applied, completed the drain before he sent me the papers. There is therefore no work now requiring to be done, and covering or altering it will cause so much additional expense; the open drain is also, as I am informed, preferred.

No. 253. ORDER THEREON, 29th September 1877 No. 809 W.

THE Superintending Engineer, Chingleput, in his letter No. 1,884, dated 15th August 1877, submitted a plan and estimate for the construction of a drain in

Guindy Park. The Chief Engineer, disapproving of the section proposed, inquired if it resembled the old drain, when the fact was elicited that the work had been already carried out.

2. It is remarked that in addition to the drain being dangerous in the extreme, it will be difficult to clean it; the name of the officer responsible for the work with a note of the number of times he visited it during construction should be reported.

3. With these remarks the expenditure of Rupees 400 is sanctioned.

4. This sanction has been registered as Provincial No. 159 B of 1877-78.

(True Extract.)

Colonel, R.E.,
Secretary to Government, P.W.D.

To the Superintending Engineer, Chingleput.
" Examiner of Public Works Accounts.

No. 1884.

Super Engineer's Office Chingleput.
Saint Tho's Mount 15 Aug 1877.

From

The Superintending Engineer
Chingleput

To The Chief Engineer
Public Works Department

Enc: 2
10 P.W.D.
1 Estimate

Sir,
I have the honor to forward for the sanction of Government approved by the Military Secretary to His Grace the Governor an estimate amounting to Rs 400 for reconstructing drain leading from Main building to the cistern in rear of Kitchen at Guindy Park.

I have the honor to be
Sir

Your most obedient servant

Robert. Colonel R.E.

Super Engineer Chingleput

From the Supg Engineer
Chingput D.

No. 1884

Dated 15 }
Recd } Aug. 1877

No of Enclosures 2
+ Returned

Drain leading from
Main building to the
Cistern in rear of the
at Gumbly Park
forwards an estimate
for sanction of Govt.
-ment. for reconstruction
the.

4029 Sept 15 1877

8-9-77

No. 2467 of 28 Aug. 1877

Memorandum.

Letter No. 1884 dated the 15th August
1877 from the District Engineer of Chingput.

As the section adopted appears
dangerous to persons likely to cross the drain
in the dark the Chief Engineer would like to
know if the drain to be reconstructed exactly
resembles that in existence or if not, if it
would not be cheaper and safer to cover it
entirely with a sectional area of 15" x 9"

Sd/ W. Farewell Colonel
Dy: Chief Engr: PWD

To
The District Engineer Chingput with
plan and estimate.

4
No 25428/32 Sept 1877

Memorandum.

Letter from the Superintending Engineer
Chingput No 2061 dated 29 August 1877

The Chief Engineer has the honor to
point out to Colonel Moherly that the questions
put in the Memorandum, to which the above
mentioned letter professes to be a reply, have
not been answered. He requests that the
information asked for may now be given.

Sd/- E. A. Hoord Colonel R.E.
Chief Engineer P.W.D.

To
The Superintending Engineer Chingput

superintendent

Chingleput District.

Taluk *Sydapett*

Village. *Guindy.*

Head of Service. - *Provincial.*

Fund. - *Ordinary.*

Class. - *Original works.*

Main-Head. - *Civil Buildings.*

Sub-Head. - *N. Government Houses & Residences.*

Name of work. *Reconstructing drain leading from Main Building
to the cistern in rear of Kitchen at Guindy Park.*

Amount- Rupees *460-0-0*

Department

To be carried out by the

No.

or

Divisional Office, }
187 . }

Divisional Officer No. or

Dn.

Chingleput District.

Working
ling
c. P

6

Specification

The drain which carries the waste water from the room at Kimbly Park being out of repair this estimate provides for constructing open drain on a bed of concrete 9" thick the side wall to be brick in channel with 2 coats of plaster as detailed in the estimate.

Amount
20⁰⁰ June 1877

J. J. Jones, Joseph R. V.

Salus Oversee D.R.M.

D. M. Conductor
Executive Officer

on
la
the

Work of constructing drain leading from Main
building to the cistern in rear of Libbey at Grunby
Park.

(Approved.)
 Wm. H. Hall
 Military Secy
 to His Excellency the Gov.

J. Janner Schrift A-B

Salvage received \$7.06
D. Glover Conductor

Thos. B. Coll. R. B. Executive Officer
Sup. Exp. Charge

Superintendent May 1902

No. 2061

Chingleput Superintending Engineer's Office,
Saint Thomas' Mount, 29 Aug 1877.

From

THE SUPERINTENDING ENGINEER,
Chingleput.

To

The Chief Engineer
Public Works Department.

SIR,

Enc:

1 Estimate
1 Plan

In reply to your Memo No. 2467 of 28th instant I have the honor to report that the drain appears to have been built before the estimate was sent to me on a requisition from the Military Secretary to the Government to the Executive Engineer at the Mount.

2. The Overseer informs me that they were desired to make an open drain because the roots of banyan trees which are numerous in the neighbourhood would injure a covered drain without any observation and also it was preferred that the Government house servants should be able to clear it out from time to time.

I have the honor to be Sir
Your most obedient servant

Thos. J. ... Colonel R.E.
Superintendent Chingleput

Mount Range
Colonel R.E.
No. 111 of 1877-78.
Works & Engineering
Main building for
the engine in rear
of Station at Kennedy
Park.
Papers 460

4629: Sept. 11/1877 252

C E no 2467 of 28 Aug 1877

From the Super Engineer
Chingleput District

N. 2061

Dated 29th } Aug 1877
Recd }

C E no 2542 of 30 Aug 1877

N. of enclosures 2

Drain in Guindy Park
— Inform that the
has been already con-
structed and furnishes
explanation relative
to the object of drain
having been made an
open one.

4029 of 29th Sept 1877
4029 of 29th Sept 1877
4029 of 29th Sept 1877

4029 of 29th Sept 1877

No. 2169

Chingleput Superintending Engineer's Office,

Saint Thomas' Mount, 5th Sept 1877.

From

THE SUPERINTENDING ENGINEER,

Chingleput.

To

The Chief Engineer
Public Works Department

Sir,

In reply to your No. 2542 of 3rd instant I have the honor to observe that the word reconstructing was an error; the drain is a "new work" and as such required the sanction of Government. There was formerly only an open shallow channel and the drain for which estimate &c are now sent was intended to replace this. The Executive Officer to whom the Military Secretary applied completed the drain before he sent me the papers. There is therefore no work now requiring to be done, and covering or altering it will cause so much additional expense. The open drain is also, as I am informed preferred.

I have the honor to be
Sir

(your most obedient servant

J. M. Kerby. Colonel M.B.

Superintendent Chinese

✓

9
27

MEMORANDUM.

Letter Number 1084

dated the 15 August 1877

from the District Engineer of Chingleput

As the section adopted
appears dangerous to
be permitted to cross the
drain in the street in
C. Eng. would like
to know if the drain is
exactly under the
in the street or if not
if it would not be deeper
and safer to ~~change~~
can it be entirely with
a sectional area of 12"
x 9" -

Wk
Sanctioned before
Sanction Wk
27.5.77

4029: Sept 1/77, No 2520
4029: Sept 1/77, No 2520

28-9-77, 2497

Public Works Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the

Read the following:—

Dist: Chingleput (P.O. No. 1884 d/15th Aug^r 1877)

The plan and
estimate of Rs 460 for
reconstructing a house
drain in Guindy Park
are sanctioned. Wk
24.8.77

Chingleput
by order from the
Comm.
and.

P. H. D.

Note

The main surface
channel was out of
order & offensive - a
delaying - or cementing
was urgently needed
No section was presented
on a plan - Section begun
In Navy Office saw it -
apparently the result is
a very dangerous growth
or cut - too deep even
for convenient cleaning -
instead of  it is 

In submitting this
estimate for sanction
the Chief Engineer observed
that the section was
not approved (as likely
to cause accident) and
a reference to the
District Engineer -
elucidated the fact that
the work had been
completed.

E. A. Ford J. R. E.
Chief Engineer, P. H. D.

Col. St. George
Sept 17/93
In view the work has been
done - 1/11 27/9

Read

13 1/2
at tracks No 80988. Public Works Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 29th Sept 1877.

Read the following:-

Eng^r. Chingleput. No 1884. 15th August/77
 " " " 2061 - 29 - "
 " " " 2169. 5th Sept/77

The Superintending Engineer Chingleput in his letter No 1884 dated 15th August 1877 submitted a plan and estimate for the reconstruction of a drain in Guindy Park. The Chief Engineer, disapproving of the section proposed, inquired if it resembled the old drain, when the fact was elicited that the work had been already carried out.

87

h 029 Sept/77 No 80988

It is remarked
that in addition to the
drain being dangerous
in the extreme, it will
be difficult to clean it;
the name of the Officer
responsible for the work
with a note of the number
of times he visited it
during construction should
be reported.

With these remarks
the Expenditure of Rs.
460 is sanctioned.

gdt Wt
29.9.77
This sanction has been
registered as Provincial No. 1591
of 1877-78.

To the Super-Dy. Chingleput
Examiner P.W. Accounts
Desd. 5-10-77 17

16/6/97

Chingput
Sobh. of 1877 *Madras*
PUBLIC WORKS.

To

Dated

Issued

Recd.

Chingput
Chingput

G. O. 29 Sept 1877, No. 809 W

Nos. 252-253

Drain in Guindy Park.

Chingput Dr Sanction

with remarks the expenditure

of Rs 160 incurred in the re-

construction of a ---.

Sub. Dir. Engg.
Chingput

10/25-10-77

11