

(1) Number of pages 12
(2) Date of repair 19-9-86
(3) Initials of the Referencer bus

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

P.W DEPARTMENT

G.O. No.	1234 W	Press.
B.P. No.		~~Mis.~~
Dated	11-3-1878	~~197~~

Not to be folded or roughly handled.

A.K

1234
1

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

11th March 1878, No. 1,234 W.

Buildings and Roads.

Civil Works.

Read the following papers :—

No. 126. From Major ROSS THOMPSON, R.E., District Engineer, Presidency, to the Chief Engineer, Buildings and Roads, dated Fort St. George, 20th February 1878, No. 5,532.

With reference to G.O., No. 694 W, dated 4th September 1877, I have the honor to submit, for sanction and allotment of funds, an estimate, amounting to Rupees 453, for fixing pipes to fill the tanks on the roof of the Revenue Board Office, Chempauk.

2. The work has been completed.

No. 126-A. From the same Officer, dated Fort St. George, 5th March 1878, No. 6,337.

ADVERTING to your memorandum, No. 1,096, of March 1st, 1878, I have the honor to inform you that it was originally intended to fill the tanks in question by means of the ordinary hose belonging to the fire engine at Chempauk, but on trial this was found to be impracticable owing to the great length of hose required, the height to which it was necessary to lead it, and the unavoidable kinks which formed. It was also found that carrying the hose up and down involved considerable risk to the workmen and damage to the ornamental parapet.

2. Under these circumstances I directed the Southern Range Officer to provide an iron pipe of sufficient capacity leading from the tanks (which all communicate with each other) to the neighborhood of one of the hydrants; short lengths of hose now suffice to connect the hydrant with the iron pipe, and the tanks can be filled safely and easily. Until the tanks had been fixed and actual trial made it was believed that the ordinary hose would suffice; hence the omission of piping in the original estimate.

No. 127. ORDER THEREON, 11th March 1878, No. 1,234 W.

The estimate of Rupees 453 for fixing pipes to fill the tanks on the roof of the Revenue Board Office at Chempauk is sanctioned. Funds are appropriated from the Provincial Reserve of 1877-78 at the disposal of Government.

2. This sanction has been registered as Provincial No. 295 B of 1877-78.

(True Extract.)

Colonel, R.E.,
Secretary to Government, P.W.D.

To the District Engineer, Presidency.
Examiner of Public Works Accounts.
Board of Revenue.
Revenue Department.

Ed. C. Howarth
Sd/-

BUILDINGS AND ROADS
CIVIL WORKS
1878
PUBLIC WORKS.

CHIEF ENGINEER
1878
MAR 11
1878

(No. 6562.
from

The District Engineer
Presidency.

1234
1878

To,
The Chief Engineer
Buildings & Roads.

Sir,

Encls.
Estimate.

With reference D. G. O. No. 694
dated 4th September 1877, I have
the honor to submit for sanction &
allotment of funds an estimate
amounting to Rs 453 for fixing
pipes to fill the tanks on the roof
of the Revenue Board Office, Chapak.
The work has been completed.

I have the honor to be
Sir,

Your most obedient servant
W. Thompson Major R.
District Engineer
Presidency.

W. A. George
20th Feb 1878

W. A. George

Buildings & Roads.

From

The District Engineer,
Residency.

No. 6062.

Dated 20 Feb'y 1878.

Copy to Mr. L. S.

Wants for Residency Board
Office. —

Submit for sanction
an estimate for fixing up
pipes to fill the —

No. 6837.

From

The District Engineer,
Residency.

To

The Chief Engineer,
Buildings & Roads.

Sir,

Referring to your Memo. No. 1096
of March 1st 1878, I have the honor to
inform you that it was originally in-
tended to fill the tanks in question
by means of the ordinary hose belonging
to the fire engine at Chapank, but on
trial, this was found to be imprac-
ticable owing to the great length of
hose required, the height to which it
was necessary to lead it, and the
unavoidable kinks which formed. It
was also found that carrying the
hose up and down involved con-
siderable risk to the workmen and
damage to the ornamental parapet.
2. Under these circumstances I
directed the Southern Range Officer
to

to provide an iron pipe of sufficient capacity leading from the tanks (which all communicate with each other) to the neighborhood of one of the Hydrants. Short lengths of hose now suffice to connect the Hydrant with the iron pipe, and the tanks can be filled safely and easily. Until the tanks had been fixed and actual trial made it was believed that the ordinary hose would suffice. Hence the omission of piping in the original estimate.

I have the honor to be

Sr,
Your most obedient servant

Wm Thompson Major R.
District Engineer
Presidentsburg

Fort St George
5 March 1873

Geo. L.
VP

UNDER date the 11th March 1878

Read the following:—

Buildings & Roads.

From,
The District Engineer
Presidency.

No. 6837.
Dated 5 March 78.

Recepts Office -

Reports the necessity
of the pipes for filling the
tanks on the roof of the

From the District Presidency (H.E. No 6062 of 20 Feb/78)
Do - do - (6837) - 5 Mar 78

The estimate of
Rs 453 for fixing pipes
to fill the tanks on the
roof of the Revenue Board
Office at Chepank is sanc-
tioned. Funds are ap-
propriated from Pro-
vincial Reserve of 1877/78
at the disposal of Govern-
ment.

W.H.
28.7.78

This sanction has
been registered as
No. 296 B of 1878/79

D. E. Presidency
By Mr. A. S. Smith
Secy to Govt
Res. Dept.
Estimate
No. 16-3-78

804.9.77. no 694 tr.

~~Copy~~
of 1878
PUBLIC WORKS.

to H. C. Price Jan 29
1878

11 Mar 1878

Nos. 126 127

Revenue Board Office
at Chapank. Madras

Sanctioned estimate for
grants for fixing pipes to
fill the tanks on the roof
of the —

Sanctioned
1878