

(1) Number of pages 8
(2) Date of repair 9.7.88
(3) Initials of the Referencer lary

TAMIL NADU ARCHIVES.

GOVERNMENT OF TAMIL NADU

P. W. D.

DEPARTMENT

G.O. No. B.P. No.	1403 (W).	Press. Mis.
Dated	19.3.1878.	197.

mss

Not to be folded or roughly handled

1403
1

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

19th March 1878, No. 1,403 W.

Buildings and Roads.

Civil Works.

Read the following paper:—

No. 281. Endorsement of the Chief Secretary to Government, Ecclesiastical Department, dated Fort St. George, 13th March 1878, No. 442.

From the Venerable C. R. DRURY, Archdeacon of Madras, to the Chief Secretary to Government, dated Madras, 12th March 1878.

I HAVE been requested by the Cathedral Trustees to bring to the notice of Government that the windows of the Cathedral which do not open out on either of the stone terraces require an iron bar to be placed across about three feet from the ground to prevent strangers walking out at the window and running the risk of seriously injuring themselves. There need be no ornamental work, and the cost will be very small.

2. I beg to recommend that this work should be executed speedily.

TRANSFERRED to the Public Works Department.

(Signed) D. F. CARMICHAEL,
Chief Secretary.

No. 282. ORDER THEREON, 19th March 1878, No. 1,403 W.

THE District Engineer, Presidency, will carry out the work.

(True Extract.)

Colonel, R.E.,
Secretary to Government, P.W.D.

To the District Engineer, Presidency.

Exd. E. C. Shunker.

Spare Copies

BUILDINGS AND ROADS,
CIVIL WORKS.

Govt. of (1878) Madras.

PUBLIC WORKS.

THE DISTRICT ENGINEER,
PRESIDENCY.

Dated March 1878.

To

For

Per

G. O. No. 11, 1878, No. 11, 1878.

MARCH

Nos. 231-232.

St. George's Cathedral, Madras.—The District Engineer, Presidency, to carry out the work of placing iron bars across the windows of the —

Ecclesiastical Department

No. 3

To The Rev. J. F. Carmichael
Chief Secretary to Government
Fort St. George.

Sir,

I have been requested by the Cathedral Trustees to bring to the notice of Government, that the windows of the Cathedral which do not open out on either of the Stone Terraces require an iron bar to be placed across about 3 feet from the ground, to prevent strangers walking out at the windows, and running the risk of seriously injuring themselves. There need be no ornamental work, and the cost will be very small.

I beg to recommend that this work should be executed speedily.

I have the honor to be

Sir,

Your most Obedt. Servant

C. R. Drury

Archdeacon

Madras
12th March
1878

1403

3

N. 642

Transferred to the Public Works
Department.

Her. Sec. Gen. J. D.
March 17/78.

Wm. H. Murray
Chief Secretary

To the Public Works Department.

As being for 2. hours
an iron bar placed
across the steel drums
to prevent accidents.

20.83

Date 12. March 1878.
Recd 12. March 1878.

Received of the
Hon. Sec. Gen. J. D.
Chief Secretary to Govt.
of Madras.
The Hon. Sec. Gen. J. D.
Chief Secretary to Govt.
of Madras.
No. 1403 Wd. 19. March 78.

The District
Engineer Presidency
will carry out the
work.

clt 14/3

Dated 26-3-78

By Presidency

1403:
4.

Ch 3227
137 A. C. 1878
Act. of (1878) ~~Public~~
PUBLIC WORKS

To *The W. G. Presidency*

*Recd
no 2-2*

Dated

Issued

Recd.

Recd.

17 G. O. 19th Mar 1878 No. 1403 W

Pos.

St. George's Cathedral Madras

The W. G. Presidency to carry
out the work of placing iron
bars across the windows of the

Sent in 1878