

- (1) Number of pages 30
(2) Date of repair 27. 8. 86
(3) Initials of the Referencer h.g.

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

P. W. DEPARTMENT

G.O. No.	3500 W	Press.
B.P. No.		Mis.
Dated	4. 9. 1878	(1972)

BR ✓

Not to be folded or roughly handled

3500
1

GOVERNMENT OF MADRAS
PUBLIC WORKS DEPARTMENT.

4th September 1878, No. 3,500 W

Buildings and Roads
Civil Works

Read the following paper —

No 27 From H WINWIN, Esq., District Engineer, Cuddalore, to the Chief Engineer, Buildings and Roads, dated Cuddalore, 4th July 1878, No 819.

In accordance with instructions contained in your memorandum No 2,818, dated 22nd September 1877, I have the honor to submit plan and revised estimate, with its accompaniments, amounting to Rupees 382, for repairing Kazipett bungalow and constructing out-houses.

2 The original papers received with the above memorandum are herewith returned.

3 For the convenience and comfort of District Officers and others on tour I recommend the work for sanction

No 28 ORDER THEREON 4th September 1878, No 3,500 W.

THE GOVERNOR IN COUNCIL sees no reason to sanction the estimate.

(True Extract.)

(Signed) E. A. FOOTE, Colonel, R.E.,
Secretary to Govt., P.W.D.

(True Copy.)

Major, R.E.,
Under Secy. to Govt., P.W.D.

To the District Engineer, Cuddalore

Frd T D Ryan

Spare Copies

no 819

District Engineer's Office,
Guddapah, 14 July 1878

31/7/78
✓

From

The District Engineer,
Guddapah

To

The Chief Engineer,
Buildings and Roads Branch,
Madras

Sir,

In accordance with instructions contained in your Memorandum no. 2848 dated 22^d September 1877, I have the honor to submit Plan and Revised Estimate with its accompaniments amounting to Rupees 382 for repairing Kazi-pett Bungalow and constructing out houses.

2 The original papers received with the above Memo are herewith returned.

3 For the convenience and comfort of District Officers and others on tour I

recommend

3500
3

get the balance —
 from Mr. and Revised
 the same making \$0.
 Total \$85 for repairing —
 in houses.

Repairing the Ka Zepet Benjelow, and
constructing Our Houses

Quantity	Description of Work	Rate	Per.	Amount	Total.
<u>Repairs</u>					
<u>Main Building</u>					
1 1/2 cys	Stone in Mud	13 6	cys	27 12	
1 1/2 sq'	Plastering with do.	6	sq'	9	
25 3/4 do	Whitewashing, two coats	3	do	4 13 1/2	
7 1/3 do	Flooring with ^{slabs 3" thick} two coats of plank	3 1 6	do	24 2 1	
2 1/10 do	Bamboo Matting for Por	2	do	4 3 2	
15 3/5 do	Thatched Roofing	5 8	do	85 12 9	
8 1/3 c.ft.	Woodwork (jungle wood)	1 8	c.ft.	12 8	
1 no	Double paneled door west	12	each	12	
<u>Bath room</u>					
1 do	do do east do	8	do	8	
2 do	Windows for Centre room	5	do	10	
Grand total				161 2 3	

1. Iron at 100
 2. Repairs estimated
 1 no Window with frame West Hall, ironed 5 8 each 5 8.

Total Amount Repairs 19 15 2
 Sundries at 5 per cent 8 10
 Total for chain & sundry repairs 19 15 2

Out Houses
 Wood House

21 7/8 cfs. Und. Hall
 7 1/2 cfs. Plastering, with a mud
 2 1/2 do. Flooring, with foreign mud
 3 1/4 do. Thatched Roofing
 18 1/2 cfs. Woodwork, joining & sanding
 1 8 cfs.

Total Amount Repairs 19 15 2
 Sundries at 5 per cent 8 10

Notes in C. O. & General Supplies 62

Stables

9 1/2 cfs. Und. Wall
 3 1/2 cfs. Thatched Roofing
 10 1/2 cfs. Woodwork (pine & fir)
 Total Amount Repairs 37 15 2
 Carried over 37 15 2

Brought over 39 15 2
 Sundries at 5 per cent 2 10

Total for stable repairs 42

53 yds Hedge forming all round compound 8 1/2 cfs 22 2
 12 1/2 yds clearing Well 4 1/2 cfs 3 10 3

Total Amount Repairs 25 12 3
 Sundries at 5 per cent 1 5 4

Total for bridge and mill 21
 Total for repairs & repairs
 do. New Work

Grand Total Estimate Repairs 210

I do hereby certify that this Estimate provides for everything necessary
 and that no supplemental Estimate will be required hereafter

Cuddapah RANGE OFFICE.
 dated 11th July 1877.

In charge of S. P. S.
 Cuddapah Range

C. P. S. S. S. S.
 District Engineer

18/6

Specification
to accompany Estimate for repairing of Rahepet Bungalow
and constructing Out houses. Proddatur Taluq

Amount of Estimate Rupees 395--

1. Stone in mud. The portions of the main walls that have tumbled down, will be rebuilt with this description of work.

The stones will be of moderate size and flat as much as possible, and will be built in level courses. The earth used should be well mixed up and manipulated, adding a little sand if the clay is sticky, to form into lumps.

2. Mud walls. The walls of the Out houses will be of mud and plastered with mud. The earth should be well mixed up, and sand added to prevent cracking. The walls should be raised in layers of one foot and allowed to dry before another layer is commenced. They will be built at first thicker than required, and then specially trimmed, before plastering, to give an even surface.

3. Plastering with Khumri. The floor of main building has worn out and broken up in many places, it is therefore proposed, to plaster the whole, using concrete wherever required, and protecting the surface with bamboo matting of good quality. The mortar will be of the nature, consisting of 1 of lime and 2 of sand for the first coat, and equal parts of each for the 2nd coat, the sand made into

From

The Officer in charge of

Range

1st or 6th Division Range Sub District
Amount of Estimate for
Repairing the Rahepet Bungalow
and constructing Out Houses, in
the Proddatur Taluq Sub Dist.
shown in Estimate No 395--

3324

DISTRICT

35/7

August 10th 1894
 Sub. Divisional Officer
 Bangalore

76
R. W. Gold
District Engineer

no.	no	cost as	8	7	8
Windows for Centre Room			5		10
Window with frame for West Bath room			5	8	5 8
Total Amount Rupees					141 7 8
Dundries at 2 Pr cent					2 15 4
Contingencies at 3 Pr cent					4 9
Total for Main Building Rupees					149
Well.					
Clearing silt		4	0	0	3 8 1
Dundries at 2 Pr cent					2 5
Contingencies at 3 Pr cent					5
Total for Well Rupees					4
Carried over / Repairs Rupees					153

W.D.
CF07E
4-1

Received of
 The Treasurer of the
 United States
 the sum of \$100.00
 for the purchase of
 land in the State of
 California.
 December 1876

L. H. H. H.

DISTRICT

Qty.	Description of Work	Rate	Per	Amount	Total
<i>Main Building</i>					
1 1/2 c yds	Stone in a Mud	11.6	c. yd	2 2 8	
1 1/2 sq	Plastering with a Mud	6	sq	9	
5 1/2	Whitewashing two coats	3		4 13 8	
5 3/5	Thatched Roofing 12" thick with bamboo mats, bamboo reapers &c	5 8		85 12 9	
8 1/2 c ft	Woodwork (jungle)	1 8	c. ft	12 8	
1 no	Doubled panelled Door for West Bathroom	12	each	12	
1	do do East do	8		8	
2	Windows for Centre Room	5		10	
1	Window with frame for West Bath room	5 8		5 8	
	<u>Total Amount Rupees</u>			141 7 8	
	<u>Sundries at 2 1/2 p cent</u>			2 15 4	
	<u>Contingencies at 3 p cent</u>			4 9	
	<u>Total for Main Building Rupees</u>				149
	<u>Well.</u>				
4 1/2 c yds	Clearing pit	4	c. yd	3 8 7	
	<u>Sundries at 2 1/2 p cent</u>			2 5	
	<u>Contingencies at 3 p cent</u>			5	
	<u>Total for Well Rupees</u>				4
	<u>Carried over / Repairs Rupees</u>				153

Brought over Repairs Rupees 153

Main Building

1st sq Flooring with 3" Buck Plabs 12 12 2 29 99 9 9
2nd sq Bamboo Matting 2 4 3 2

Total Amount Rupees 103 12 11
Sundries at 2 1/2 per cent 2 1
Contingencies at 3 1/2 per cent 3 2 1

Total for Main Building Rupees 109

Cool House 12' x 10' inside dimensions
2 1/2 sq Mud Wall 4 c yds 5 5 2
1 1/2 sq Flooring with 3" Buck Plabs 6 c yds 2 13 10
2 1/2 sq Flooring with 3" Buck Plabs 1 2 3 6
1/2 sq Thatched Roofing 5 10 24 6
10 1/2 sq Woodwork (jungle) 1 8 c ft 27 8
Sundries & contingencies
for new works complete 2

Total Amount Rupees 64 4 6
Sundries at 2 1/2 per cent 1 12
Contingencies at 3 1/2 per cent 1 15 6
Total for Cool House Rupees 68
Brought over Repairs 153
do New Work 177

Brought over Repairs Rupees 153
do New Work 177

Stables for 2 Horses 12' x 6' 5"

9 1/2 c yds Mud Wall 4 c yds 2 6 2
3 1/2 sq Thatched Roofing 5 10 21 15
10 1/2 c ft Woodwork (jungle) 1 8 c ft 15 10

Total Amount Rupees 39 15 2
Sundries at 2 1/2 per cent 15
Contingencies at 3 1/2 per cent 1 1 10

Total for Stables Rupees 42

Hedge

531 1/2 ft Forming all round the farm
pound 8 c ft 22 2

Sundries at 2 1/2 per cent 4
Contingencies at 3 1/2 per cent 10
Total for Hedge Rupees 23

For Repairs

New Work
Grand Total Estimate Rupees 225

I do hereby certify that this Estimate provides for everything necessary and that no Supplemental Estimate will be required hereafter

Loddapah

RANGE OFFICE

dated 19 June 1878

Resigned & Commission by
Superior
Public Works Officer

In charge of
Loddapah Range

Amud Alamin
3/7/11 District Engineer

Report

31/10

to accompany estimate for repairs
the Rajpet bungalow in Prodatore
Taluk

Amount of estimate No 309

The records now available do
not show from what ^{source} funds were
originally provided for the construc-
tion of the bungalow at Rajpet.

It is however understood
that it was originally erected for
the accommodation of the over-
superintending the construction of
the road from Guddapale to Ruse-
hool, via Chayaluan, and the
road from Guddapale to Katter-
pattam via Budhal and Kallor.
It was probably constructed from
funds obtained from those esti-
mates, and kept in repair from
maintained grants.

The bungalow is pleasantly sit-
at the junction of the above
road was occupied by a con-
siderable

building should be, entirely removed,

From

The officer in charge of

Range

Nº of Guddapale Range Bud Dist.

Abstract Estimate for
Repairs to the Rajpet
Bungalow, and Constructing
Out Houses in the Pro-
datore Taluk

Amount of Estimate No

Considerable number of the total
of the above have been of some
value as well as the other
things as it was the best
to the localities of the
household goods and
to extend under the same
roof as the house is
connected with the main
house, the same has not been
had any hope for the removal
of the same

Under the name of *Chadwick*
the name of the house is given
as it was the name of the
household goods and
the building is in the
state of ruin

Household goods
in the house

Under the name of *Chadwick*
the name of the house is given
as it was the name of the
household goods and
the building is in the
state of ruin

35/11

main building should be entirely removed

Specification
to accompany Estimate for Repairing Kasepet
Bungalow and Constructing Out Houses.
Proddatur Taluk. 11/10

Amount of Estimate Rupees 395.00

1. Stone and Mud. The portions of the main walls that have tumbled down, will be rebuilt with this description of work.

The stones will be of moderate size and flat as much as possible, and will be built in level course. The earth used should be well mixed up and manipulated, adding a little sand if the clay be stiff, to form into a paste.

2. Mud Wall. The walls of the Out Houses will be of mud, and plastered with mud. The earth should be well mixed up and sand added to prevent cracking. The walls should be raised in layers of 1 ft. and allowed to dry before another layer is commenced. They will be built at first thicker than required, and then nicely trimmed, before plastering is commenced, so as to give an even surface.

3. Floor with 3" stone slabs. Floor with 3" stone slabs 18" x 18" on a bed of concrete and point the joints nicely with chunam paste made of equal parts of fine sand, and lime ground on stone slabs.

Roofing. The old thatch of the should be entirely removed.

to accompany Page, 60 pages

to accompany
estimate for repairing
the Kasepet Bungalow
in Proddatur Taluk

395
20/10/10

and jungle wood rafters and bamboo, reeds
 substituted for the broken ones and to be covered
 with bamboo mats. From the latter will be
 laid a thatching of hill grass 2' thick in the
 usual way and firmly laid, so that it may be
 blown by the wind. The roofing of the that
 houses is made in the same way as
 above, the rafters being made of bamboo
 and bamboo, will be new.

5. Whitewash. The walls will be first
 mud plastered, mixed with the clay
 as usual, and then painted with a coat
 of white wash. On its drying the second coat will be applied, add
 ing a little water and lime to the composition.
 The flooring of the
 will be mixed with
 clay and well tamped down to a firm
 and even surface, and be covered over
 with mud and grain and dung.

Approved by the
 Superintendent
 District Office
 Cuddalore, 15/12/18
 15/12/18
 District Engineer

35-80

No 3500W P.H.D. Chavan
Proceedings of the Madras Local Board
Under date the 4th July 1898
Read the following:-

From

The District Engineer
Madras } (G.O. No. 819 of 4th July 1898)

The Government in
Council declines to
sanction the estimate.
G.O. No. 29.07.98

1st of Madras Range, Madras District.

Specification to accompany
Estimate for Repairing Katchep
Dungals and Constructing
Cattle Houses & Roadside Salub

Amount of Estimate Rs. 10000/-

Dt. Madras 16-9-98

7/1

10/10/1919

81 WINDMILLS.
WORKS.

Edwards

Box 4

1912, 7 3180 W

2-24

valow. luddipat

to Sanchon

repair to

Wm. W. W.