

(1) Number of pages 24
(2) Date of repair 26.8.83
(3) Initials of the Referencer (O.V.)

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

P W DEPARTMENT

G.O. No. <u>3516W</u>	Press. Mis.
B.P. No.	
Dated <u>A</u> — <u>9</u> — <u>1878</u> — <u>197</u> .	

V.S M

Not to be folded or roughly handled

GOVERNMENT OF MADRAS
PUBLIC WORKS DEPARTMENT.

4th September 1878, No 3,516 W.

Buildings and Roads
Civil Works

Read the following papers —

No 47. From J W RUNDALL, Esq., District Engineer, Bellary, to the Chief Engineer, Public Works Department, Buildings and Roads, dated Kuppargal, 6th June 1878, No 1,084

I HAVE the honor to submit, for the sanction of Government, estimates of Rupees 170 and 120 for repairing the buildings called Overseer's shed and tools shed at Gooty.

2 These buildings are very old, and are of a temporary character, no information forthcoming from records as to when and from what funds they were originally built. The approximate value of the tools shed is Rupees 600 and that of the Overseer's shed Rupees 200. The present estimates exceed one-fourth of these values, and they cannot therefore be locally sanctioned.

3 The Overseer's shed is in the occupation of the Overseer in charge of the Gooty Taluk, at present Sergeant Healy, he pays no rent for the building, but is said to repair it occasionally at his own expense. After the building has been put in order I shall see that rent is charged for it.

4 In the event of the estimates being sanctioned, I request that funds may be provided for the same. The grant assigned to this district under "Repairs, Civil Buildings," has been already appropriated.

No 47-A From the same Officer, dated Bellary, 9th July 1878, No 1,599

With reference to your memorandum, No. 2,773, dated 25th June 1878, I have the honor to retransmit the estimates for repairing the Overseer's shed and tools shed at Gooty with a revised specification.

No 48 ORDER TIRUNEL, 4th September 1878, No 3,516 W

The estimates aggregating Rupees 860,* for repairing the Overseer's and tools sheds at Gooty, in the Bellary District, are

	Register No.	Budget of 1878-79	sanctioned, and funds to the requisite extent are appropriated from the Reserve.
* Overseer's shed	170 94		
Tools shed	120 95		

2 The District Engineer will take steps to see that an appropriate amount of rent is recovered from the Overseer occupying the building from the date that it is placed in proper repair.

3 The money should not be spent if the Overseer can be accommodated in the bungalow recently built under Lieutenant Wilson's directions near the Railway Station, regarding which report should be made.

4. This sanction has been registered as Provincial and numbered as shown above.

(True Extract)

(Signed) E A FOORD, Colonel R.E.,
Secretary to Govt., P.W.D.

(True Copy)

Major, R.E.,
Under Secy to Govt., P.W.D.

To the District Engineer, Bellary
From Secy of Public Works Accounts

Edw A F Goodall
Spore Copy

Report

2

The tool shed being in a very bad condition and the walls discolored. It is proposed to remove the tiles and broken portions of chunam borders & replace them with $\frac{1}{4}$ new tiles & chunam borders and to whitewash the building.

Patthachacharoor
27: May 1878

W. H. P. M. S. S.
Lahy Censor

W. H. P. M. S. S.
Range Officer

Value of the building Rs. 500-00-00
Date of last repair - 1878
1878-79
J. W. S.

Report

The overalls shed is in a very leaky condition; during the late rains, the water entered a portion of the wall over front door in hall, and washed portions of the wall down, and several portions around being also cracked over the same doorway and also over the doorway of room to East of hall.

The thatch on roof being rotten in many places causes the rain to enter and wash the mud down the sides of the walls. It is proposed to utilize the best of the old thatch with $\frac{1}{2}$ new. The timber in the roofing over hall requires removing as the common rafters of palmyra in the roof at present being rotten have sagged as also the furlins (two) on which they rest. It is proposed to substitute 5 jungle couples for the present rafters in hall.

The roof over the Corridor and
 a large room in the
 end of the house
 is to be thatched
 with

The roof of the
 Corridor and the
 large room in the
 end of the house
 is to be thatched
 with

The roof of the
 Corridor and the
 large room in the
 end of the house
 is to be thatched
 with

Footy Lanes Footy Range Pelham Diets
 Detail and Abstr. Estimate Repairing
 Quens's shed and out houses at Footy.

Particulars of work ^{Measurement} in feet ^{Contents}
 L. B. D.

Resurfacing with $\frac{1}{2}$ bar thatch
 Quens's shed

Shout slope	1 $\frac{53+18}{2}$ 25	887.50
Near S ₂	1 $\frac{51+18}{2}$ 21	721.50
East S ₂	1 $\frac{22 \times 14}{2}$	154
West S ₂	1 $\frac{41 \times 24}{2}$	492
Total Spts with $\frac{1}{2}$ bar thatch		<u>2258.00</u>
or Spts		<u>22.58</u>

That arch work

Over door in front of Hall	1 7 $1\frac{1}{2}$ $1\frac{1}{4}$	13.12
S ₂ Room East	1 $6\frac{1}{2}$ $1\frac{1}{2}$ $1\frac{1}{4}$	12.18
Total Cpts of That arch work Brick in Churn		<u>25.30</u>

Brick & mud

Brick & mud Over door of Hall	1 9 $1\frac{1}{2}$ $4\frac{1}{2}$	60.75
S ₂ Room East	1 8 $1\frac{1}{2}$ $1\frac{1}{2}$	18
Total Cpts Brick & mud		<u>78.75</u>

Whitewashing 2 coats

Hall North wall inside	1 14 $\cdot$ $11\frac{3}{4}$	164.50
S ₂ East & west S ₂	2 16 $\cdot$ $13\frac{3}{4}$	364.00
S ₂ South wall S ₂	1 14 $\cdot$ $9\frac{3}{4}$	136.50
Carried over		<u>645.00</u>

White wash 1st & 2nd floors	64	71	455
Do 1st floor	71	8	237
Do 2nd floor	123 1/2		51.50
Do 3rd floor	164 1/2		104
Do 4th floor			
Do 5th floor			
Do 6th floor			
Do 7th floor			
Do 8th floor			
Do 9th floor			
Do 10th floor			
Do 11th floor			
Do 12th floor			
Do 13th floor			
Do 14th floor			
Do 15th floor			
Do 16th floor			
Do 17th floor			
Do 18th floor			
Do 19th floor			
Do 20th floor			
Do 21st floor			
Do 22nd floor			
Do 23rd floor			
Do 24th floor			
Do 25th floor			
Do 26th floor			
Do 27th floor			
Do 28th floor			
Do 29th floor			
Do 30th floor			
Do 31st floor			
Do 32nd floor			
Do 33rd floor			
Do 34th floor			
Do 35th floor			
Do 36th floor			
Do 37th floor			
Do 38th floor			
Do 39th floor			
Do 40th floor			
Do 41st floor			
Do 42nd floor			
Do 43rd floor			
Do 44th floor			
Do 45th floor			
Do 46th floor			
Do 47th floor			
Do 48th floor			
Do 49th floor			
Do 50th floor			
Do 51st floor			
Do 52nd floor			
Do 53rd floor			
Do 54th floor			
Do 55th floor			
Do 56th floor			
Do 57th floor			
Do 58th floor			
Do 59th floor			
Do 60th floor			
Do 61st floor			
Do 62nd floor			
Do 63rd floor			
Do 64th floor			
Do 65th floor			
Do 66th floor			
Do 67th floor			
Do 68th floor			
Do 69th floor			
Do 70th floor			
Do 71st floor			
Do 72nd floor			
Do 73rd floor			
Do 74th floor			
Do 75th floor			
Do 76th floor			
Do 77th floor			
Do 78th floor			
Do 79th floor			
Do 80th floor			
Do 81st floor			
Do 82nd floor			
Do 83rd floor			
Do 84th floor			
Do 85th floor			
Do 86th floor			
Do 87th floor			
Do 88th floor			
Do 89th floor			
Do 90th floor			
Do 91st floor			
Do 92nd floor			
Do 93rd floor			
Do 94th floor			
Do 95th floor			
Do 96th floor			
Do 97th floor			
Do 98th floor			
Do 99th floor			
Do 100th floor			

Specification to accompany
Estimates for repairing Overseer's Shed, Out houses
and Tools shed at Gooty.

The whole of the old thatch on shed and
roof over hall to be removed and fine rough jungle
wood couples with two collar pieces 1 1/2 ft apart laid
on granite slabs fixed on top of wall. Bamboo pice-
-pieces to be tied to the couples and rafters, a bamboo
mat laid above them and the thatch 1/2 new and
1/2 old straw to be laid on the mat - to form the
ridge two pieces of palmyrah (old common rafters)
will be nailed on both sides of the apices of the
couples. Over these purlins bamboos will be placed
at right angles and tied at the apex and purlins
of roof smaller bamboos or reapers will be placed
at right angles and tied; lastly over these mats
will be laid and tied. The thatch to be laid on
in layers of one foot and each layer to be bound
down by a split bamboo fastened to the bamboos
within by palmyra fibres.

The whole of the thatch on the Cook room

W. W. W.
L. W. W.
M. W. W.

rendered slightly glutinous; by the addition of
congee water, and the mixture laid on the surface
of the wall with a brush -

Similarly as in the above, but the
operation repeated a 2^d time.

The plaster to consist of one of lime
to two of sand well incorporated -

J. W. Shinnall
District Engineer
Bellary.

No. 1084

District Engineer's Office
Camp Kuppagal
6th June 1878.

From

The District Engineer
Bellary

To The Chief Engineer
Buildings and Roads

Enclosures

2 Estimates

Sir

I have the honor to submit
for the sanction of Government Es-
timates of Rupees 170 and 170 for repair-
ing the buildings called Overseer's
Shed and Tools Shed at Gooty.

2 These buildings are very old
and are of a temporary character,
no information is forthcoming from
records as to when and from what
funds they were originally built.
The approximate value of the Tools
Shed is Rupees 500 and that of the
Overseer's Shed Rupees 200. The pre-
sent Estimates exceed one fourth of
these values and they cannot there-
fore be locally sanctioned.

3 The Overseer's shed is in the

No 1599

515
District Engineer's Office,
BELLARY,

9th July 1878

From

The District Engineer
Bellary

To

The Chief Engineer
P. W. D.

Sir,

Closures..

With reference to your
Memorandum No. 2773 dated
25th June 1878, I have the
honor to retransmit the
Estimates for repairing
the Overseer's shed and
Tools shed at Gooty with
a revised specification
I have

"recognition of his own
 of the fact, that he is
 good & happy, and
 the feeling, and every
 of them."

1911

100

1

1994

100

1000

17

1922-5

1875

her

10-17-71

7

—

B & R
Chambers

No 3576 Public Works Department

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the 4th Sept 1898.
Read the following.

3576
11

From
The D. Engineer Bellary (A.E. No. 1084 d/6th June 1898)
" do " do " (A.E. No. 1599 d/9th July 1898)

*
The estimates aggregating Rs 360 for repairing the Overcists and Tools sheds at Gooty in the Bellary District are sanctioned, and funds to the requisite extent are appropriated from the Reserve.

The District Engineer will take steps to see that an appropriate amount of rent is recovered from the Overcist occupying

3512
12

... ..
... ..

1st
12
50 7 44

... ..
... ..
... ..
... ..
... ..

... ..
... ..
... ..
... ..
... ..
... ..
... ..
... ..
... ..

... ..
... ..
... ..
... ..

100
9-78

