

(1) Number of pages 8
(2) Date of repair 2.9.86
(3) Initials of the Referencer bmj

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

P. W. D. DEPARTMENT

G.O. No.	<i>H024.W.</i>	Press.
B.P. No.		Mis.
Dated	<i>16.10.1878</i>	<i>197</i>

Not to be folded or roughly handled

B.S. 28

4024
1

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

16th October 1878, No. 4,024 W.

General.
Establishment.

Read the following paper :—

No. 204. From Colonel F. J. MOBERLY, R.E., District Engineer, Bangalore,
to the Chief Engineer, Public Works Department, dated Bangalore, 11th
October 1878, No. 139.

I HAVE the honor to report that in removing the frame of a ventilator in the
guard-room, 67th Regiment, a cooly, named Mootoocherry Muniah, fell on the back
of his head from the scaffolding, a height of about eight feet, on the stone floor and
died a few hours after in the Bowring Hospital. Another man who was working with
him states that the frame gave way unexpectedly on Muniah's pulling.

2. The Sub-Magistrate instituted an inquiry and came to the conclusion that
the death was accidental.

No. 205. ORDER THEREON, 16th October 1878, No. 4,024 W.

ORDERED to be recorded.

(True Extract.)

(Signed) E. A. FOORD, Colonel, R.E.,
Secretary to Govt., P.W.D.

Exd. T. D. Ryan.
Spare Copies

GENERAL
ESTABLISHMENT.

Gobt. of (1878) Madras.
PUBLIC WORKS.

Dated October 1878.

Issue

Recd.

Encl.

G. O., 1878, October 1878, No. 4324 W.

OCTOBER

Nos. 204-205

Montocherry Munniah, a cooly, who worked in
the Guard-room of the 67th Regiment, Banga-
lore. Letter from the District Engineer

G. O. 139

From

To

Sir,

District Engineer's Office
Bangalore, 11th October 1878

The District Engineer
Bangalore,

The Chief Engineer
Public Works Dept.
Madras.

I have the honor to report
that in removing the frame of a
ventilator in the Guard-room, 67th
Regiment, a cooly, named Montocherry
Munniah, fell on the back of his head
from the scaffolding, a height of
about 8 feet, on the stone floor, and
died a few hours after in the
Bawring Hospital. Another man who
was working with him states that the
frame gave way unexpectedly on
Munniah's pulling.

2. The Sub Magistrate instituted
an inquiry and came to the conclusion
that the death was accidental.

I have the honor to be

Sir,

Your most Obedt. Servt.

J. M. Hardy. Col. R. B.
District Engineer.

11/10

11/10/3

3

No 4024 W 716 A 11/78

Recorded.

Oct 14/10

Quarant or Establishment

From

The District Engineer
Bangalore

To

The Chief Engineer

P. W. Depto

Madrass.

No 139.

Dated 11th

Oct 12th } Oct 12th 1878

Mattacherry Mammiah,
a cooly — Reports that on
fall on the stone floor while
removing the frame of a
ventilator in the Guard
Room, 10th Regt, and died
a few hours after at the
Mourning Hospital.

To acty 12-10-78

Cir 14-10-78

Put 16-10-78

With order

1092

4

11/5/78

Govt. of (1878) Madras.

PUBLIC WORKS.

To

Dated

Issued

Recd.

Encl.

G. O., 16th Oct. 1878, No. 4024, A.

Nos. 204 to 245

Neostocherry Munnials & Cooly
who worked in the
Room of the by Reg. Bangalore

Letter from the S.D. reporting
the accidental death of —
Recorded

Encl. in Rept.