

(1) Number of pages 8.
(2) Date of repair 20. 1. 87
(3) Initials of the Referencer lms

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

P. W. D. DEPARTMENT

G.O. No.	663 W	Press.
B.P. No.		Mis.
Dated	5. 3. 1879	197.

Not to be folded or roughly handled

B.S. 21

663
1

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

5th March 1879, No. 663 W.

Buildings and Roads.
Civil Works.

Read the following paper :—

- ✓ No. 83. From the Acting Superintending Engineer, First Circle, to the Chief Engineer, Public Works Department, dated Dowlaishvaram, 25th February 1879, No. 511 G.D.

I HAVE the honor to report, for your information, that an estimate, amounting to Rupees 70, was sanctioned by me under the countersignature of the Collector for fixing wrought-iron bars to windows of the Sea Custom House godowns at Cocanada. The Collector states that the work is absolutely required, and I request, therefore, you will be good enough to obtain the special sanction of Government for proceeding with it from the allotment placed at my disposal for "Repairs, Civil Buildings, Provincial."

- ✓ No. 84. ORDER THEREON, 5th March 1879, No. 663 W.

THE work may be proceeded with as emergent. It is presumed that the absolute necessity for undertaking it at once has reference to the safe custody of the goods contained in the godowns of the Sea Custom House.

2. An appropriation of Rupees 70 is made for the work from the Reserve at the disposal of Government.

(True Extract.)

Colonel, R.E.,
Ag. Secy. to Govt., P.W.D.

To the Superintending Engineer, First Circle.
" Examiner of Public Works Accounts.

Exd. C. Howarth.
Spare Copies

BUILDINGS AND ROADS
CIVIL WORKS.

Govt. of (1879) Madras.

PUBLIC WORKS.

The SUPERINTENDING ENGINEER,
FIRST CIRCLE.
Cc., Cc., cc.

Dated March 5th.

Issued

Recd.

Recd.

G. O., 5th March 1879, No. 83-84.

MARCH.

Nos. 83-84.

Sea Custom Customs at Cocanada.
Appropriates from the Reserve Super. 70
for fixing iron bars to windows of the

NO. 511 G/D

General.

FROM,

THE ~~OFFICER~~ SUPERINTENDING ENGINEER

1st Circle
GODAVERY DISTRICT.

TO,

THE CHIEF ENGINEER

PUBLIC WORKS DEPARTMENT

MADRAS.

CAMP DOWLAISH^{na}W^{ra}RAM, 25th February 1879.

SIR,

I have the honor to report for your information that an estimate amounting to Rs 70 was sanctioned by me under the countersignature of the Collector for fixing wrought iron bars to windows of the Sea Custom House Godsums, at Cocanada. The Collector states that the work is absolutely required; and I request therefore you will be good enough to obtain the special sanction of Government for proceeding with it from the allotment placed at my disposal for repairs, Civil Buildings Provincial.

I have the honor to be,
Sir,
Your Most obedient Servt

M. P. M. Asst. Eng.
Asst. to Supr Engineer 1st Circle
For As Supr Engineer

4th 79

P. 5-3-79 10663 K

General.

FROM,

Ag
THE OFFG. SUPERINTENDING ENGINEER
1st Circle
GODAVERY DISTRICT.

TO,

THE CHIEF ENGINEER

PUBLIC WORKS DEPARTMENT.

MADRAS.

DATED

25

February 1879.

RECEIVED

No. 511 G.D.

ENCLOSURE.

Cacana-da-Sea Custom
Godowns at —.

Requests to obtain special
Sanction of Govt. for pro-
ceeding with the work of
fixing iron bars & windows
from the allotment placed
at the disposal of the Supg. Engr.
for "Repairs", "Civil Buildings"
"Provenencia".

663 W
No. 663 W. Public Works Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 5th March 1879

Read the following:—

From
The Ag. Supg. Engr. } (M.C. No. 511 G.D. d/25th Feb/79)
1st Circle

The work may
be proceeded with as
emergent. It is presumed
that ^{the} absolute necessity
for undertaking it
at once, has reference
to the safe custody
of the goods ~~stored~~
contained in the godowns
of the Sea Customs
house.

To the Supg. Engr. and Chief
Engineer
19

An appropriation of Rs 70
is made for the work from the
Reserve at the disposal of Govt.

P. 5-3-79
10663 K

3.3.79

Wk
4.3.79

1879

Gobt. of (1879) Madras.

PUBLIC WORKS.

To

Dated

Issued

Recd.

Encl.

*sent to Sup
8/3/79*

G. O. 5 March 1879, No. 663 W

Nos. 83-84

Sea Custom Exdms.
Cocanada... Appropriate
to go from the Reserve to
for fixing iron bars to
windows of the —